

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

State of New Mexico
Energy, Minerals and Natural Resources

JUN 13 2019

DISTRICT II - ARTESIA

OIL CONSERVATION DIVISION

South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

WELL API NO.

30-015-43990

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

-

7. Lease Name or Unit Agreement Name

Willow Lake WC 15

8. Well Number

001H

9. OGRID Number

12361

10. Pool name or Wildcat

Purple Sage Wolfcamp Gas Pool

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Kaiser-Francis Oil Company

3. Address of Operator

P. O. Box 21468, Tulsa, OK 74121-1468

4. Well Location

Unit Letter L : 1930 feet from the South line and 220 feet from the West line
Section 14 Township 24S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
2995' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Proposed procedure:

1. Clean out to at least 7600'. Set retainer @ 7515' & sqz w/200 sxs cmt.
2. Log cement on 5 1/2" post squeeze.
3. Perf & circ the 5 1/2" & 5 1/2" x 9 5/8" w/mud.
4. Free-point, cut and pull 5 1/2" (approximately 7300' of it). 35 sxs WOC + Tag
5. Set 9 5/8" CIBP above 5 1/2" csg stub. Dump 20 sxs cmt on it. Log cmt on 9 5/8".
6. Spot 100 sx cmt plug from 7200'-7000' (1st Bone Spring Sand).
7. Spot 95 sx cmt plug from 4500'-4300' (Delaware Sand).
8. Spot 50 sx cmt plug from 2782'-2682' (Int csg shoe plug). WOC & tag.
9. Perf 9 5/8" @ 415' & circ cmt to surface.

Spud Date:

2/15/18

Rig Release Date:

4/21/18

* See Attached COAs Must be Plugged by 6/24/20
I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Charlotte Van Valkenburg

TITLE Mgr., Regulatory Compliance DATE 6/7/19

Type or print name Charlotte Van Valkenburg E-mail address: Charlotv@kfoc.net PHONE: 918-491-4314

For State Use Only

APPROVED BY:

Staff Mgr.

TITLE Staff Mgr.

DATE 6/24/19

Conditions of Approval (if any):