Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD	Arte	sia
-----	------	-----

FORM APPROVED OMB NO. 1004-0137

, 2018

NMNM78214

4	Expires: January 31.
tesia	5. Lease Serial No.

Do not use the	· 400/Q	NMNM78214 6. If Indian, Allottee or Tribe Name					
SUBMIT IN	TRIPLICATE - Other instr	ructions on	page 2		7. If Unit or CA/Agree	ement, Name and/or No.	
Type of Well	· ier						
Name of Operator EOG Y RESOURCES INC					9. API Well No. 30-015-28133-0)0-S1	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well			Exploratory Area				
	,				,		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
Notice of Intent	☐ Acidize	☐ Dee	pen Proc		ion (Start/Resume)	☐ Water Shut-Off	
Subsequent Report		S	☐ Reclama	ation	■ Well Integrity		
,		_				☐ Other	
☐ Final Abandonment Notice			•	•			
EOG Resources, Inc. plans to 1. MIRU all safety equipment 2. Perforate at 9626 ft. Attem 9626 ft - 9303 ft. WOC and tag 3. Perforate at 8969 ft. Attem 8969 ft - 8700 ft. WOC and tag 4. Set a CIBP at 7866 ft with 5. Perforate at 7382 ft. Attem 7382 ft - 7209 ft. WOC and tag 6. Perforate at 3413 ft. Attem	plug and abandon this we as needed. NU BOP. POC of to establish circulation of This will plug Atoka. This will plug 7 inch casi 35 ft Class H cement on to to establish circulation of to establish circulation of This will plug Wolfcamp. This will plug Wolfcamp. This will plug Wolfcamp.	DH with product spot a 25 stores a 25 stores a 25 stores and a 25 stores a 25	uction equipmer ex Class H ceme ex Class H ceme I Strawn. Add	nt. ent plug from ent plug from Pluq (in ent plug from ent plug from SEE A	TTACHED	ent from 8311 135, woc Tag.	
14. I hereby certify that the foregoing is	true and correct.	00045	d				
. Commi	For EOG Y R	ESOURCES	NC, sent to the C	Carlsbad		IL CONSERVATION ARTESIA DISTRICT	
					•	OCT 17 2019	
Signature (Electronic S	dubmission)		Date 09/18/2	019	· ·	PECEIVED	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	- C	
			Title 57	AG T		1 D-6-19 Date	
certify that the applicant holds legal or equ which would entitle the applicant to condu	titable title to those rights in the sect operations thereon.	subject lease	1				
Fitle 18 U.S.C. Section 1001 and Title 43 States any alse, fictitious or fraudulents	U.S.C. Section 1212, make it a c	rime for any pe	rson knowingly and	willfully to ma	ike to any department or	agency of the United	




Additional data for EC transaction #483915 that would not fit on the form

32. Additional remarks, continued

Perforate at 2712 ft. Attempt to establish circulation or spot a 43 sx Class C cement plug from 2712 ft - 2585 ft. WOC and tag. This will plug Glorieta.
 Perforate at 1671 ft. Attempt to establish circulation or spot a 25 sx Class C cement plug from 1671 ft - 1529 ft. WOC and tag. This will plug shoe.
 Perforate at 1008 ft. Attempt to establish circulation or spot a 37 sx Class C cement plug from 1008 ft - 898 ft. WOC and tag. This will plug San Andres.
 Spot a 10 sx Class C cement plug from 57 ft up to surface. WOC and tag.
 Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached

Anemon	io AA	E Fodor	al #/1			Sec-TWN-RNG:				API:	30-015-28	3133		
	العاتيا	i Frivêncî	CHARLE		B .	FOOTAGES:	1650' FSL & 198	0' FEL			3995			
COMMENTS	ZI	. [İ	1/ 43	-					KB:		and the fee	ar interpretation	la in la destit f
		-	1 1	7/日曜			edicalianism call	radius, r	CONTRACT.		19ments:	368823	Fish and Control of	stratue.
	2			17/18		DETAIL '		T	,			1	ai 500	
	ZI I					HOLE SIZE	SIZE		GRADE	Тор	Bottom	Sx Cmt	Clic/TOC	TOC Method
Α .	' /	}	1 1	1/1	A_	22	16	75	J-\$5	0_	55		Surf	
m m	55 to	1	1 (\$55071	_B_	14 3/4	9 5/8		H-40	0	1,621	1150	Surt	
18		i	1 1		<u>c</u>	8 3/4		26	J-55	0	8747	650	?	
]	i i	建	D	6 1/8	4 1/2	11.6	P-110	8265_	10450	115	7	
ii		İ	1 [2.5	TWEIN	attenta partamententa	Karanerina ing	*****************************	TREASON OF	WEST TRAPE	1044	10 CH 13 EVEN	PARTHUAL OF THE	OF ENCINE
· 🖟		- 1	1	[602]		TION TOPS	AMERICA MALINE COLOR TANAS CONT.	N. Managara	entaine co	**************************************	ANN WOUNDS	- HERMAN CAL	W. WILLSON AND ALCO AL	authorithes & 171
(A		i	1 1	3	FURM	TION TOPS	FORMATION	TOP			T	T		r
i i			1 1	238			MORROW	9968			 	 		
) i			1 [ATOKA	9576			 	 		
Z	8		1 1	<u></u>			STRAWN	8919			 	 		<u> </u>
	-						UPPER PENN	7904			1	ļ		l
	ľ		1				WOLFCAMP	7332			I			
	\$7.78		1 1				BONE SPRINGS	3363				·		
	4	- 1] [GLORIETA	2662						
	見清			医 阳			SAN ANDRES	958						
	100		1 1	SET.										
				10	X 9.7	和物理运动和政治的	等地名加纳马利斯特里	relay na	era era	The state of	語言をはない	William All	TERRITOR IN	un Marin
	199	1	1		TUBIN	DETAIL								
	[[6]]	i	1 1		#	. Joints	Description	Length	OD	1D	Grade	Wt (lb/ft):	Top (fiKB):	Blm (ftKB):
		ļ	1 1					FT	in		Ι			
PERFS @ 7916-8060'	_ (EVG)		i l		1	243	2 7/8" TBG	7948,53	2 7/8				13,40	7,961.90
			1 1		2	1	27/8" SN		27/8				7,961.90	
		·	1 8	100		·		1				J		
	200	- 1	1 1					1						
	175	1	1 1					T						
	9.5	}]											
		_	ار ا		-			-	_		ļ			
4 1/2 Uner top @ 8265'	E	\forall		i.e.				 			 	 		
	經過	1 1	1 1	[6]				 						
		1 1	1 1	<u> </u>										
	C	1 1	1 1 -		L			ļ			ļ	ļ		
		1 1			1 500 7	To ATT SHIP STORE WIT - A VIN	TO REMEMBER THE SERVICE	English to the	Section 1	352977995	Security and	.05b 11 tz. id	SADMO TO	(22) 9 19 19 19
		1			Plugs	C 1 1 11 24 12 12 12 12 12 12 12 12 12 12 12 12 12	200000000000000000000000000000000000000							
		T SH	5		#	SX	CMT Class	Тор	BTM		Descr	ption		
			-											
								Τ						
			l											
	1	<u> </u>	200											
	į								L					
•	ŀ	96	Control of the Contro		_		massect in real	14 1250	師母型部	Relative	进事等企	Every	Coffi - Change	<u> 1955 (1957)</u>
		£ a	2		ADDIT	ONAL DETAIL		1		<u></u>				<u> </u>
		531	搬				FORMATION	TOP	ВТМ	4		<u> </u>	NOTES	
in cont		[4]		,	<u></u>	PERFS	CANYON	7916		20	5		42 HOLES	
132	ĺ	TEST T	进行 [1]		<u></u>	PERFS		7945		<u> </u>	5		.42' HOLES	ļ
CIBP @ 10,046'	į					PERFS		7960		<u>/</u>	3 _	J	42' HOLES	<u> </u>
	Į.	·	[1]		<u> </u>	PERFS		8010		9/ 5	5	↓	.42° HOLES	<u> </u>
PERFS	ŧ	5 62	100			PERFS	1	8022		7	-	1	.42" HOLES	
PERFS			1 N. 161	<u> </u>		PERFS		8034		27		 	42" HOLES	
PERFS .	=	=		-		PERFS	MORROW	10096		240		ļ	.42" HOLES	
PERFS	Ę	100 P	E			PERFS		1018B	10196	5.4			.42" HOLES	
PERFS	1	81				PERFS		10200		1 50		4	.42" HOLES	<u> </u>
Float Collar @	1					PERFS		10206		78			.42" HOLES	
Float Shoe @ 10446'		D				PERFS	L	10320	10332	71	В	1	.42' HOLES	<u> </u>
PB	STD: 10,0				<u></u>	l	l	<u> </u>	ļ	l	J		L	<u> </u>
	TD: 10,4	148 MD				Prepar	ed by: SCB							



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.