

- Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

S

SOIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-30066
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. NM-22080
7. Lease Name or Unit Agreement Name: Barclay Federal #15
8. Well No. 15
9. Pool name or Wildcat Livinston Ridge
10. Elevation (Show whether DR, RKB, RT, GR, etc.)



SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Forrest Oil Corporation

3. Address of Operator
707 17th Street, Suite 3600, Denver CO. 80202

4. Well Location
Unit Letter **M** : **660** feet from the **West** line and **660** feet from the **South** line
Section **1** Township **23S** Range **31E** NMPM County **Eddy**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/10/06. MIRU. POH w/ 15 1.2" rods. Ros parted.. Dug out cellar CWI. SDFN.
8/11/06. ND wellhead. Release TAC. NU BOP. POH to parted rods. tripped rods out of hole.
8/14/06. Finished POH w/rod and 237 jts. tbg. RIH w/ 5 1/2 CICR. to 6160'. Pumped through tool. Set CICR. @ 6160. Pumped 3 bls/min @ 0 psi. SDFN.
8/15/06. Sqz. 250 sx cement and dumped 50 ft. on top of CICR. POH w/ 10 jts. circ. hole w/ mud laden fluid. PPOH w/tbg. RUWL. Perf 5 1/2 csg. @ 4500'. POOH w/ WL. RIH w/ 5 1/2 CICR & set @ 4442. Establishrate @ 1 1/2 bbls/min. Sqz. 75 sx. cement and dumped 40 ft on top of CICR. POH w/ 60 jts. SDFN.
8/16/06. Perf. csg. @ 920'. Set packer @ 30'. Established circulation. Layed down packer. ND BOP. NU wellhead. Circulate 250 Sx. cement down 5 1/2 and up 8 5/8 to surface WOC 2 hrs. RIH w/ 1 jt. and circulate 15 sx cement to surface inside 5 1/2. Cut off wellhead. Install Dry hole marker. Clean loc. rigged down.

Accepted for record
NMOCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Cindy Bush TITLE Sr. Regulatory DATE 11-1-06

Type or print name Cindy Bush Telephone No. 303-812-1554
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any: