4.3.43°		w Mexico	Form C-103				
Office District I	Energy, Minerals and	Natural Resources	May 27, 2004				
1625 N. French Dr., Hobbs, NM 87240 District II	OH GOMGERMA	TION DIT WOLON	WELL API NO. 30-015-29376				
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA		5. Indicate Type of Lease				
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South S		STATE X FEE				
District IV	Santa Fe, 1	NIM 8/303					
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No.				
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	7. Lease Name or Unit Agreement Name: 0XY Mustang State						
1. Type of Well: Oil Well Gas Well X	Other	Month - Year FEB 1 5 2007	8. Well Number 1				
2. Name of Operator							
OXY USA WYP Limited Partne	rship		192463				
3. Address of Operator			10. Pool name or Wildcat				
P.O. Box 50250 Midland, T	X 79710-0250		Empire Morrow, South				
4. Well Location							
Unit Letter I:	1980feet from the	south line and	660 feet from the east line				
Section 16	Township 18	S Range 29E	NMPM County Eddy				
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3519'							
Pit or Below-grade Tank Application	or Closure						
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water							
Pit Liner Thickness: mil			ion Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data							
	ニトリナトヘトリナヘ・		ACCUENT DEPORT OF				
NOTICE OF INTE			BSEQUENT REPORT OF:				
	ENTION TO: PLUG AND ABANDON						
			☐ ALTERING CASING ☐				
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING  LING OPNS.  PLUG AND ABANDONMENT				
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS MULTIPLE	REMEDIAL WORK COMMENCE DRILL CASING TEST AND	ALTERING CASING  LING OPNS.  PLUG AND ABANDONMENT				
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi	ALTERING CASING  LING OPNS.  PLUG AND ABANDONMENT  On				
PERFORM REMEDIAL WORK   TEMPORARILY ABANDON   PULL OR ALTER CASING   OTHER:  13. Describe proposed or completed	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and give	ALTERING CASING  LING OPNS.  PLUG AND ABANDONMENT				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and give	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and give	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  operations. (Clearly state	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and give	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and giv fultiple Completions: Attac	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and give	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and giv fultiple Completions: Attac	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work).	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and giv fultiple Completions: Attac	ALTERING CASING  LING OPNS. PLUG AND ABANDONMENT  on X  ve pertinent dates, including estimated date				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION  Toperations. (Clearly state SEE RULE 1103. For M	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and giv fultiple Completions: Attac	ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  On Ve pertinent dates, including estimated date h wellbore diagram of proposed completion				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M  See	REMEDIAL WORK COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Completi all pertinent details, and giv fultiple Completions: Attact Attachment	ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  On X  we pertinent dates, including estimated date h wellbore diagram of proposed completion  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M  See	REMEDIAL WORK  COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Completi all pertinent details, and give fultiple Completions: Attack  Attachment  to the best of my knowledge didelines , a general permit	ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  On Ve pertinent dates, including estimated date h wellbore diagram of proposed completion  ge and belief. I further certify that any pit or below-				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  I hereby certify that the information at grade tank has been/will be constructed or complete thank has been thank has bee	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M  See	REMEDIAL WORK  COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Completi all pertinent details, and give fultiple Completions: Attack  Attachment  to the best of my knowledge didelines , a general permit	ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  on  ve pertinent dates, including estimated date h wellbore diagram of proposed completion  ge and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan				
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  I hereby certify that the information algrade tank has been/will be constructed or constru	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M  See	REMEDIAL WORK  COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Completi all pertinent details, and given for the completions: Attack  Attachment  to the best of my knowledged delines, a general permit to the best of my knowledged delines, a general permit to the best of my knowledged delines. Sr. Regulations.	ALTERING CASING  ABANDONMENT  On  Ve pertinent dates, including estimated date h wellbore diagram of proposed completion  The completion of an (attached) alternative OCD-approved plan of the completion of an (attached) alternative OCD-approved plan of the completion of the completion of the completion of an (attached) alternative OCD-approved plan of the completion of t				
PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER:  13. Describe proposed or completed of starting any proposed work). or recompletion.  I hereby certify that the information algrade tank has been/will be constructed or cons	PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  I operations. (Clearly state SEE RULE 1103. For M  See	REMEDIAL WORK  COMMENCE DRILL  CASING TEST AND CEMENT JOB  OTHER: Completi all pertinent details, and give full tiple Completions: Attack  Attachment  to the best of my knowledge idelines, a general permit	ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  On Water pertinent dates, including estimated date the wellbore diagram of proposed completion  The proposed completion and the proposed completion with the proposed completion are attached alternative OCD-approved plan attory Analyst DATE TOTAL COTAL david stewart@oxy.com				

٠,

٠.

#### **OXY MUSTANG STATE COM #1**

This work was done prior to rigging up the drilling rig for the sidetrack.

10/24/2006 CMIC: Henrich/Ross

Move in and rig up equipment. TBG running over. Pump 10bbls of 10# brine at 1500psi. Tbg now standing full but not running over. ND tree, NU BOP. SION.

10/25/2006 CMIC: Henrich/Ross

SITP 0psi, SICP (4 1/2")0psi, (inter)600psi,(surf)0psi. Blow inter.csg down to 0psi in 45min.no fluid. Trip out of hole with 344jts. of 2 7/8"tbg. Rig Schlumberger up. Run 3.75 gauge ring to 10,700'. Set 4.5"CIBP at 10,600'. Run dump bailer and cap plug with 35' of cement on top of CIBP. Top of cement 10,565'. Rig Schlumberger down. SION.

10/26/2006 CMIC: Henrich/Ross

SICP (4 1/2)0psi, (8 5/8) slight blow, (13 3/8) 0psi. Rig Scientific Drilling Wireline up. Run Gyro from 10,000' to surface. Run 2 3/8 SN, 329jts tbg to 10,120'. Displace hole with 141bbls of 10# brine. Pump 25 sack cement plug. Trip out with 329jts of tbg. SION.

10/27/2006 CMIC: Henrich/Ross

hold safety meeting,0# sip,nd bop,nd wh,spear 4.5" csg.,pull max. that rig could pull & could not get slips to release,wrap wh w/prima cord & shoot wh,slips came free but could not get out of wh,weld slips to csg. & pull out of wh,ru rotary wl,rih w/free point tools,csg. showed to be 100% free @ 8500',pooh,rih w/jet cutter & cut csg. @ 8500',pooh,try to pull csg. free w/no success,rih w/another cutter & cut csg.@ 8495',pooh,rd wl,(csg. cut this time)nu wh & bop,ru csg. crew & lay down machine, lay down top lading jt. of csg.,sisd!

10/28/2006 CMIC: Henrich/Ross

Shut In.

10/30/2006 CMIC: Henrich/Ross

SICP (4 1/2)0psi,(8 5/8)0psi,(13 3/8)0psi. Lay down 199jts and 6'cut jt. of 4 1/2"csg. Change rams. Run 279jts 2 3/8tbg to 8590'. (Found top of 4 1/2"csg stub at 8475' by tbg tally.) SION. This report was for

10/31/2006 CMIC: Henrich/Ross

Rig up Halliburton, displace hole with 500bbls of 10#brine. Pump 50sx class H cement, spot plug from 8590'to 8350' Rig down Halliburton. Lay down 279jts of 2 3/8tbg. ND BOP&WH. NU 11" 5M Blind Flange. RD and move off of location. All equipment, released and removed from location. Turn well over to Drilling Dept.

## **OXY MUSTANG STATE COM #1 - Completion**

12/27/2006 CMIC: Barton

MIRU pulling unit and reverse unit. Spot pipe racks and unload 350 joints of new L-80 2? tubing. (23 joints less than ordered.) NU BOP and test, OK. Pick up and RIH W/ 4¾ bit, 6-3½ drill collars, and 125 joints of tubing. SION Prep to drill out DV tool.

12/28/2006 CMIC: Barton

Tag cmt on top of DV tool at 8060'. Test to 1000# OK. Drill 10' of cmt and DV tool. Test to 1000# OK. SDON. Prep to finish in hole

12/29/2006 CMIC: Barton

Finish in hole and tag @ 11,371'. Circ hole clean. Start out of hole and had rig problems. SION. Prep to repair rig in am.

12/30/2006 CMIC: Barton

Finish out of hole. Pick up and run bit and scrapper. Dress DV tool with scrapper. Finish in hole with bit and scrapper to 11,340'. Circ. hole with 6% KCL. POOH. Prep to log and perforate.

01/02/2007 CMIC: Barton

Open well up with 0#. Finish OOH. Pick up and RIH W/ 4 ¾ bit and 5 ½ scrapper. Dress DV tool with scrapper. Finish in hole to 11,340. Circ hole with 6% KCL. POOH SION Prep to log.

01/03/2007 CMIC: Barton

Wait on Schlumberger. Wireline could not show. SION Prep to log.

01/04/2007 CMIC: Barton

Rig up Schlumberger. Run CBL from 8,000 - 11,347. Pressure casing to 1000# and run CBL again. Wireline PBTD @ 11,347. SION Prep to perf.

01/05/2007 CMIC: Barton

Rig up Schlumberger. Perforate Morrow as follows: 11164-72, 11186-89, 11214-16, 11221-26, and 11236-60 with 2 JSPF. Fluid level for all runs, surface. No pressure. Rig down Schlumberger. Pick up and run in hole 2 3/8 wireline entry guide, 1.81 F nipple, mechanical set Baker Hornet pkr, L-10 on/off tool W/ 1.87 ID, on 351 joints of new 2 3/8 L-80 tubing. Set packer @ 11,104 W/ 13 points of compression. Nipple down BOP and nipple up tree. SION Prep to acidize.

01/06/2007 CMIC: Barton

Open up well with 0# press. Rig up Stinger and Halliburton. Acidize well W/2,000 gal of 7 ½% HCL, 12 tons of CO2, and 75-1.3 sg balls. Some ball action. (From 5000# to 6400#) Av. Rate 4.1 bpm Av. pressure 5474# Av. Max rate 4.3 bpm Max pressure 6948#. ISIP 4144# 5 min. SI 3815# 10 min SI 3568#. 15 min SI 3337#. Load to recover 130 bbls. Start flowing well back @ 3:00 pm. Recover 25 bbls in 15 hours. 105 bbls left to recover.

01/07/2007 CMIC: Barton

Continue shutting in well for pressure buildup and flowing until dead. Well will not stay flowing. Recover 16 bbls. Load to recover 89 bbls.

01/08/2007 CMIC: Barton

Make 9 swab runs. Starting fluid level 4600'. Ending fluid level was scattered to seat nipple. Recovered 24 bbls. Load to recover 65 bbls. SION Prep to RDMO

01/09/2007 CMIC: Barton

RD pulling unit

01/10/2007 CMIC: Barton

MIRU pulling unit. Well had 2200# of SI tubing pressure. Blow down tubing in 50 minutes. Did not recover any fluid. SION Prep to POOH W/ packer & tubing. Set 2 Key frac tanks and fill with 360 bbls of 6% KCL

01/11/2007 CMIC: Barton

Open well up with 1500# press. Blow down tubing. Load tubing with 25 bbls of 6% KCL. Release packer and POOH. ND BOP and NU frac valve. SION Prep to Frac on Saturday the 12th.

01/12/2007 CMIC: Barton

Rig up Halliburton and Stinger. Attempt to load intermediate casing. Casing would not load. Wait on Halliburton 5 hours. Frac Morrow perfs 11,164' - 11,260' W/ 50.000 lbs. of versa prop and 178 tons of CO2. Av rate 41 bpm. Av pressure 5,657#. Max rate 43.5 bpm. Max pressure 6,326#. ISIP=4,534# 5 min=4,159# 10 min= 4,072# 15 min= 4,019# Load to recover 520 bbl. RD Halliburton and Stinger. Flow well back. In 15 hours well was flowing on a ½ choke at a 1300 MCF/24 hr rate. CO2 content 50%. Recovered 296 bbls of liquid. Load left to recover 224 bbls.

## 01/13/2007 CMIC: Barton

Recovered 80 bbls of liquid. Well flowing on a ¾ choke at a 1200 MCF/24 hr rate. CO2 content 12%. Load left to recover 144 bbls.

### 01/16/2007 CMIC: Barton

flow back well on 48/64 choke. from 7am to 11am pressure fluctuated between 80# and 120#. from 11am to 3pm pressure was at 100#. from 3pm to 4pm it was at 75#. recovered 20bbls of water. 124bbls of load left to recover.

## 01/17/2007 CMIC: Barton

SICP=2000#. Rig up Schlumberger, RIH with gauge ring to 11,262' tagged fill RIH with Baker packer and on&off tool set packer at 11,090'. ND frac valve. RIH with 75 stands of 2 3/8tbg.

## 01/18/2007 CMIC: Barton

Finish running 2 3/8tbg.(100 stands). Circulate packer fluid.(250bbls). Space out packer and test to 1000#. Tested OK. ND BOP NU TREE. Swab fluid down to 5500'. Rig up Pro Wireline, and pull plug out of packer. Turn well over to flowback hand.

6:00PM. Tbg. pressure=1450, open well on 24/64 choke.

6:00AM. Tbg pressure=400# choke on 24/64 choke. Recovered 47bbls of water, rate=1362mcf. CO2 is at 8%.

# 01/19/2007 CMIC: Barton

Flowback well

7AM TBG pressure400#, rate=1362, CO2=8%

6AM TBG pressure=330# rate=1124, CO2=3%

Recovered 59bbls of water.

Rig down PU and move to Fed.AB #4

Rig down flowbac manifold and release.

DATE	Oil	Water	Gas	Hrs	WHP	Choke
02/03/07	20	45	762	24	1100	16
02/04/07	15	9	1168	24	700	22
02/05/07	11	20	1109	24	550	22
02/06/07	14	32	1101	24	490	64
02/07/07	13	33	1076	24	450	64
02/08/07	11	18	1090	24	490	64
02/09/07	14	36	965	24	470	64
02/10/07	15	12	930	24	450	64
02/11/07	5	11	904	24	400	64
02/12/07	11	20	878	24	440	64