Submit 3 Copies To Appropriate District		lew Mexico					Form C	
Office District 1	Energy, Minerals and	d Natural Re	sources	TWELL ADI	NO		May 27	, 2004
1625 N. French Dr., Hobbs, NM 87240	077 00170PPY		******	WELL API	NO. 30-015-	34316		
District II 1301 W Grand Ave., Artesia, NM 88210	OIL CONSERVA			5. Indicate				
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South		Dr.	STA			Е 🗆	
District IV	Santa Fe,	NM 87505		6. State Oi				
1220 S. St Francis Dr., Santa Fe, NM 87505				o. State Of	1 & Gas	Lease No	J.	
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	ES AND REPORTS O SALS TO DRILL OR TO DE ATION FOR PERMIT" (FOR	EDEN OD DI II	IG BACK TO A SUCH 2 2008	7. Lease N Red Lake			eement Nar	ne:
1. Type of Well:		ACD A	~ 2000	8. Well Nu	mber			
Oil Well X Gas Well	Other	OCD-A	riesia		1			
2. Name of Operator				9. OGRID 1	Number			
Nearburg Producing Company				_	0157	42		
3. Address of Operator			•	10. Pool na	ame or V	Vildcat		
3300 N A St., Bldg 2, Ste	<u>120, Midland, TX 79</u>	9705		Red Lake;	San A	<u>Andres</u>		
4. Well Location								
Unit Letter G:	feet from the _	North	line and	1650	feet fron	n the	East	_ line
Section 32	Township 1	.7S Range	27E	NMPM	Eddy	County	/	}
3000000	11. Elevation (Show w							
Pit or Below-grade Tank Application	or Closuro	3432						
			U D'	C	4			
Pit type Depth to Groundwater .								
Pit Liner Thickness: mil	Below-Grade Tank: `	Volume	bbls: Constructi	on Material				
		idicate Natu	re of Notice,	Report, or SEQUEN	Other	Data ORT C ALTER PLUG	OF: RING CASII	NG [
12. Check A NOTICE OF INTE	ENTION TO: PLUG AND ABANDON	ndicate Natu	re of Notice, SUB EDIAL WORK	Report, or SEQUEN [ING OPNS. [Other	Data ORT C ALTER PLUG	OF: RING CASI	vg []
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	ndicate Natu	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND	Report, or SEQUEN [ING OPNS. [Other	Data ORT C ALTER PLUG	OF: RING CASII	₩
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state	Idicate Natu REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work).	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For M	REMI COM CASI CEMI OTHE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv	Report, or SEQUEN [ING OPNS. [work e pertinent da	Other T REP	Data ORT C ALTER PLUG ABANE	DF: RING CASII AND DONMENT	
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. See attached work performed.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For Med to test San Andres	Adicate Nature REMI COM CASI CEMI OTHE all pertinent Multiple Comp	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv bletions: Attach	Report, or SEQUEN [ING OPNS. [Work e pertinent dans wellbore dia	Other T REP	Data ORT C ALTER PLUG ABANE	OF: RING CASII AND DONMENT imated date d completic	X en
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. See attached work performed starting and tank has been will be constructed or	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For Med to test San Andres	REMI COM CASI CEMI OTHE e all pertinent Multiple Comp s formation	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ENT JOB ER: Plugback details, and giv bletions: Attack	Report, or SEQUEN' [ING OPNS. [work e pertinent dan wellbore dia	Other T REP	Data ORT C ALTER PLUG ABANE	OF: RING CASII AND DONMENT imated date d completic	X e e low-plan
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. See attached work performed.	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For Med to test San Andres	REMI COM CASI CEMI OTHE e all pertinent Multiple Comp s formation to the best of guidelines X, TITLE	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ER: Plugback details, and giv bletions: Attach	Report, or SEQUEN [[] [] [] [] [] [] [] [] []	of Other T REP	Data ORT C ALTER PLUG ABANE uding esti proposed proposed certify that native OC DATE	DF: AND DONMENT imated date d completic	X e e low-plan
12. Check A NOTICE OF INTE PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. See attached work performed starting and tank has been will be constructed or	ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION operations. (Clearly state SEE RULE 1103. For Med to test San Andres	REMI COM CASI CEMI OTHE e all pertinent Multiple Comp s formation	re of Notice, SUB EDIAL WORK MENCE DRILL NG TEST AND ER: Plugback details, and giv bletions: Attach	Report, or SEQUEN' [ING OPNS. [work e pertinent dan wellbore dia	of Other TREP description I further of hed) alter	Data ORT C ALTER PLUG ABANE uding esti proposed retify that native OC DATE	DF: AND DONMENT imated date d completic	X elow-plan [

APPROVED BY_______ TITLE _____ FOR RECORDS ONLY

Conditions of Approval, if any:

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Red Lake 32 State G #1

1750 FNL and 1650 FEL
Sec 32, 17S, 27E
Red Lake; Glorietta-Yeso
Eddy County, New Mexico
** ALL COSTS ARE FIELD ESTIMATES **

11/28/07

Move pulling unit from Wright #1 to location. MIRU Lucky Well Service pulling unit. Blow tbg pressure dn. Well was still pumping OK when we shut well dn. Recomplete well in the San Andres formation. Unhang well. POOH & LD 1 1/2" x 22' PR w/ 1 3/4" x 12' PRL. Tried to unseat pump, but couldn't after working on it for awhile. Had to backoff rods w/ backoff tool. POOH checking every break w/ (4) 7/8" x 2' x 2' x 4' x 6' "D" pony rod subs, (60) 7/8" x 25' "D" rods w/ FHTC, (56) 3/4" x 25' "D" rods w/ FHTC, (8) 1 1/2" x 25' Grade K sinker bars w/ 3/4" pins. Backed off on top of the pump, leaving the right hand release (backoff tool) and pump in seat nipple. ND WH & NU BOP. POOH w/ 14 jts- 2 7/8" J-55 tbg to FL. RU to swab FL dn inside tbg. Swab fluid back dn csg w/ perforated tbg sub. POOH & LD perforated tbg sub after LD swab line. Put TIW valve in tbg. Open csg into flowline. SDFN. Will finish POOH w/ 2 7/8" tbg in the AM before RU JSI to set CIBP. Had Two-State deliver a 500 Bbl frac tank to circulate into.

Current Operation This AM: POH w/ tbg.

11/29/07

Remove TIW valve from tbg. Open BOP rams. POOH w/ 69 jts- 2 7/8" J-55 6.5# EUE 8rd tubing. The pump was stuck in the jt above seat nipple. POOH w/ 2 7/8" API SSN & 1 jt- 2 7/8" J-55 tbg (open ended tail pipe) and LD along w/ 14 more jts to make a total of 15 jts LD on ground. Have 84 jts in derrick & 15 jts on ground. MIRU JSI electricline truck. RIH w/ 4.32" Gauge ring to 2800' to make sure csg was in good shape. POOH w/ gauge ring. RIH w/ gamma ray/CCL tools to log from 2800' up to 1800' correlating log w/ Schlumberger's open hole log. POOH w/ GR/CCL tools. RIH w/ 4.242" Alpha CIBP & set @ 2700'. POOH w/ Baker setting tool. RIH w/ 2 cement bailer dump runs putting a total of 35' cmt on top of CIBP. LD dump bailer. RDMO JSI electricline truck. Had TRM pump truck to load 5 1/2" csg w/ 56 Bbls 2% KCL wtr & pressure test plug to 2000#. Held pressure OK for 10 minutes. Bled dn csg pressure. Open BOP blinds. RIH w/ 2 7/8" API SSN, 81 jts- 2 7/8" J-55 6.5# EUE 8rd tubing to 2605'. Close BOP rams. RU Crain acid truck to tbg to pickle tbg. Start pumping 350 gals xylene @ 1.5 bpm dn tbg then went to 750 gals 15% NEFE acid followed by 80 Bbls 2% KCL wtr w/1 gpt ClayMaster to circulate acid dn tbg & out csg to frac tank leaving clean fluid in wellbore. RDMO Crain acid truck. Put TIW valve in tbg. Close BOP rams. SI well. SDFN. Had Malone welding cut out pump from last jt of tbg. Had Banta roustabout gang haul 12 jts- 2 7/8" J-55 tbg to yard that was layed down. Will swab csg FL dn in the AM before POOH w/ tbg. JSI will perforate also in the AM. Current Operation This AM: Swab well.

11/30/07

RU to swab 2 7/8" tbg to pull csg FL dn to 700' FS before perforating to create an underbalanced. Made 3 swab runs to frac tank bringing back 20 Bbls wtr. POOH w/ 81 jts- 2 7/8" J-55 6.5# EUE 8rd tubing, 2 7/8" API SSN. RU JSI electricline truck to RIH w/ csg gun to perforate San Andres formation from 1949'- 1952', 1958'- 1960', 1975'- 1978', 2041'- 2042', 2045'- 2046', 2103'- 2106' and 2111'- 2113' @ 1 spf w/ 120 degree phasing making a total of 22 holes. Correlated gun on depth w/ Schlumberger Three Detector Litho-Density Compensated Neutron log dated 3-8-06. Perforated under a 5000# lubricator. POOH w/ shot gun. RDMO JSI electricline truck. PU & RIH w/ 2 7/8" x 6' N-80 tbg sub, 32A tension pkr, 2 7/8" API Standard Seat Nipple, 57 jts- 2 7/8" J-55 6.5# EUE 8rd tubing. Set pkr @ 1843' in 15,000# tension. RU to swab 2 7/8" tbg. Made 1 swab run pulling from SN and did not bring back any fluid. Well took fluid after perforating. LD swab line. Put TIW valve in tbg. SI well. SDFW. Will make another swab run in the AM before RU BJ Services to acidize perforations. Current Operation This AM: Swab.

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Red Lake 32 State G #1

1750 FNL and 1650 FEL Sec 32, 17S, 27E Red Lake; Glorietta-Yeso Eddy County, New Mexico

** ALL COSTS ARE FIELD ESTIMATES **

12/03/07

RU to swab 2 7/8" tbg. Made 1 swab run pulling from SN. Had no fluid entry over the weekend. Did not bring back any fluid to frac tank. RD swab line. MIRU BJ Services to acidize perforations from 1949'- 2113' w/ 1250 gals 15% NEFE HCL acid dropping (44) 7/8" 1.3 sp gr ball sealers & flushing to btm perf. Had TRM pump truck load csg backside & hold 500# on csg while pumping acid job for pkr monitoring purposes. Had 2% KCL wtr w/1 gpt ClayMaster loaded on truck for flush. Had safety meeting. Test lines to 5000#. Start pumping 250 gals (5.9 Bbls) 15% NEFE acid @ 1.1 bpm rate until csg loaded w/ 10.7 Bbls pumped. Increased rate to 2.6 bpm w/ formation breaking back @ 3400#. Brought rate up to 4 bpm @ 2254# tbg pressure. Pumped 5 stages of (5.9 Bbls) 15% NEFE acid dropping 4 drops of 11 (44 total) between each of 1.3 sp gr ball sealers. Went to flush pumping 17.1 Bbls 2% KCL wtr @ 4.3 bpm. Balled out two different times pumping acid away on flush. Had to surge balls. Finished pumping flush to btm perf. SD. ISDP- 765#. 5 min- 717#, 10 min-702#, 15 min- 693#. Treating pressure: MAX- 4000#, MIN- 898#, AVG- 2250#. Injection rates: Treating fluid- 4 bpm, Flush- 4 bpm. Have 46.8 Bbls load to recover. RDMO BJ Services acid trucks. Left well SI for 2 hrs to let acid spend on perforations. Had 600# tbg pressure when opening well to start flowing back @ 12:00 (noon). Flowed well to frac tank for 1 1/2 hrs before well open to full choke. Flowed back 35 Bbls wtr before well quit flowing. RU to swab 2 7/8" tbg. Made a total of 4 swab runs pulling each run from SN and brought back 2 1/2 Bbls wtr for a total recovered of 37.5 Bbls. Have 9 Bbls still to recover. Release pkr. RIH w/ 9 jts- 2 7/8" J-55 tbg to below btm perf to knockoff any ball sealers that may have been stuck in perforations. POOH w/ those 9 jts- 2 7/8" tbg. Continue to POOH w/ 57 jts- 2 7/8" J-55 tbg, 2 7/8" API SSN, 32A tension pkr w/ unloader, 2 7/8" x 6' tbg sub. Close BOP blinds. Open csg into flowline. SDFN. Will ND BOP & NU Stinger frac valve in the AM.

Current Operation This AM: Swab.

12/04/07

Open BOP blinds to blow csg dn. ND BOP & NU Stinger frac valve. Had TRM pump truck on standby to kill well if needed, but it wasn't needed. MIRU BJ Services pump trucks to frac well dn csg. RU Stinger csg saver on top of frac valve on wellhead. BJ tested lines to 5000#. Open well w/ 0# csg pressure. Start pumping 643 Bbls Lightning 2000 as pad @ 51 bpm rate w/ 1054# csg pressure. Staged to 224 Bbls Lightning 2000 w/ 1# (ppg) SB Excel 20/40 sand (as 1st stage w/activator). The following is a breakdown of proppant pumped:

Csg Psi	Bbls Pumped	BPM Description	
1470#	224.4	51.8 1# (ppg) SB Excel 20/40 resin coated (activated	.)
1366#	390.8	51.8 2# (ppg) SB Excel 20/40 resin coated (activated)
1309#	396.4	51.6 3# (ppg) SB Excel 20/40 resin coated (activated	.)
1260#	100.9	50.8 4# (ppg) SB Excel 20/40 resin coated (activated)
1247#	44.3	52.6 Flush (20# Linear Gel)	

Shutdown pumps. ISDP @ 956#. 5 min- 834#, 10 min- 795#, 15 min- 782#. Treating pressures: MAX- 3400#, MIN- 800#, AVG- 1300#. Injection rates: Treating fluid- 51 bpm, Flush- 51 bpm. RD Stinger csg saver. RDMO BJ Services pump trucks. Have 1802 Bbls load wtr to recover. RU Pro well testing frac manifold up to wellhead. Left well shut in for resin to set. Will start flowing well back to frac tank in the AM. Pumped 99,180# proppant into perforations.

Current Operation This AM: Flow back.

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Red Lake 32 State G #1

1750 FNL and 1650 FEL

Sec 32, 17S, 27E

Red Lake; Glorietta-Yeso Eddy County, New Mexico

12/05/07 Opened well to Pro flowback manifold. Had 420# csg pressure @ 7:00 AM. Opened well to start flowing back to frac tank on a 12/64" choke trying to keep rate @ 20 bph rate. The following is an hourly breakdown of the flowback results:

Time	Csg Psi	Choke	Bbls/Hr flw bck	Comments
7:40 AM	420#	12/64"	0	Frac tank had 56" wtr to start (212 Bbls)
8:00 AM	415#	12/64"	13	
9:00 AM	375#	12/64"	24	TRM hauled 130 Bbls wtr to disposal
10:00 AM	330#	14/64"	25	
11:00 AM	300#	14/64"	23	TRM hauled 130 Bbls wtr to disposal
12:00 noon	260#	14/64"	26	
1:00 PM	200#	16/64"	26	
2:00 PM	120#	20/64"	34	Increased rate to 30 bph
3:00 PM	80#	20/64"	32	TRM hauled 130 Bbls wtr to disposal
4:00 PM	30#	20/64"	29	
5:00 PM	15#	22/64"	31	

Increase rate & checking for sand in returns. Flowing back more aggressive if sand allows. Flowed back a total of 263 Bbls in 9.5 hrs today averaging 27.6 bph rate. Have a total to recover of 1802 Bbls. Have 1539 Bbls total left to recover. Kept Pro flowback hand watching well flow back to frac tank overnight. If well allows we will RIH w/ bailer to bail sand before RIH w/ production tomorrow AM.

Current Operation This AM: RIH w/ bailer on tbg.

12/06/07

Well flowing through manual choke on manifold. Had 0# csg pressure @ 7:00 AM. Well flowing back to frac tank on a full open choke bringing back 61 Bbls wtr from 5:00 PM yesterday to 7:00 AM this morning. ND Stinger frac valve. NU BOP. PU & RIH w/ 2 7/8" notched collar, (2) 2 7/8" check valves, 16 jts- 2 7/8" J-55 tbg, 2 7/8" S&P bailer, 65 jts- 2 7/8" J-55 tbg. Tag fill (TOS) @ 2632' by tally. Have 33' of sand to bail. Bailed dn to 2652' w/ next jt of tbg leaving 13' of sand above TOC @ 2665'. POOH & LD 14 jts- 2 7/8" J-55 tbg on ground to take to yard. Continue to POOH standing back 52 jts- 2 7/8" J-55 tbg, 2 7/8" S&P bailer, 16 jts- 2 7/8" J-55 tbg (emptying cavity), (2) 2 7/8" check valves & 2 7/8" notched collar. The last it was full of resin coated sand. PU & RIH w/ 1 it- 2 7/8" J-55 tbg (open ended as tail pipe), new 2 7/8" API Standard Seat Nipple, 70 jts- 2 7/8" J-55 6.5# EUE 8rd tubing. ND BOP & NU WH. PU & RIH w/ 2 1/2" x 2" x 20' RHBC HVR pump w/ HW SCID Bbl (+.001"), 2" x 4' SM plngr (-.006"), DV T/C b&s, 1' LS & SRG w/ 1 1/2" x 6" strainer nipple, (8) 1 1/2 x 25' Grade K sinker bars w/ 3/4" pins, (56) 3/4" x 25' "D" rods w/ FHTC, (23) 7/8" x 25' "D" rods w/ FHTC, (3) 7/8" x 8' x 4' x 2' "D" pony rod subs w/ FHTC, 1 1/2" x 22' PR w/ 1 3/4" x 12' PRL. Space pump 8" off btm. Hang well on. RU TRM pump truck to test tbg to 500#. Held good pressure & had good pump action. The wind was blowing too hard to RD pulling unit. Put well on production @ 4:00 PM. SDFN. Flowed back a total of 324 Bbls of the 1802 Bbls load. Still have 1478 Bbls load left to recover. Will RD pulling unit in the AM.

Current Operation This AM: Released to production.

12/07/07

Well pumping OK. SD pumping unit. RDMO Lucky Services pulling unit. Clean around wellhead & location. Release all equipment. Put well back on production. Will have Banta rebalance pumping unit today (weight heavy since coming up hole). FINAL REPORT. Current Operation This AM: Released to production.

^{**} ALL COSTS ARE FIELD ESTIMATES **