7007 2560 0002 2222 8360



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required - Deadline Enclosed

01-Dec-08

APOLLO ENERGY, L.P.6363 WOODWAY SUITE 1100
HOUSTON TX 77057-

LOV NO. 2-08-168

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

RUSSELL US	A No.009			30-015-02356-00-00
,		Active Oil (Producing)		O-13-20S-28E
Test Date:	11/20/2008	Permitted Injection PSI: 300	Actual PSI:	500
Test Reason:	Initial Test	Test Result: F	Repair Due:	2/23/2009
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on I	MIT: Injection pressure over	limit. Shut-in.		
RUSSELL USA	No.041			30-015-02390-00-00
	•	Active Oil (Producing)		F-13-20S-28E
Test Date:	11/20/2008	Permitted Injection PSI: 300	Actual PSI:	650
Test Reason:	Initial Test	Test Result: F	Repair Due:	2/23/2009
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	•
Comments on M	IIT: Injection pressure over	limit. Shut-in		
RUSSELL USA	No.049	,		30-015-06186-00-00
•	,	Active Oil (Producing)		B-13-20S-28E
Test Date:	11/20/2008	Permitted Injection PSI: 300	Actual PSI:	600
Test Reason:	Initial Test	Test Result: F	Repair Due:	2/23/2009
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on M	IIT: Injection pressure over	imit. Shut-in.		

RUSSELL USA No.050

30-015-06187-00-00

Active Oil (Producing)

B-13-20S-28E

Test Date:

11/20/2008

Permitted Injection PSI: 300

Actual PSI:

550

Test Reason: Test Type:

Initial Test

Test Result:

Repair Due:

2/23/2009

Std. Annulus Pres. Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT: Injection pressure over limit. Shut-in

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.