

Submit 3 Copies 10 Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
June 19, 2008

WELL API NO. 30-015-24732
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E30363
7. Lease Name or Unit Agreement Name Theos State
8. Well Number 1
9. OGRID Number
10. Pool name or Wildcat Grayburg, Jackson, SA,

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other	NOV 24 2008
2. Name of Operator Marks & Garner Production LTD., CO	OCD-ARTESIA
3. Address of Operator P.O. Box 108	
4. Well Location Unit Letter <u>G</u> : <u>1650</u> feet from the <u>NORTH</u> line and <u>1650</u> feet from the <u>EAST</u> line Section <u>05</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>EDDY</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

Notify OCD 24 hrs. prior
To any work done.

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Move in unit & rig up.
2. Run guage ring to 2500'
3. Set CIBP @ 2400'
4. Dump 35' cement on CIBP
5. pick up approx. 2350' tbg, & run in the hole
6. Circulate hole with mud gel
7. Come out of hole with tbg & lay down
8. set CIBP @ 1600'
9. Dump 35' cement on CIBP
10. spot 100' plug @ surface
11. Rig down unit
12. Cut off well head & install dry hole marker

* 100' cmt Plug @ B. Salt. @ 664'
(614' - 714') - WOC TAC

* 135' Top of Salt.
100' cmt Plug @ 8 3/8" CSG. Shoe.
(300' - 400') WOC TAG
265'

Spud Date:

Rig Release Date:

Approval Granted providing work
is complete by 3/3/09


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Quinton W. L. Brown TITLE Manager DATE 11-21-2008

Type or print name Quinton W. L. Brown E-mail address: Quilborm@union.net.com PHONE: 505-393-9358
For State Use Only

APPROVED BY [Signature] TITLE CO. DATE 12/3/08
Conditions of Approval (if any):

Theos State # 1



100' Cement Plug @ Surface

135'
8 5/8" @ 350' ~~100'~~ cement
* Plug. ~~265'~~ 265' - 400'
WOC TAC.
Top of Salt.

* 100' cement Plug. *
@ 664' - B. Salt.
614' - 714' WOC TAC

35' Cement
Set Cast Iron Bridge Plug @ 1600'

35' Cement
Set Cast Iron Bridge Plug @ 2400'

Perf @ 2453' - 2467'
5 1/2" Casing @ 2500'

1. Move in unit & rig up.
2. Run gauge ring to 2500'
3. Set CIBP @ 2400'
4. Dump 35' cement on CIBP
5. Pick up approx. 2350' tbgs & run in hole
6. Circulate hole with mud gel
7. Come out of hole with tbgs & lay down
8. Set CIBP @ 1600'
9. Dump 35' cement on CIBP
10. Spot 100' plug @ surface
11. Rig down unit
12. Cut off well head & install dry hole marker

* 100' cement plug. @ 8 7/8" CSG shoe
300' - 400' WOC TAC.