Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT Artesia, NM 88210 MELLS FORM A OMB NO Expires Jar Artesia, NM 88210 MM 033647B **BUREAU OF LAND MANAGEMENT**

Oil Cons.

FORM APPROVED OMB NO. 1004-0135 Expires January 31, 2004

Do not use this form for proposals to drill or to re-enter an

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or CA/Agreement, Name and/or No BOGIE FLATS UNIT	
ype of Well Oil Well X Gas Well Other RECEIVED			8. Well Name and	- · · · - ·		
2. Name of Operator KERR MOSEE OIL & GAS ONSHORE, LLC		DEC	29 7003	9. API Well No.		
3a. Address 16666 NORTHCHASE, HOUSTON, TEXAS 77060		3b. Phone No. (1997) APPLES A 281-673-6590		30-015-31080 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2185' FNL & 1650' FEL				INDIAN BASIN; UPPER PENN 11. County or Parish, State		
SEC. 17, TWP. 22S, RGE. 23E 12. CHECK APPROPRIATE	BOY/ES) TO IN	DICATE NATURE OF	NOTICE DED	EDDY	NM	
TYPE OF SUBMISSION	E BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION					
Notice of Intent	Acidize	Deepen	Production	1 (Start/Resume)	Water Shut-Off	
Subsequent Report	Alter Casing Casing Repair	Fracture Treat New Construction	Reclamation Recomple			
X Final Abandonment Notice	Change Plans Convert to Inject	Plug and Abandon Plug Back	Temporari	ily Abandon posal		
13. Describe Proposed or Completed Operation (clear						

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

KERR MCGEE OIL & GAS ONSHORE, LLC REQUESTS APPROVAL TO PLUG AND ABANDON THE SUBJECT WELL PER BLM SPECIFICATIONS AS PER THE ATTACHED PLUGGING PROCEDURE. IF YOU SHOULD HAVE ANY QUESTIONS OR CONCERNS PLEASE CONTACT DAVID EYLER @ 432.687.3033.

APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS ATTACHED

14. I hereby certify that the foregoing is true and correct Name (Printed Typed)	Title					
DAVID A. EYLER	AGENT					
Daudh. E.l	Date 12/11/03					
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved by (ORIG. SGD.) ALEXIS C. SWCBODARD	THETROLEUM ENGINEER	Data DEC 2 2 2003				
Conditions of approval, if any, are attached. Approval of this solice does not warran certify that the applicant holds legal or equitable title technology rights in the subject k which would entitle the applicant to conduct operations thereon.	t of Office					

Kerr McGee Oil & Gas Onshore, LLC

Bogle Flats #21

A.P.I. #: 30-015-31080 Lease Serial #: NM 033647B Field: Indian Basin; Upper Penn

Location: 2185' FNL & 1650' FEL, Sec. 17, Twp. 22S, Rge. 23E

Eddy County, New Mexico

Completion Date: 2000

Total Depth: 7,600' P.B.T.D.: 7.515'

Casing Data: 9-5/8" 36# K-55 @ 1340' w/ 1250 sxs. - TOC = Surface

7" 23# K-55 @ 7600' w/ 370 sxs. – TOC = 4930' (CBL – 05/27/00)

Tubing Data: 2-7/8" 6.5# L-80 IPC @ 7580' w/ 3/8" SS capillary string

Rod Data: None – sub-pump Open Perfs: 7070'-7270'

Remarks: None

PXA PROCEDURE

1) MIRU workover rig, cable spooler & PXA equipment.

- 2) ND wellhead & NU BOP's; POOH w/ 2-7/8" tubing & sub pump; Remove sub pump & PU 7" CBIP; RIH w/ CIBP & tubing to 7050'; Set CIBP & mix & pump a 15 sx. cmt. plug on top of CIBP @ 7050'; Circ. well w/ pxa mud & POOH laying down tbg. to 6850'; Mix & pump a 90 sx. cmt. plug @ 6425'-6850'; POOH w/ tbg. standing back 4050' & laying down the balance.
- 3) ND BOP's & NDWH & NU csg. equip.; Work stretch on 7" csg.; RUWL & RIH & cut 7" csg. (estimated recovery = 4000'); POOH & RDWL; POOH laying down 7" casing.
- 4) ND csg. equip. & NUWH & NU BOP's; RIH w/ tubing OE to 4050'; Mix & pump a 75 sx. cmt. plug @ 4050'; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug; POOH laying down tbg. to 1340'; Mix & pump a 60 sx. cmt. plug @ 1340'; POOH w/ tbg. & WOC; RIH w/ tbg. & tag top of cmt. plug; POOH laying down tbg. to 400'; Mix & pump a 60 sx. cmt. plug @ 400'.
- 5) POOH laying down tubing to 63' & mix & pump a 30 sx. cmt. surf. plug @ 3'-63'. FOOH w/ tubing.
- 4) Dig out and cut off well head 3' B.G.L.; Weld steel plate on top of casings & set dry hole marker.
- 5) RDMO rig and PXA equipment. Clean location.

