

LENTINI FEDERAL COM NO. 1  
2010' FSL AND 1980' FWL  
SECTION 9, R28E, T23S  
EDDY COUNTY, NEW MEXICO

RECEIVED

MAR 3 11 55 AM '93

CARL  
AREA

Plugging Procedure (see attached schematic)

1. MIRU PU. ND WH. NU BOP.
2. RIH with tubing and spot 200' plug on top of CIBP at 5894' (+/- 50 sacks of cement).
3. PU 300' above TOC and WOC. RIH and tag plug. POOH with tubing.
4. RU wireline unit with jet cutter.
5. RIH with jet cutter and cut casing at +/- 5600'. POOH and LD 7 <sup>5</sup>/<sub>8</sub>" casing. RD wireline unit.
6. RIH with tubing and spot 200' plug at 2750' ( +/- 115 sacks of cement ).  
NOTE: 56' of cement in open hole and 144' of cement above 10 <sup>3</sup>/<sub>4</sub>" casing shoe.
7. PU 300' above TOC and WOC. RIH and tag plug.
8. POOH and LD all but 450' of tubing.
9. Spot cement from 450' to surface ( +/- 225 sacks of cement ). POOH and LD tubing.
10. Cut off WH and 10 <sup>3</sup>/<sub>4</sub>" casing 3' below GL. Top off cement to surface.
11. Install dryhole marker.
12. Fill in cellar, clean up and restore location. RDMO PU. Notify Gene Atkins that all operations have been completed. Procedure