

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-33305
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VO-4972
7. Lease Name or Unit Agreement Name Southern Cross 32 State
8. Well Number 3
9. OGRID Number 013837
10. Pool Name or Wildcat Yeso

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960 Artesia, NM 88210	
4. Well Location Unit Letter <u>H</u> <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>East</u> line Section <u>32</u> Township <u>18S</u> Range <u>24E</u> NMPM County <u>Eddy</u>	
11. Elevation (Show whether DR, RKB, RT, GR etc) 3780' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIALWORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐


**Notify OCD 24 hrs. prior
to any work done.**

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Notify OCD 24 hours prior to starting plugging operations.

1. Set CIBP @ 1875' w/35' cmt cap.
2. Pump 25sx plug from 1730-1830'. Cover Glorieta.
3. Pump 25sx plug from 1158-1258'. Cover surface shoe. - WOC, Tag
4. TIH to 60' circulate cmt to surface.
5. Install Dry Hole Marker.

Note: All plugs set w/14.8ppg, 1.34 yield Class C.



**SEE ATTACHED
CONDITIONS OF
APPROVAL**

Spud Date: 4/15/2004

Rig Release Date: 5/12/2004

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 1/25/12

Type or print name Jerry W. Sherrell E-mail address: jerrys@mec.com PHONE: (575)748-1288

For State Use Only


APPROVED BY: [Signature] TITLE DATE 1/30/2012
Conditions of Approval (if any):

Approval Granted providing work
is complete by 4/30/2012

Mack Energy Corporation
Southern Cross 32 State #3 30-015-33305

Before

After



8 5/8 @ 1208' cmt
w/780sx, circ.

Perfs 1916-2286'

CIBP @ 2425' w/35' cap

Perfs 2483-2789'

CIBP @ 2905' w/35' cap

Perfs 2932-3133'

CIBP @ 3900' w/35' cap

Perfs 3939-4005'

CIBP @ 4950' w/35' cap

CIBP @ 5820' w/35' cap

Perfs 5901-6205'

CIBP @ 6260' w/35' cap

Perfs from 6269-6487'

Perfs from 6588-6653' sqzd w/518sx

CIBP @ 6740' w/35' cap

Perfs from 6814-7006'

4 1/2 @ 7027' cmt

TD @ 7028' w/2000sx, circ.



Circ cmt from 60' to
surface

25sx plug from 1158-1258'

8 5/8 @ 1208' cmt
w/780sx, circ.

25sx plug from 1730-1830'

CIBP @ 1875' w/35' cap

Perfs 1916-2286'

CIBP @ 2425' w/35' cap

Perfs 2483-2789'

CIBP @ 2905' w/35' cap

Perfs 2932-3133'

CIBP @ 3900' w/35' cap

Perfs 3939-4005'

CIBP @ 4950' w/35' cap

CIBP @ 5820' w/35' cap

Perfs 5901-6205'

CIBP @ 6260' w/35' cap

Perfs from 6269-6487'

Perfs from 6588-6653' sqzd w/518sx

CIBP @ 6740' w/35' cap

Perfs from 6814-7006'

4 1/2 @ 7027' cmt

TD @ 7028' w/2000sx, circ.