Office	State of N				Form C-103	
District I – (575) 393-6161	Energy, Minerals a	ınd Natu	ral Resources		Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283				WELL API NO. 30-015-24591		
811 S. First St., Artesia, NM 88210	OIL CONSERV	ATION	DIVISION	5. Indicate Type	of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South				FEE	
<u>District IV</u> - (505) 476-3460	Santa Fe,	, NM 87	505	6. State Oil & G	as Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				L-654		
	CES AND REPORTS ON	WELLS		7. Lease Name of	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC				NEW MEXICO	DI STATE	
·	PROPOSALS.)					
2. Name of Operator				9. OGRID Numl	per 155615	
NADEL AND GUSSMAN PERMI	AN, LLC			10. Pool name of	r Wildoot	
3. Address of Operator 601 N. MARIENFELD, SUITE 508	3, MIDLAND, TEXAS 79	701			NE SPRING, GP 2	
4. Well Location				ĺ	,	
Unit LetterL:	1980'feet from the	_SOUTH	line and	660'feet from t	the _WESTline	
Section 19	Township 23S	Rang	·	NMPM	County EDDY	
	11. Elevation (Show whe	ether DR,	RKB, RT, GR, etc.,)		
	3470 GL					
12. Check A	ppropriate Box to Ind	licate N	ature of Notice,	Report or Other	Data	
NOTICE OF IN	• •		,	•		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\boxtimes	REMEDIAL WOR	SEQUENT RE	ALTERING CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRI		P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEN		FANDA	
DOWNHOLE COMMINGLE	MOLTH EL COMI E		CASINO/CEMEN	1 300		
i						
OTHER: 13. Describe proposed or compl	eted operations (Clearly	state all r	OTHER:	d give pertinent dat	res_including estimated date	
of starting any proposed wo						
proposed completion or reco			•	•	Č	
PLAN TO PLUG WELL BASED O	ON PLUGGING PROCE	EDURE 4	APPROVED ON 1	0/19/2001 NO C	HANGES TO	
WELLBORE HAVE OCCURRED						
ATTACHED.	CONDITIONS OF	• DDBOV	AL ATTACHED			
	Approval Grant	ed provi	ding work is		DEOCUED	
	Completed by	10	24-2013		RECEIVED	
		C) LL	0-1-0-		APR 2 4 2013	
N/A			N/A		NMOCD ARTESIA	
Spud Date:	Rig Re	elease Da	te:		I I I I I I I I I I I I I I I I I I I	
I hereby certify that the information a	hove is true and complete	to the be	est of my knowledg	e and belief		
	so to is a de diad complete	to the oc	or or my late wroag	e and belief.		
SIGNATURE /	TITL	E EN	GINEER	DATE 4/	/22/12	
SIGNATURE	1111.	EEIV	UINEEK	DATE4/	23/13	
Type or print nameJASON GOS	S E-mail address	: _JGOS	S@NAGUSS.COM	M PHONE:	432-682-4429	
For State Use Only	~ 0	\wedge	\mathcal{O}		1.1.	
APPROVED BY:	TITLE	Dist	HJYXW	11.0\ DA	ATE 4/24/2013	
Conditions of Approval (if any):					1 1	
SEE Attachments!					·	
JCC MINEUMON.						

Submit 3 Copies To Appropriate District Office Construction of	Professional Prof	District	Page		101
District	Professional Prof	Principle Prin	Principle Prin	Submit 3 Copies To Appropriate District 1117 State of New Mexico	Form C-103
New Mexico District L 1980' feet from the South line and South	District II South French Dr., Hobbs, NM&87240 A District II South Frist, Artesia, NM &7210 District II South Pacheco Santa Fr., NM &7505 CD. ARTESIA Santa Fr., NM &7505 Santa Fr., NM &7505 CD. ARTESIA	Medical District Medical Dis	Medical District Medical Dis	Offir Hards Minerals and Natural Decourage	C XC /
South First, Artesia, NM 87210 COpenhal State St	South First, Artesia, NM 87210 South Pacheco South Pache	Substitute State	Substitute State	A TOTAL CONTRACTOR OF THE PARTY	
District III 1000 Re Brazos Rd., Aziec, NM 87410 RECEIVE Santa Fe, NM 87505 Santa Fe, NM 87505 Santa Fe, NM 87505 Santa Fe, NM 87505 State Oil & Gas Lease No. L - 654	District III 1000 Nio Brazos Rd., Aziec, RM 87410 RECEIVE 2040 South Pacheco Santa Fe, NM 87505 L - 654	Sunday Received Shata Fe, NM 87505 Shata Fe	Sunday Received Shata Fe, NM 87505 Shata Fe		
SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS L - 654	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Lease No. 1. L - 654 7. Lease Name or Unit Agreement Name: Name: Name: New Mexico "DI" State 1. Type of Well: Oil Well Location New Mexico "DI" State Name: 1. Lees Name or Unit Agreement Name: New Mexico "DI" State Name: New Mexico "DI" State Name: 1. Lees Name or Unit Agreement Name: New Mexico "DI" State Name: 1. Lees Name or Unit Agreement Name: New Mexico "DI" State Name: 1. Lees Name or Unit Agreement Name: New Mexico "DI" State Name: 1. Lees Name or Unit Agreement Name: 1. Lees Name or Unit	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS, 1% 1984). OR TO DEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Name: Name: New Mexico "DI" State New Mexico	SUNDRY NOTICES AND REPORTS ON WELLS SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS, 1% 1984). OR TO DEEPER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Name: Name: New Mexico "DI" State New Mexico		·
SUNDRY NOTICES AND REPORTS ON WELLS The composition of the composi	SUNDRY NOTICES AND REPORTS ON WELLS T. 654	South Pacheco, Santa Fe, MN 87905 L - 654	South Pacheco, Santa Fe, MN 87905 L - 654	1000 Rio Brazos Rd., Aztec, MM 87410 COLIVE J District IV Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L: 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO BEFFEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS, TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS, TO BRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well		
DO NOT USE THIS FORM FOR PROPOSALS TO BEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well	DO NOT USE THIS FORM FOR PROPOSALS TO BEACH OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well	DO NOT USE THIS FORM FOR PROPOSALS, TILE BEALD IN SUCH PROPOSALS, TILE BEALD IN SUCH PROPOSALS.) Type of Well: Oil Well	DO NOT USE THIS FORM FOR PROPOSALS, TILE BEALD IN SUCH PROPOSALS, TILE BEALD IN SUCH PROPOSALS.) Type of Well: Oil Well	SUNDRY NOTICES AND REPORTS ON WELLS	
PROPOSALS.) 1. Type of Well: Oil Well	PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 Wildcat Bone Springs, WC GP 2 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Rope of Well: Other Other Other	Rope of Well: Other Other Other	(DO NOT USE THIS FORM FOR PROPOSALS TX) DEKLL OR TO DEEPEN OR PLUG BACK TO A	1
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	1. Type of Well: Oil Well	1. Type of Well: Oil Well	1. Type of Well: Oil Well		
2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ CHANGE PLANS □ COMMENCE DRILLING OPNS □ PLUG AND ABANDONMENT □	2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLANS OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Alac 100' Plug 29 3 4 5 30 34 4	2. Name of Operator Nadel and Gussman Permian, L.L.C. #155615 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION CHANGE PLANS OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Alac 100' Plug 29 3 4 5 30 34 4	1. Type of Well:	New Mexico "DI" State
Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 9. Pool name or Wildcat Wildcat Bone Springs, WC GP 2 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 9. Pool name or Wildcat Wildcat Bone Springs, WC GP 2 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 9. Pool name or Wildcat Wildcat Bone Springs, WC GP 2 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON EMEMBEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	Nadel and Gussman Permian, L.L.C. #155615 3 3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 9. Pool name or Wildcat Wildcat Bone Springs, WC GP 2 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON EMEMBEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDON CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.		
3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS ABANDONMENT	3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON COMMENCE DRILLING OPNS. PLUG AND TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	3. Address of Operator 601 N Marienfeld, Suite 508, Midland, Texas 79701 4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON COMMENCE DRILLING OPNS. PLUG AND TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	•	8. Well No.
4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Well Location Unit Letter: L 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County	Well Location Unit Letter: L 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County		Q Pool name or Wildcat
Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	4. Well Location Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND COMPLETION CASING TEST AND COMPLETION CASING TEST AND COMPLETION CASING TEST AND COMPLETION CHARGE. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud-TIH and spot sus plug across 8-518" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot **Example Completed Surface: Sex in casing, Sex in annulus.	Unit Letter: L : 1980' feet from the South line and 660' feet from the West line Section 19 Township 23 S Range 26 E NMPM Eddy. County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND COMPLETION CASING TEST AND COMPLETION CASING TEST AND COMPLETION CASING TEST AND COMPLETION CHARGE. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud-TIH and spot sus plug across 8-518" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot **Example Completed Surface: Sex in casing, Sex in annulus.	•	
Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ALTERING CASING OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 292 to 3034' 1. Load hole with 10 PPG salt gel much. Tilh and spot starting any group and tag plug. 2. Cut off wellhead and spot ~ 1524 cement at surface: Sax in casing, in annulus.	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ALTERING CASING OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 292 to 3034' 1. Load hole with 10 PPG salt gel much. Tilh and spot starting any group and tag plug. 2. Cut off wellhead and spot ~ 1524 cement at surface: Sax in casing, in annulus.		Wildeat Done Springs, We GI 2
Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ALTERING CASING OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 292 to 3034' 1. Load hole with 10 PPG salt gel much. Tilh and spot starting any group and tag plug. 2. Cut off wellhead and spot ~ 1524 cement at surface: Sax in casing, in annulus.	Section 19 Township 23 S Range 26 E NMPM Eddy County 1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS ALTERING CASING OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 292 to 3034' 1. Load hole with 10 PPG salt gel much. Tilh and spot starting any group and tag plug. 2. Cut off wellhead and spot ~ 1524 cement at surface: Sax in casing, in annulus.		A1
1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMMENCE DRILLING OPNS. PLUG AND ABANDON COMPLETION CEMENT JOB	1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING DEMENTION COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DESCRIBED TO THER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe proposed work). SEE RULE 1103. O2-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 29 36 16 30 36 1 1. Load hole with 10 PPG salt gel mud. TIH and spot with plug across 8-5/8" surface casing shoe from 1550' to 139'. WOC and tag plug. 2. Cut off wellhead and spot - 1550 cement at surface: See in casing, with annulus.	1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3476' GL 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUIS AND ABANDON COMMENCE DRILLING OPNS. ALTERING CASING DEMENTION COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT DESCRIBED TO THER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. Describe proposed work). SEE RULE 1103. O2-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Place 100' Plag 29 36 16 30 36 1 1. Load hole with 10 PPG salt gel mud. TIH and spot with plug across 8-5/8" surface casing shoe from 1550' to 139'. WOC and tag plug. 2. Cut off wellhead and spot - 1550 cement at surface: See in casing, with annulus.	Unit Letter: L : 1980' feet from the South line and 60	of eet from the West line
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS CASING TEMPORARILY ABANDON COMPLETION CASING TEST AND CEMENT JOB	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TiH and spot ** Sping across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ 1550 coment at surface: Sex in casing, ** in annulus.	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TiH and spot ** Sping across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ 1550 coment at surface: Sex in casing, ** in annulus.	Section 19 Township 23 S Range 26 E	NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot 29 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 2. Cut off wellhead and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud.	11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot 29 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 1. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 2. Cut off wellhead and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud. TIH and spot 20 3/2 to 30 3/4 3. Load hole with 10 PPG salt gel mud.		tc.)
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDON COMPLETION CASING CASING CASING CASING CASING CASING CASING CASING CASING TEST AND CEMENT JOB	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot Plug Ag 3 to 30 3 4 (1)	NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot Plug Ag 3 to 30 3 4 (1)		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	PERFORM REMEDIAL WORK PLUIG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OF ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Plug 29 32 to 30 36' Load hole with 10 PPG salt gel mud. Till and spot plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot temporary cement at surface: Sex in casing, tex in annulus.	PERFORM REMEDIAL WORK PLUIG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT OF CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Plug 29 36 16 30 36 16 Load hole with 10 PPG salt gel mud. TiH and spot 29 36 16 Load hole with 10 PPG salt gel mud. TiH and spot 29 36 16 Load hole with 10 PPG salt gel mud. TiH and spot 29 36 16 Load hole with 10 PPG salt gel mud. TiH and spot 20 36 36 Load hol		
TEMPORARILY ABANDON	TEMPORARILY ABANDON	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Plug 2936 to 3036' Load hole with 10 PPG salt gel mud. TiH and spot 200	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Plug 2936 to 3036' Load hole with 10 PPG salt gel mud. TiH and spot 200		<u> </u>
ABANDONMENT	PULL OR ALTER CASING	PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot response plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot time casing. Examinating any proposed work.	PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot response plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot time casing. Examinating any proposed work.	PERFORM REMEDIAL WORK PEOS AND ADAIDON REMEDIAL WO	ALTERING CASING L
	PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot 25 to 3034. 1. Load hole with 10 PPG salt gel mud. TIH and spot 25 to 150' to 150'. WOC and tag plug. 2. Cut off wellhead and spot - time cement at surface: 8 in casing, 25 in annulus.	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 1. Load hole with 10 PPG salt gel mud. TIH and spot 25 to 3034. 1. Load hole with 10 PPG salt gel mud. TIH and spot 25 to 150' to 150'. WOC and tag plug. 2. Cut off wellhead and spot - time cement at surface: 8 in casing, 25 in annulus.		
PULL OR ALTER CASING L. MULTIPLE	COMPLETION CEMENT JOB	OTHER: COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Pluq 2936 to 3036' Load hole with 10 PPG salt gel mud. TIH and spot 2500 plug across 8-5/8" surface casing shoe from 1550' to 1500'. WOC and tag plug. 2. Cut off wellhead and spot - 1500 cement at surface: 8500 in casing, 2500 in annulus.	OTHER: COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. Acc 100' Pluq 2936 to 3036' Load hole with 10 PPG salt gel mud. TIH and spot 2500 plug across 8-5/8" surface casing shoe from 1550' to 1500'. WOC and tag plug. 2. Cut off wellhead and spot - 1500 cement at surface: 8500 in casing, 2500 in annulus.	TEMPORARILY ABANDON	
COMPLETION CEMENT JOB		Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot are plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ the cement at surface: 8 ax in casing, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot are plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ the cement at surface: 8 ax in casing, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.		ABANDONMENT
OTHER:	OTHER:	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING MULTIPLE CASING TEST / COMPLETION CEMENT JOB	ABANDONMENT
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	PULL OR ALTER CASING MULTIPLE CASING TEST / COMPLETION CEMENT JOB	ABANDONMENT
starting any proposed work). SEE RULE 1103.	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT
02.04.84 Set CIRD at 4774' and cannod with 30' coment. I coded help with inhibited unter	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT
2204-04 Set Cibr at 4774 and capped with 50 cement Loaded note with inhibited water.	starting any proposed work). SEE RULE 1103.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Pe pertinent dates, including estimated date of
ρ_{loc} ρ_{loc} ρ_{loc} ρ_{loc} ρ_{loc} ρ_{loc} ρ_{loc}	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1. Load hole with 10 PPG salt gel mug. Till and spot and plug across 8-5/2" surface casing shoe from	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	2. Cut off wellhead and spot ~1 like cement at surface: 8 lin casing, 7 lin annulus.	2. Cut off wellhead and spot ~1 like cement at surface: 8 lin casing, 7 lin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1 1 6 APPALA MARKA 1 10100 14 1	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot 25 plug across 8-5/8" surface casing shoe from	3. Set dry hole marker. Clean location and pick up flowline.	3. Set dry hole marker. Clean location and pick up flowline.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ time cement at surface: 8 in casing, 2 in annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot a cement at surface: 8 in casing, a in annulus.			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ time cement at surface: 8 in casing, 2 in annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot a cement at surface: 8 in casing, a in annulus.			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ 155x cement at surface: 85x in casing, 55x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. Till and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	N. O. C.		PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ time cement at surface: 8 in casing, 2 in annulus.	1. Load hole with 10 PPG salt gel mud. TiH and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	Notify OCD 24 hrs. prior to any work done	Notify OCD 24 hrs. prior to any work done	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ 155x cement at surface: 85x in casing, 55x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. Till and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	Notify OCD 24 hrs. prior to any work done	Notify OCD 24 hrs. prior to any work done	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
2. Cut off wellhead and spot ~t accement at surface: 8 in casing, and in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done	1. Load hole with 10 PPG salt gel mud. TIH and spot are plug across 8-5/8" surface casing shoe from 1550' to 100'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: 8 in casing. The annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from the surface casing shoe
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ 155x cement at surface: 85x in casing, 55x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. TIH and spot are plug across 8-5/8" surface casing shoe from 1550' to 100'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: 8 in casing. The annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from the surface casing shoe
2. Cut off wellhead and spot ~t are cement at surface: 8 in casing, as in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief.	1. Load hole with 10 PPG salt gel mud. TIH and spot plug across 8-5/8" surface casing shoe from 1550' to 100' Plug across 8-5/8" surface casing shoe from 25 to 1550'	I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that the information above is true and complete to the best of my knowledge and belief.	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the pertinent dates.
2. Cut off wellhead and spot ~ tiest cement at surface: Sex in casing, in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01	1. Load hole with 10 PPG salt gel mud. TIH and spot response plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot response cement at surface: Sex in casing, response in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Threby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the pertinent dates.
2. Cut off wellhead and spot ~t are cement at surface: 8 in casing, as in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief.	1. Load hole with 10 PPG salt gel mud. Tith and spot representation and plug across 8-5/8" surface casing shoe from plus 1550' to 1303'. WOC and tag plug. 2. Cut off wellhead and spot reserve cement at surface: the in casing, the in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Title Operations Engineer DATE 9-20-01	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (
2. Cut off wellhead and spot ~1 are cement at surface: 8 in casing, as in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DATE 9-20-01	1. Load hole with 10 PPG salt gel mud. Till and spot with plug across 8-3/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot test cement at surface: test in casing, test in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded had 100' Play 2936. 1. Load hole with 10 PPG salt gel mud. TIH and spot 2500 plug acr 1550' to 250'. WOC and tag plug. 2. Cut off wellhead and spot 1550 cement at surface: 8500 in casin 3. Set dry hole marker. Clean location and pick up flowline. Notify I hereby certify that the information above is true and complete to the best of my knowledge. TITLE Operations Type or print name Robert McNaughton Telepho	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (
2. Cut off wellhead and spot ~ 1550' to 150'. WoC and tag plug. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915 - 682 - 4429 (This space for State use)	1. Load hole with 10 PPG salt gel mud. Till and spot representation and spot r	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use)	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use)	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (to 3
		starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING MULTIPLE CASING TEST / COMPLETION CEMENT JOB	ABANDONMENT
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot and plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~ that cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING MULTIPLE CASING TEST / COMPLETION CEMENT JOB	ABANDONMENT
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of		1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.	Day 1	1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	1. Load hole with 10 PPG salt gel mud. Till and spot and plug across 8-5/8" surface casing shoe from 1550' to 200'. WOC and tag plug. 2. Cut off wellhead and spot across 8-5/8" surface. Sex in casing, a in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT
starting any proposed work). SEE RULE 1103.	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDO
saming any proposed works. See NOEE 1103.	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDO
02-04-84 Set CIBP at 4774' and capped with 30' cement I caded hole with inhibited water	Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	1. Load hole with 10 PPG salt gel mud. TIH and spot some plug across 8-5/8" surface casing shoe from 1550' to 1330'. WOC and tag plug. 2. Cut off wellhead and spot ~1550 cement at surface: 8 in casing, the sin annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDO
02-04-04 Set Cibr at 4//4 and capped with 30 cement. Loaded note with inhibited water.	starting any proposed work). SEE RULE 1103.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Pe pertinent dates, including estimated date of
	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	2. Cut off wellhead and spot ~1550 cement at surface: 82x in casing, 25x in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
- Place 100' Plue 2436 to 3036'	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	145 1550' to 1300'. WOC and tag plug. 2. Cut off wellhead and spot ~1500 cement at surface: 800 in casing, 200 in annulus.	145 1550' to 1300'. WOC and tag plug. 2. Cut off wellhead and spot ~1500 cement at surface: 800 in casing, 200 in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1 Load hole with 10 PPG gatt gol muck TIH and anot attempt the access 251" auriface assign about from	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water.	2. Cut off wellhead and spot ~t accement at surface: 8 in casing, the in annulus.	2. Cut off wellhead and spot ~t accement at surface: 8 in casing, the in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1. Load hole with 10 PPG salt gel mud. TIH and spot App plug across 8-1/8" surface casing shoe from	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. \[\rangle \lambda \circ \rangle \lambda \circ \rangle \lambda \circ \rangle	2. Cut off wellhead and spot ~1 leax cement at surface: 8 leax in casing, 7 leax in annulus.	2. Cut off wellhead and spot ~1 leax cement at surface: 8 leax in casing, 7 leax in annulus.	PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
1 1 6 APPALA MARKA 1 10100 14 1	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TiH and spot 25 plug across 8-5/8" surface casing shoe from			PULL OR ALTER CASING	ABANDONMENT ABANDONMENT Per pertinent dates, including estimated date of the with inhibited water.
以S 1550' to 语句'. WOC and tag plug.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. A 100' P 100' 29 36 6 30 36 6 Load hole with 10 PPG salt gel mud. TiH and spot 250 000 100' 100' Load hole with 10 PPG salt gel mud. TiH and spot 250 000 100' 100' Load hole with 10 PPG salt gel mud. TiH and spot 250 000 100' 100' Load hole with 10 PPG salt gel mud. TiH and spot 250 000	3. Set dry hole marker. Clean location and pick up flowline.	3. Set dry hole marker. Clean location and pick up flowline.	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
以S 1550' to 语句: WOC and tag plug.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. A 100' P 100' 29 36 6 30 36 6 Load hole with 10 PPG salt gel mud. TiH and spot 250 x plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug.	or out any more marken clean leadach and plot up flowing.	or out any note thanken clean lecason and plot up nowing.	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~150x cement at surface: 850x in casing, 50x in annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot and plug across 8-5/8" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot a cement at surface: Sex in casing, a in annulus.			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot ~150x cement at surface: 850x in casing, 50x in annulus.	starting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded hole with inhibited water. 1. Load hole with 10 PPG salt gel mud. TIH and spot and plug across 8-5/8" surface casing shoe from 1550' to 130'. WOC and tag plug. 2. Cut off wellhead and spot a cement at surface: Sex in casing, a in annulus.			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ tiest cement at surface: 82x in casing, 25x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. TiH and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ 155x cement at surface: 85x in casing, 55x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. Till and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	Notify OCD 24 hrs. prior to any work done	Notify OCD 24 hrs. prior to any work done	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
1550' to 159'. WOC and tag plug. 2. Cut off wellhead and spot ~ tiest cement at surface: 82x in casing, 25x in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	1. Load hole with 10 PPG salt gel mud. TiH and spot to 1550' to 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: Sex in casing, to in annulus. 3. Set dry hole marker. Clean location and pick up flowline.	Notify OCD 24 hrs. prior to any work done	Notify OCD 24 hrs. prior to any work done	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (the state of the state
2. Cut off wellhead and spot ~t accement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done	1. Load hole with 10 PPG salt gel mud. TIH and spot with 20 graph plug across 8-5/8" surface casing shoe from 1550' to 100'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from the surface casing shoe
2. Cut off wellhead and spot ~t accement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done	1. Load hole with 10 PPG salt gel mud. TIH and spot with 20 graph plug across 8-5/8" surface casing shoe from 1550' to 100'. WOC and tag plug. 2. Cut off wellhead and spot to cement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done			PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (Tooss 8-5/8" surface casing shoe from the surface casing shoe
2. Cut off wellhead and spot ~t is cement at surface: 8 in casing, in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief.	1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug across 8-5/8" surface casing shoe from 1. Load hole with 10 PPG salt gel mud. TIH and spot reserve plug acros	I hereby certify that the information above is true and complete to the best of my knowledge and belief.	I hereby certify that the information above is true and complete to the best of my knowledge and belief.	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the with inhibited water. To 30 34 (Toss 8-5/8" surface casing shoe from the pertinent dates, including estimated date of the pertinent dates.
2. Cut off wellhead and spot ~t accement at surface: sex in casing, in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE DATE 9-20-01	1. Load hole with 10 PPG salt gel mud. Tith and spot representation and plug across 8-5/8" surface casing shoe from plus 1550' to 1303'. WOC and tag plug. 2. Cut off wellhead and spot reservement at surface: Sex in casing, the in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Title Operations Engineer DATE 9-20-01	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (
2. Cut off wellhead and spot ~1550 cerment at surface: 852 in casing, 253 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	1. Load hole with 10 PPG salt gel mud. TIH and spot with plug across 8-3/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot term cement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded had 100' Play 2936. 1. Load hole with 10 PPG salt gel mud. TIH and spot 2500 plug acr 1550' to 250'. WOC and tag plug. 2. Cut off wellhead and spot 1550 cement at surface: 8500 in casin 3. Set dry hole marker. Clean location and pick up flowline. Notify I hereby certify that the information above is true and complete to the best of my knowledge. TITLE Operations Type or print name Robert McNaughton Telepho	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (
2. Cut off wellhead and spot ~1550 cerment at surface: 852 in casing, 253 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	1. Load hole with 10 PPG salt gel mud. TIH and spot with plug across 8-3/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot term cement at surface: 8 in casing, 2 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded had 100' Play 2936. 1. Load hole with 10 PPG salt gel mud. TIH and spot 2500 plug acr 1550' to 250'. WOC and tag plug. 2. Cut off wellhead and spot 1550 cement at surface: 8500 in casin 3. Set dry hole marker. Clean location and pick up flowline. Notify I hereby certify that the information above is true and complete to the best of my knowledge. TITLE Operations Type or print name Robert McNaughton Telepho	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 30 34 (
2. Cut off wellhead and spot ~ 1550' to 150'. WoC and tag plug. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915 - 682 - 4429 (This space for State use)	1. Load hole with 10 PPG salt gel mud. Till and spot representation and spot r	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use)	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use)	PULL OR ALTER CASING	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (to 3
2. Cut off wellhead and spot ~ 1550' to 1550'. WOC and tag plug. 2. Cut off wellhead and spot ~ 1550 cernent at surface: 852 in casing, 1550 in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429	1. Load hole with 10 PPG salt gel much. Till and spot a plug across 8-5/8" surface casing shoe from 1550' to 150'. WOC and tag plug. 2. Cut off wellhead and spot test cement at surface: 8 in casing, in annulus. 3. Set dry hole marker. Clean location and pick up flowline. Notify OCD 24 hrs. prior to any work done Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 APPPROVED BY TITLE DATE 10-19-01	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use) APPPROVED BY TITLE DATE 10-19-01	I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Engineer DATE 9-20-01 Type or print name Robert McNaughton Telephone No. 915-682-4429 (This space for State use) APPPROVED BY TITLE DATE 10-19-01	PULL OR ALTER CASING MULTIPLE CASING TEST OF CEMENT JOB OTHER: Describe proposed or completed operations. (Clearly state all pertinent details, and girstarting any proposed work). SEE RULE 1103. 02-04-84 Set CIBP at 4774' and capped with 30' cement. Loaded had a load hole with 10 PPG salt gel mud. Till and spot plug acres plug acres plug acres plug. 1. Load hole with 10 PPG salt gel mud. Till and spot plug acres plug acres plug acres plug acres plug. 2. Cut off wellhead and spot temperature at surface: text in casing 3. Set dry hole marker. Clean location and pick up flowline. Notify Thereby certify that the information above is true and complete to the best of my knowledge signature. Title Operations Type or print name Robert McNaughton Telepho (This space for State use) APPPROVED BY TITLE	ABANDONMENT The pertinent dates, including estimated date of the with inhibited water. To 3034 (to 3

NADEL AND GUSSMAN PERMIAM

New Mexico "DI" State No. 3 1980' FSL, 660' FWL, Unit L, Sec 19, 23S, 26E, Eddy County, NM API# 30-015-24591

Elev: 3476' GL


Recommended P&A

DV Tool @ 668' 650 sx, DNC, cement fell back 1" cement from 680' 1000 sx, circulated

8-5/8", 24#, K-55 @ 1434' 1050 sx, TOC @ DV tool. 12-1/4"

DV Tool at 2986' 650 sx, TOC @ 690' by temp

5-1/2", 15.5#, K-55 @ 5191' 590 sx, TOC @ DV tool 7-7/8" Hole



Spot 15 sx (50') at surface:

8 sx in casing, 7 sx in annulus

Spot 25 sx across intermediate shoe

1300' to 1550'



CIBP @ 4774' w/ 30' cement

Delaware Perfs: 4844' - 4852' Delaware Perfs: 4876' - 4886'

@ 1 SPF, 20 holes, 2000 15%, 32/34 foam frac

Delaware Perfs: 4938' - 4952' @ 4 SPF, 56 holes, 1500 15%

Operator Well Unit <u>L</u> API #	Nadel Gussma Permianh C New Marco DI' State 3 Section 19 Township 23 Range 26 30 - 015 - 24591	TOPS Delaware 1195' Bone 4877'
	60' Surface Plug. Inside: Outside better	t gel mud consisting of 10# brine h 25# of gel per barrel must be placed ween each plug stall Dry Hole Marker lify OCD 24 hrs. prior to any work done
1434, 848,	< shoe Plug # 10 1550' Tag	
2986'-	DV Took 4 100' Plug 2936' to 3036'	
4774' 4844 4952 5191	CIBP W/30'cmt.	

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Nadel & Gussman Perman, CIC

Well Name & Number: New Mexico DI State #3

API #: 30-015-24591

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 4/24/2013

APPROVED BY: Alek

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).