Form 3160-5 (April 2004)

OCD-ARTESIA **UNITED STATES** DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

SUNDRY NOTICES AND REPORTS ON WELLS					NMNM84701	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side					7. If Unit or C	A/Agreement, Name and/or No.
1. Type of Well			REC	CEIVED		
X Oil Well Gas Well Other FEB 0.7 7006					8. Well Name and No. Dagger Draw 31 Fed	
2. Name of Operator					#1	
Nearburg Producing Company 3a. Address 3b. Phone No. (include area code)					9. API Well N	
3a. Address 3300 N A St., Bldg 2, Ste 120, Midla	432/686-8235 x 203			30 - 015 - 26425 10. Field and Pool, or Exploratory Area		
3300 N A St., Bldg 2, Ste 120, Midland, TX 79705 432/686-8235 x 203 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				<u> </u>	Dagger Draw; Upper Penn,	
660 FNL and 660 FWL, Sec 31-19S-25E					North	
						r Parish, State
				Eddy	NM NM	
12. CHECK APPROPRIATE	BOX(ES) TO INE	DICATE NAT	URE OF N	IOTICE, REPO	ORT, OR OT	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize	Deepe	n	Production	(Start/Resume)	Water Shut-Off
	Alter Casing	Fractu	re Treat	Reclamatio	n	Well Integrity
X Subsequent Report	Casing Repair	New (Construction	Recomplet	e	Other
Final Abandonment Notice	Change Plans	X Plug a	nd Abandon	Temporaril	y Abandon	
I mai romaonnem ronee	Convert to Injection Plug Back Water D			Water Disp	osal	
Please see attached break down of	work performed		e subject	Approved as	to plugging or bond is rel or bond is con	of the wee seen tained unto
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Sarah Jordan THIS	SPACE FOR FEE	Title Date DERAL OR S	1/31/06	tion Analys		
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations the	those rights in the sub	arrant or of	ce Ce	HONEER		FEB 0 6 2006

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Dagger Draw 31 Federal #1

660' FNL and 660' FWL, Section 31, T19S, R25E Dagger Draw Eddy County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

01/13/06

Well Repair Service: P&A well.

Road rig & crew to location from Pennzoil 1 Fed #3. MIRU Mesa Well Service pulling unit. ND WH & NU BOP. RU JSI electric line truck to dump bail 35' cmt on top of CIBP @ 7613'. Made 2 dump bail runs. RDMO JSI electric line truck. Had Two-State deliver 245 jts- 2 3/8" N-80 4.7# EUE8rd tbg (workstring) & pipe racks to location. Tallied tbg on racks. PU & RIH w/ 40 jts- 2 3/8" N-80 tbg. Put TIW valve in tbg. Close BOP rams. SDFW. Will have frac tanks brought to location in the AM & fresh wtr put in one of them. Will finish PU tbg Monday AM & tag TOC above CIBP before POOH & pumping first cmt plug.

01/16/06

Well Repair Service: P&A well.

Remove TIW valve from tbg. Clean threads on collars & pins of tbg on pipe racks (old cement). PU & RIH w/ 196 jts- 2 3/8" N-80 4.7# EUE 8rdtbg (workstring). Could not get cement trucks until tomorrow. Had TRM haul 260 Bbls fresh wtr to frac tank on location. Put TIW valve in tbg. Close BOP rams. SDFN. Will RU BJ Service trucks to pump cement plugs in the AM. Had TRM put 270 Bbls 10# brine w/ salt gel in another frac tank to circulate well. Tagged TOC above CIBP @ 7581' by tbg tally.

01/17/06

Well Repair Service: P&A well.

MIRU BJ Service cement trucks. RU to tbg & circulate well w/ 265 Bbls 10# brine wtr w/ 25 sx Salt gel per/100 Bbls brine wtr. POOH w/ 77 jts-2 3/8" N-80 4.7# EUE 8rd tbg to 5109'. Mix 8 Bbls 14.8# cement in tub (35 sx) & pump dn tbg displacing w/ 18 Bbls 10# brine wtr/salt gel. Pumped a balanced plug. POOH & LD 18 jts- 2 3/8" N-80 tbg to 4526'. Mix 8 Bbls 15.0# cement in tub (35 sx). Tried to pump dn tbg, but couldn't due to tbg being plugged. Pumped cement out of tub into frac tank. POOH standing back 122 jts- 2 3/8" N-80 tbg. The next 19 jts were full of cement. LD cement jts on pipe rack. With 550' of tbg w/ cement in them there should be 152' of cement plug @ 4957'- 5109' in 7" csg. With displacing w/ 18 Bbls10# brine we should have only left 258' cement in tbg that should have fallen out btm of tbg while POOH. RIH w/ 141 jts- 2 3/8" tbg to 4526'. Put TIW valve in tbg. Close BOP rams. SDFN. Will pump the rest of the plugs in the AM.

01/18/06

Well Repair Service: P&A well.

RU BJ Service pump truck to tbg to break circulation w/ 22 Bbls 10# brine wtr w/ salt gel. EOT @ 4526'. Mixed 8 Bbls 14.8# cement (35 sx) in tbg and pumped dn tbg displacing w/ 16.6 Bbls 10# brine wtr w/ salt gel. Pumped a balanced plug. POOH standing back 10 jts- 2 3/8" N-80 tbg then LD 14 jts- 2 3/8" N-80 tbg on pipe racks for a total of 24 jts POOH to EOT @ 3760'. Mixed another 8 Bbls 14.8# cement (35 sx) in tub and pumped dn tbg displacing w/ 13.6 Bbls 10# brine wtr w/ salt gel. Pumped a balanced plug. POOH standing back 10 jts- 2 3/8" N-80 tbg then LD 30 jts- 2 3/8"N-80 tbg on pipe racks. RIH w/ 20 jts- 2 3/8" tbg from derrick then POOH & LD 20 jts- 2 3/8" tbg on racks. Continue POOH & LD w/ 35 jts- 2 3/8" tbg on pipe racks to EOT @ 1356'. Mixed 8 Bbls 14.8# cement (35 sx) in tub & added 2% calcium chloride so cement would set quicker. Pumped dn tbg displacing w/ 4.5 Bbls 10# brine wtr w/ salt gel. Pumped a balanced plug. POOH w/ 20 jts- 2 3/8" tbg. Let well sit for 2 1/2 hrs to let cement dry to tag 1356' plug pumped. RIH w/ 14 jts- 2 3/8" tbg & tag TOC @ 1162'. Good plug. POOH & LD 36 jts- 2 3/8" N-80 tbg on racks then RIH w/ 4jts-2 3/8" N-80 tbg & POOH & LD 4 jts- 2 3/8" on racks. RIH w/ last 2 jts- 2 3/8" tbg to 65' FS. Break circulation w/ 5 Bbls 10# brine wtr w/ salt gel. Mixed 8 Bbls 14.8# cement (35 sx) in tub and pumped dn tbg displacing cement to open top frac tank. Put sugar in tank to keep from setting up & had TRM haul to disposal. RDMO BJ Service pump truck. ND BOP & NU flanged valve. BLM approved the plugging job (Clark Bennett). Will have wellhead cutoff & dry hole marker put on in the AM. Will RDMO Mesa pulling unit in the AM.

TIGHT HOLE-PLEASE DO NOT RELEASE ANY INFORMATION ON THIS WELL

Dagger Draw 31 Federal #1

660' FNL and 660' FWL, Section 31, T19S, R25E Dagger Draw Eddy County, New Mexico ** ALL COSTS ARE FIELD ESTIMATES **

01/19/06 Well Repair Service: P&A well.

RDMO Mesa Well Service pulling unit. Had backhoe dig around wellhead so welder could cutoff B-section & weld plate & dry hole marker on top of well. Had backhoe dig up dead men (anchors). Will have 2 3/8" tbg hauled to pipe yard in the AM. Will have 500 Bbl steel tank that's on location hauled to yard. Will finish remediating location after BLM looks to see what needs to be done. Well P&A. FINAL REPORT.