Carlsbad Field Office

Form 3160-5 (June 2015) D.	UNITED STATES EPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT OCD Artesia			OMB NO. 1004-0137 Expires: January 31, 2018	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an			5. Lease Serial NMNM115	No. 3411	
abandoned we	ell. Use form 3160-3 (API	drill or to re-enter an D) for such proposals.	6. If Indian, All	ottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				Agreement, Name and/or No.	
Type of Well ☐ Gas Well ☐ Other				nd No. e Attached	
		AMANDA AVERY		9. API Well No. MultipleSee Attached	
3a. Address 600 W ILLINOIS AVENUE MIDLAND, TX 79701		3b. Phone No. (include area code) Ph: 575.748.6940	BONE SPR	10. Field and Pool or Exploratory Area BONE SPRINGS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Descriptio				WILLOW LAKE-BONE SPRING, SE 11. County or Parish, State	
MultipleSee Attached			EDDY COL	,	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
■ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resum	e) Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	□ Well Integrity	
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	Onshore Order Varia	
	Convert to Injection	☐ Plug Back	☐ Water Disposal	ce	
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the woi following completion of the involved testing has been completed. Final Attach that the site is ready for fit COG Operating LLC requests Fed Com #3H tank battery. Toperating equipment necessal facility. COG Operating LLC LC and the proposed in the prop	he will be performed or provide to operations. If the operation restandonment Notices must be file in all inspection. permission to install a Vaphis request is due to the fary to capture the gas excertification.	the subsurface locations and measure he Bond No. on file with BLM/BIA. lits in a multiple completion or record only after all requirements, including the compustor Unit (VCU) at a cot that the cost of installing areas the value of the gas over ling conditions apply.	red and true vertical depths of all particle in Required subsequent reports mu mpletion in a new interval, a Forming reclamation, have been completed the Really Scary and the life of the	pertinent markers and zones. ust be filed within 30 days	
facility. COG Operating LLC understands that the following conditions apply: 1. COG Operating LLC may be required to provide economic justification and provide volume verification to the Authorized Officer upon request. 2. COG Operating LLC will comply with NTL-4A requirements. 3. If volume being combusted is less than 50 MCF of gas per day, it is considered unavoidably lost,				JUN 0 6 2018	
therefore, no royalty obligation a. Unavoidably Lost productio combusted) from low-pressure	shall be accrued and will n shall mean (1) those gas	not be required to be reported	1	RICT II-ARTESIA O.C.D.	
Essentially all measured co	mbusted volumes over 50	MCF will require payment of	royalties and G C Accepted for r	6-6-18 ecord NMOCD	
14. I hereby certify that the foregoing is Com Name (Printed/Typed) AMANDA	Electronic Submission #3t For COG OP mitted to AFMSS for proces	89794 verified by the BLM Well ERATING LLC, sent to the Car ssing by PRISCILLA PEREZ on Title AUTHOR	richad		
		AUTHOR	MELD REPRESENTATIVE		
Signature (Electronic S		Date 09/26/20			
	THIS SPACE FOI	R FEDERAL OR STATE O	FFICE USE		
Approved By J. W. W.	ithref	Title TEPE	ET	6/4/18 Date 4/18	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduct	itable title to those rights in the s	ot warrant or ubject lease Office	: >		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #389794 that would not fit on the form

Wells/Facilities, continued


Agreement	Lease	Well/Fac Name, Number API Number Location
NMNM126700	NMNM115411	REALLY SCARY FEDERAL COM 300-015-36372-00-S1 Sec 33 T24S R28E SESW 430FSL 2310FWL 32.167730 N Lat, 104.093480 W Lon
NMNM115411	NMNM115411	REALLY SCARY FEDERAL 5H 30-015-40241-00-S1 Sec 33 T24S R28E SESE 380FSL 990FEL
NMNM115411	NMNM115411	REALLY SCARY FEDERAL 6H 30-015-42863-00-S1 Sec 33 T24S R28E NWNW 360FNL 380FWL
NMNM126700	NMNM115411	REALLY SCARY FEDERAL COM 230-015-41411-00-S1 Sec 33 T24S R28E SESW 190FSL 1683FWL
NMNM115411	NMNM115411	REALLY SCARY FEDERAL 4H 30-015-41670-00-S1 Sec 33 T24S R28E SWSE 250FSL 2293FEL
	NMNM115411	32.167068 N Lat, 104.090734 W Lon
NMNM126700	I A PC I LIVERIIVIE	FAC RLYSC3 REALLY, SCARY Sec 33 T24S R28E Mer NMP SESW
141411411120700		FAC RLYSC3 REALLY SCARY Sec 33 T24S R28E Mer NMP SESW

32. Additional remarks, continued

volumes need to be reported on OGOR B reports as disposition code 08.
5. Per 43 CFR 3162.7-5(d)/Onshore Order No.3.III.I.1, site facility diagram must be submitted within 60 days of equipment installation.


6. This approval does not authorize any additional surface disturbance.
7. Subject to like approval from NMOCD.


Attached are the following:
Site Security Diagram of the current tank battery, as well as the location of the VCU and the manifold line connecting the tanks to the VCU.
Contact name and number to retrieve information on volumes being combusted.
Specification sheet(s) for the VCU.





General Arrangement Drawing

NOTE: This drawing is intended for your review and approval of the general arrangement for an ABUTEC 100 Some dimensions are subject to change during the linal engineering phase of this project. "As Bufft' drawings will be provided at engineering complation.











ABUTEC 100 (SCUF) C ABUTEC-100GAD SCALLE 124 WILGHIS MALES THESE FOLT



Sequence of Operation

ABUTEC 100 Combustion Flare

- 1. The system is put in "Auto" mode by switching from "OFF" to "ON" on the control panel.
- Once in "Auto" there is a 15-45 second delay while the PLC boots up, the pilot solenoid valve SDV-102 will open, at the same time the ignition transformer TX-101 will be energized, and the ignition electrode IE-101 will start sparking for a period of 10 seconds.
- 3. The pilot gas will be ignited, and proof of pilot lit will be detected by the flame rod (FR-101). Once the PLC has received confirmation that the pilot is lit the ignition transformer is disabled and energy is no longer supplied to the ignition electrode. The pilot will remain lit continuously while the power switch is in the "ON" position. If pilot flame is lost or undetected the PLC will make an infinite number of attempts to relight.
- 4. Once a "Start-up" pressure of 7" H2O is detected by the pressure transmitter (PT-101) on the main gas line for a period of 10 seconds, the process controller will initiate the start sequence.
 - o The solenoid valve (SDV-101) will open and release gas to the main burner.
 - o The main burner is lit.
 - The stack temperature is monitored by the thermocouple (TE-101).

Shutdown Parameters:

- High Stock Temperature –Temp greater than 2200°F > 10 seconds
- Low Pressure Pressure less than 2" H2O > 5 seconds
- Loss of pilot flame

NOTE: Any shutdown will cause valve SDV-101 to close.

 The system will wait for 10 seconds upon any shutdown for purging process and reinitiate the start sequence.

ABUTEC MTF Inspection and Maintenance Procedures

Thermocouple

- The thermocouple head should be opened for a visual inspection of all wire connections. A simple pull test can be performed to ensure secure connections of the wires on the thermocouple terminal block.
- The thermocouple should be removed from the enclosed flare stack for a visual inspection of its component probe. The probe should be checked for signs of excessive heating and material fatigue. Visual indicators include:
 - cracks or gaps in the continuous probe material
 - > exposure of thermocouple's fully enclosed bi-metal wire
 - droop of the probe tip at an angle greater than 60° from horizontal
- Discoloration of the thermocouple probe is a normal occurrence and does not necessarily indicate excessive heating or material fatigue.

If excessive wear is detected, the thermocouple must be replaced.

 Once a thermocouple has been replaced, its wired connections should be checked to ensure of proper signal transmissions and temperature detection.

Ignition Electrode/ Flame Detector / Boot / Cable

Caution: Electric shocks can be fatal! Before working on live components, confirm that power to the flare has been disconnected and all stored energy has dissipated.

- The ignition electrode, flame detector, and boot are one complete assembly. Each component can be removed, inspected and if found to be faulty, replaced.
- Once removed from ignition assembly, the electrode should be inspected for cracks in the ceramic insulation which would be a potential location for spark to escape.
- The metallic portion (electrode tip and rod of the flame detector) should be inspected for excessive corrosion or overheating.

Visual indication of compromise includes:

- Ignition Electrode
 - > scaly build up on electrode tip
 - > excessive loss of material at electrode tip
 - fragile state of the metallic tip, this can also be a sign of excessive corrosion
- Flame Detector
 - > scaly build up on flame rod
 - > excessive loss of material
 - > fragile state of the metallic rod, this can also be a sign of excessive corrosion
- The electrode tip and flame rod can be scrubbed clean with an abrasive material. This process
 can expose virgin metal and possibly restore the component's original performance.
 If cracks in the ceramic portion or excessive corrosion on the metallic portion are detected, the
 compromised component must be replaced.