Form 3160-5 (June 2016)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM92957

SUNDRY NOTICES AND REPORTS ON WELLEN II O	O	2040
Do not use this form for proposals to drill or to re-enter an &	Ð	2013
abandoned well. Use form 3160-3 (APD) for such proposals		

6. If Indian, Allottee or Tribe Name

						<u>.</u>
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No.			
Type of Well     Gas Well □ Other			Well Name and No.     WILMAR FEDERAL 4			
Name of Operator Contact: HOWIE LUCAS     CHEVRON USA INCORPORATED E-Mail: howie.lucas@chevron.com			9. API Well No. 30-015-25618-0	0-S1		
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706  3b. Phone No. (include area code) Ph: 832-588-4044			10. Field and Pool or Exploratory Area N SHUGART			
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description	)			11. County or Parish, State	
Sec 4 T18S R31E NENW 990FNL 2310FWL			EDDY COUNTY	′, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	ΓE NATURE OF	NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION			TYPE OF	ACTION	-	
STACE - CTACA	□ Acidize	☐ Deep	oen .	☐ Product	ion (Start/Resume)	■ Water Shut-Off
☑ Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete	Other
☐ Final Abandonment Notice	□ Change Plans	▶ Plug	and Abandon	☐ Tempor	arily Abandon	
	☐ Convert to Injection	🗖 Plug	Back	☐ Water I		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  1. Contact BLM 24 hours prior to MIRU. 2. MIRU pulling unit. 3. Verify pressures on all casing strings. If sustained casing pressure is noted on any strings, then Chevron plans to use either Zonite, cut and pull casing, or another menas to eliminate pressure as agreed upon with the BLM. 4. Kill well and N/U BOP. 5. Pull tubing, standing back (will test tubing running in the hole). Tubing was previously cut at CONDITIONS OF APPROVAL 7,756' after several attempts to free. 6. Set CIBP at 7,756', pressure test casing to 1,000 psi for 10 minutes. 7. Spot 85 sx CL "C" cmt f/ 7,756' t/ 6,988' (Perfs). Contact BLM to waive WOC and tag if casing passed a pressure test. 8. Spot 25 sx CL "C" cmt f/ 5,430' t/ 5,177' (Bone Springs).  Below grown at least tubing running or provide the Bond and the pressure test. 8. Spot 25 sx CL "C" cmt f/ 5,430' t/ 5,177' (Bone Springs).						
14. I hereby certify that the foregoing is	Electronic Submission #	472155 verifie	d by the BLM Wel	I Information	n System	
Con	nmitted to AFMSS for prod		RATED, sent to t SCILLA PEREZ or			
Name (Printed/Typed) HOWIE LUCAS Title ENGINEER		ER				
Signature (Electronic S	Submission) THIS SPACE FO	OR FEDERA	Date 07/03/20		SE	
	1 1		<u> </u>			70.0
Approved By Approved By	1 Cl-Comp_		Title SA	ET_		7-9-/9 Date
Conditions of approval, it any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition	uitable title to those rights in that operations thereon.	e subject lease	Office CFU	2	<u> </u>	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations a	a crime for any pe s to any matter w	erson knowingly and ithin its jurisdiction.	willfully to m	ake to any department or	agency of the United

## ' Additional data for EC transaction #472155 that would not fit on the form

#### 32. Additional remarks, continued

9. Spot 60 sx CL "C" cmt f/ 4,090' t/ 3,483' (San Andres, Grayburg).

10. Spot 25 sx CL "C" cmt f/ 3,106' t/ 2,854' (Queen).

11. Perforate Casing at 2,006' and squeeze 90 sx CL "C" cmt f/ 1,638' t/2,006', WOC & tag (Yates, B-8aft).

12. Perforate Casing at 810' and squeeze 210 sx CL "C" cmt f/ Surface t/ 810'.

13. Cut wellhead off and weld dry hole marker as per BLM requirements.

Well: Wilmar 4 Field: Shugart North Reservoir: Bone Spring 11' RKB

### **Current** Wellbore Diagram

Surface Csg: 13.375" J 55 54.5# 641' Set: 17.5 Hole Size: Circ: Yes TOC: Surface Circ \_ TOC By:

Int Csg: 8.625" J55 24# 2149 Set: Hole Size: 11" 4 Circ: yes TOC: Surface TOC By: circ

Prod Csg: 8600' • Set: Hole Size: 7.875" Circ: No TOC: TOC By: 2134' 1850 sxs

Temp Survey

Formation Name	TD, ft
	Тор
Top of Salt	760'
Base of Salt	1770'
Yates	1956'
Queen	3056'
Grayburg	3634
San Andres	4040'
Bone Springs	5380'
1st Bone Springs Sand	7140'
2nd Bone Springs Sand	7674'

PBTD:8589 TD: 8600'

Tubing stuck in hole after RWW job. Rod string pulled

End of tubing 8566' RWW cut tubing at 7756'

This is where free point showed tubing unstuck They laid down a couple of joints t/ ensure free and R/D (see well history tab)

Bone Spring 8092-8564 B3 80

ASS 8470-8564 1/4/00

Well: Wilmar 4 Field: Shugart North Reservoir: Bone Spring

11' RKB

#### **Proposed** Wellbore Diagram

Surface Csg:

Set: Hole Size:

13.375" J55 641' 17.5"

Circ:

Yes Surface

TOC: TOC By:

Circ

Int Csg: Set:

8.625" J55 2149'

Hole Size: Circ:

11"

TOC: TOC By: yes Surface

circ

Formation Name	TD, ft
	Top
Top of Salt	760'
Base of Salt	1770'
Yates	1956'
Queen	3056'
Grayburg	3634'
San Andres	4040'
Bone Springs	5380'
1st Bone Springs Sand	7140'
2nd Bone Springs Sand	7674'

PBTD:8589 TD: 8600'

Prod Csg:

Set: Hole Size:

Circ:

TOC: TOC By:

5.5" 17# 8600' 7.875

Νo 2134' 1850 sxs Temp Survey

6 Perforate at 810' and sqz 210 sx CL "C" cmt f/ surface t/ 810' (T Salt, Shoe, Surf)

5 Perforate at 2006' and sqz 90 sx CL "C" cmt f/ 1638' t/ 2006', WOC & tag (Yates, B Salt)

4 Spot 25 sx CL "C" f/ 3106' t/ 2854' (Queen)

3 Spot 60 sx CL "C" cmt f/ 4090' t/ 3483' (San Andres

2 Spot 25 sx CL "C" cmt f/ 5430' t/ 5177' (Bone Springs)

1 Pull tubing, run CIBP and set above TOF at 7756', spot 85 sx CL "H" cmt f/ 7756' t/ 6988' (Perfs)

Tubing stuck in hole after RWW job. Rod string pulled

End of tubing 8566'
RWW cut tubing at 7756'
This is where free point showed tubing unstuck
They laid down a couple of joints t/ ensure free and R/D (see well history tab)

Bone Spring 8092-8564

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1<sup>st</sup> through June 15<sup>th</sup> annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted