Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103 May 27, 2004	
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resourc	WELL API NO.	1 1 1 2 7, 2004	
District II	OIL CONSERVATION DIV ISIO	I	30-015-30703	
1301 W. Grand Ave., Artesia, NM 88210	1220 South St. Francis Dr.	5. Indicate Type of I		
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe NM 87505	STATE State Oil & Gas L	FEE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr. Santa Fe, NM 87505	0. State Off & Gas L	E-7437	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	1	NM 70064 D		
PROPOSALS.)			Indian Hills Unit NM-70964-B 8. Well Number 16	
1. Type of Well: Oil Well G	as Well 🗵 Other			
2. Name of Operator Marathon Oil Company ATTN: Charles E. Kendrix		9. OGRID Number 014	4021	
3. Address of Operator			10. Pool name or Wildcat	
P.O. Box 34	87 Houston, Texas 77253-3487	Indian Basin (M	lorrow)	
4. Well Location				
Unit Letter E :	2,200 feet from theNorth line an			
Section 17		4-E NMPM	County Eddy	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,914' GR				
Pit or Below-grade Tank Application 🛛 or C	losure 🗌			
Pit type_STEEL Depth to Ground	water Distance from nearest fresh water wel	Distance from neares	t surface water _N/A	
Pit Liner Thickness: STEEL mil	Below-Grade Tank: Volume180h	bls; Construction Material	STEEL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WORK ☐ ALTERING CASING ☐				
	-	-	AND A	
	MULTIPLE COMPL ☐ CASING/C ☐ OTHER:	EMENT JOB	Г-1	
OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1				
See attached proposed plugging pro-	cedure			
see assessed by obosen bragging brook				
11 12 12 12 13 13				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or classed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .				
SIGNATURE THE	TITLE James F. New	man, P.E. (Triple N Services	s) DATE <u>02/06/07</u>	
Type or print name	E-mail address: jim@	triplenservices.com Telepl	hone No. 432-687-1994	
For State Use Only	1			
APPROVED BY:	whi TITLE Id.	D	ATE 2/13/07	
Conditions of Approval (if any):			1.	



Proposed Plugging Procedure Marathon Oil Company Indian Hills Unit #16 API #30-015-30703

Surface casing:

95/3" 36# J-55 @ 2,409', cmt circulated

Production csg: 41/2" 11.6# N-80 @ 9,869' cmt'd w/ 975 sx, TOC 6,500' calculated

Open perfs:

9,324 - 9,357' (Atoka)


Tubing/packer:

2%" 4.7# L-80 EUE with Arrowset 1x 19K packer w/ 1.875" 'F' profile nipple &

on/off tool @ 9,284', EOT @ 9,358'

- 1. Notify NMOCD prior to move-in & daily with plugs. Set 180 bbl steel work pit and flow well down as needed.
- 2. MIRU plugging equipment. NU BOP. Release packer and POOH standing back production tubing. Lay down packer.
- 3. RIH w/ HM tbg-set CIBP on production tubing, set CIBP @ 9,300'. Circulate hole w/ mud and pump 25 sx cmt on top of CIBP. Atoka plug
- 4. ND wellhead and stretch 4½" casing to determine freepoint.
- 5. RIH w/ wireline and cut 4½" casing @ freepoint based on stretch, estimated ~6,500'. POOH w/ wireline. RU casing tools and POOH w/ 4½" casing. RD casing tools. RIH w/ tubing to 50' inside casing stub and pump 40 sx C cmt w/ 2% CaCl2. If casing is not free, RIH w/ tubing and pump 25 sx C cmt w/ 2% CaCl₂ 50' below casing cut. WOC & TAG this plug. Casing stub & base of salt plug
- 6. POOH w/ tbg to 4,437'. Load hole w/ plugging mud and pump 40 sx C cmt 4,437 4,337'.
- 7. POOH w/ tbg to 3,200'. Load hole w/ plugging mud and pump 40 sx C cmt 3,200 3,100'.
- 8. POOH w/ tbg to 2,458'. Load hole w/ mud and pump 65 sx C cmt w/ 2% CaCl₂ 2,458 -2,358'. WOC & TAG this plug no deeper than 2,358'. POOH w/ tubing. surface casing shoe plug
- 9. POOH w/ tbg to 848'. Load hole w/ mud and pump 35 sx C cmt 848 748'. POOH w/ tubing. San Andres plug
- 10. ND BOP and wellhead. RIH w/ tubing to 60' and pump 20 sx C cmt 60' to surface. RDMO.
- 11. Close working pit. Cut off wellhead and install dryhole marker. Cut off anchors and level location.

Indian Hills Unit No. 16



Currently Shut-in