

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-26315
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-484
7. Lease Name or Unit Agreement Name BUDDY AWY STATE COM
8. Well Number 1
9. OGRID Number 25575
10. Pool name or Wildcat DARK CANYON II PENN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	RECEIVED NOV 28 2003 OCD-ARTESIA
2. Name of Operator Yates Petroleum Corporation	
3. Address of Operator 105 S. 4 <sup>th</sup> Street, Artesia, NM 88210	10. Pool name or Wildcat DARK CANYON II PENN
4. Well Location Unit Letter <u>G</u> : <u>1980</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>EAST</u> line Section <u>32</u> Township <u>23S</u> Range <u>25E</u> NMPM <u>EDDY</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3849' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

**CALL OCD WITH 24 HOUR NOTICE BEFORE COMMENCING OPERATIONS.**

- MIRU WSU; ND wellhead, NU BOP. RU all safety equipment. No casing recovery will be attempted. POH w/ tubing & packer – packer is @ 9611'.
- MIRU WL; set CIBP @ 9632' & cap w/ 35' cement. This will seal off the Strawn perforations.
- Tally tubing & TIH open ended to 7385'. Load hole w/ plugging mud & spot a 25 sk plug from 7960' to 8380' – across the Wolfcamp top. Pull 5 stands & reverse circulate to clean out tubing.
- Move tubing to TIH open ended to 5380'. Load hole w/ plugging mud, then spot 25 sk plug from 4960' – 5380'. Pull 5 stands and reverse circulate; POH. *100' Plug 4553' - 4653' - in & out of csq.*
- RU WL & perforate 6 squeeze holes @ 2920' – TOC is @ 2920' by CBL. Tie onto casing & establish an injection rate before setting a retainer. If unable to pump into perfs, re-perf @ 2900' & try to establish an injection rate. Set a retainer @ 2820'; TIH w/ tubing & load hole w/ plugging mud. Sting into retainer & establish circulation. Squeeze w/ 50 sx Class C cement & leave 5 sx on top of retainer. This will leave a plug across the intermediate casing shoe. If no retainer is used, displace cement to 100' above top perforation. WOC & tag; reset plug if necessary.
- RU WL & perforate 6 squeeze holes @ 473'. WL set a retainer @ 373'. TIH w/ tubing & load hole w/ plugging mud. Sting into the retainer & establish circulation. Squeeze w/ 50 sx of Class C cement & leave 5 sx on top of retainer. This will set a plug across surface casing shoe. If no retainer is used, displace cement to 100' above top perf. WOC & tag; reset if necessary.
- RU WL & perforate 6 squeeze holes @ 150'. Tie onto 5-1/2" casing & establish circ back up 4.5"x 8.625 annulus. Pump 70 sx Class C cement – this should circ cement from 150' to surface. Do not displace cement. WOC 24 hrs & tag – reset if necessary.
- Remove all surface equipment & weld dry hole marker per regulations.

Notify OCD 24 hrs. prior to any work done

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE: Donna Clack TITLE: Regulatory Compliance Technician DATE: 11-25-2003

Type or print name DONNA CLACK E-mail address: \_\_\_\_\_ Telephone No. 505-748-1471

(This space for State use)

APPROVED BY: [Signature] TITLE: Wildcat ID **APPROVED DEC 2 2003**

Conditions of approval, if any: \_\_\_\_\_