

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

JUN 18 2009

Form C-103
June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-60907
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Walter Exploration Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 6116 N. Central Exp. #313, Dallas, TX 75206		7. Lease Name or Unit Agreement Name J G O'Brien (11602)
4. Well Location Unit Letter <u>F</u> : <u>1980</u> feet from the <u>N</u> line and <u>1830</u> feet from the <u>W</u> line Section <u>31</u> Township <u>07 S</u> Range <u>29 E</u> NMPM County <u>Chavez</u>		8. Well Number <u>003</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 4009.4		9. OGRID Number <u>24581</u>
		10. Pool name or Wildcat SWD; Fusselman (96104)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☒
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Attempt to get into stub unsuccessful.
Notify OCD before starting, if approved.
See Attached.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief:

SIGNATURE Eddie W. Seay TITLE Agent DATE 6/17/09

Type or print name Eddie W. Seay E-mail address: seay04@leaco.net PHONE: 575-392-2236

For State Use Only

APPROVED BY: DENIED DATE AUG 18 2009

Conditions of Approval (if any): DE

ATTACHMENT

Notify OCD before starting, if approved.

- 1) Run in hole with tubing and pkr to top of stub at 2430' . Attempt to establish a pump in rate.
If well will take fluid, cement squeeze with 50 sx cement leaving 100' plug from top of stub to approximately 2300' . Wait on cement and (TAG).
- 2) If cement is not high enough, add additional cement.
- 3) Make sure hole is loaded with salt gel.
- 4) Spot Yates plug at 887' -787' .
- 5) Set shoe plug 50' in and 50' out of 13 3/8" @ 386' (TAG).
- 6) 60' cement plug from 60' to surface.
- 7) Install dry hole marker.
- 8) File Sundry Notice after location ready for inspection.