UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

	OMB NO. 1004-013
	Expires: July 31, 20
5. Lease So	
NIMI C	ገፍደ1ደ1

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010	K
--	---

MINITO	10100	

SUNDRY	NOTICES AND REPO	ALIS ON V	VELLS CO		MIVILCUSOTOT		
abandoned wel	s form for proposals to I. Use form 3160-3 (API	D) for such	proposals.	ia (6. If Indian, Allottee	or Tribe N	Vame
SUBMIT IN TRII	PLICATE - Other instruc	tions on re	everse side.		7. If Unit or CA/Agre	ement, Na	ame and/or No.
1. Type of Well					8. Well Name and No		
☑ Oil Well ☐ Gas Well ☐ Oth					BEECH FEDERA	\L 2	
Name of Operator COG OPERATING LLC	Contact: E-Mail: kcarrillo@d	KANICIA C conchoresou			9. API Well No. 30-015-31790		`
3a. Address 550 WEST TEXAS AVE STE MIDLAND, TX 79701	1300	3b. Phone Ph: 432-	No. (include area code 085-4332 RECEN	VED 1	10. Field and Pool, o LOGAN DRAW		
4. Location of Well (Footage, Sec., T Sec 25 T17S R27E 1650FSL	•	i)	MAR 03	l l	11. County or Parish EDDY COUNT		
			NMOCD AF	RTESIA			
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICAT	CONTRACTOR OF THE PARTY OF THE		EPORT, OR OTHE	R DATA	A
TYPE OF SUBMISSION			ТҮРЕ О	F ACTION			
- Notice of Intent	☐ Acidize	ΩD	eepen	☐ Produc	tion (Start/Resume)	_D W	ater Shut-Off
Notice of Intent	Alter Casing		racture Treat	Reclan	nation	o W	ell Integrity
☐ Subsequent Report	Casing Repair		ew Construction	Recom	plete	□ Ot	ther
Final Abandonment Notice	☐ Change Plans		lug and Abandon	☐ Tempo	rarily Abandon		
	Convert to Injection	□ P!	lug Back	□ Water	Disposal		
following completion of the involved testing has been completed. Final At determined that the site is ready for fi COG Operating Recompletion	pandonment Notices shall be final inspection.)	led only after a	iple completion or recall requirements, inclu	completion in a diding reclamation of the state of the st	new interval, a Form 31 on, have been completed	60-4 shall l, and the c	I be filed once operator has
•							
Additional Well info listed belo Objective: Set a CIBP over the stages. Install 2 7/8? tbg and 1. MIRU POH w rods & tbg. (2 1.25? insert pump) Scan tbg. 2. RIH w/5?? CIBP and set @	e Wolfcamp interval. Cor FG rods. Install pumping 224 jt 2 3/8? L-80 tbg SNo while POH and send to C 16900? with 20 sks of Cla	g unit? @7021?, T/ concho yard ass C cmt or	AC@6828?, 95 ? in top. Test csq to :	7/8?, 182-? 3500 psi for	? rods, MAR	9 <u>RO\</u>	<u>VED</u> 2010
minutes w kill truck. If csg test work string.	•	•			m	250	411405145113
3. RU wireting and perforated	HILL SILVORY stage a	as listed bel	ow. (1 spf, .41? E	H)	CARLSB	AD FIELD	ANAGEME NT O OFFICE
CONDITION	IS OF APPROV	'AL					
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #	#81410 verif	ied by the BLM We LLC, sent to the C	II Information	ı System		
	Committed to AFMSS f		ng by KURT SIMMO	ONS on 02/16	/2010 ()		
Namc (Printed/Typed) KANICIA	CARRILLO		Title PREP	ARER			
Signature (Electronic S	Submission)		Date 02/15/2	2010			
	THIS SPACE F	OR FEDE	RAL OR STATE	OFFICE U	JSE		
Approved By /s/ Myles	Kristof		3 4104 1/ Title Per		Engineer		Date
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conduction of th	litable title to those rights in the		or	- vivuiii	man de la constant de		

Additional data for EC transaction #81410 that would not fit on the form

32. Additional remarks, continued

```
Perf # Depth SPF
1 4390 1/SPF
2 4382 1/SPF
3 4374 1/SPF
4 4366 1/SPF
5 4358 1/SPF
6 4350 1/SPF
7 4342 1/SPF
8 4334 1/SPF
9 4326 1/SPF
10 4318 1/SPF
11 4310 1/SPF
12 4302 1/SPF
13 4294 1/SPF
14 4286 1/SPF
15 4278 1/SPF
16 4270 1/SPF
17 4262 1/SPF
18 4254 1/SPF
19 4246 1/SPF
20 4238 1/SPF
21 4230 1/SPF
22 4222 1/SPF
23 4214 1/SPF
24 4206 1/SPF
25 4198 1/SPF
26 4190 1/SPF
4. TIH w/2 7/8? J-55 6.4# tbg and PKR, Set PKR @4090?. Acidize perfs 4190?-4390? with 2500 g 15% and 30 bio-balls. Swab test Lower Blineberry. 5. Frac the 1st stage Blineberry 4190?-4390? with 114,850 g 20# cross ling gel & 148,400 lbs 16/30
White and 30,000 lbs resin coated sand. (2x all sand? 20# XL, 8 tanks)
6. Flowback
7. Set a 5 ?? CBP @ 4150? and test.
8. RU wireline and perforate the second Blineberry stage as listed below. (1 spf. .41? EH)
Perf # Depth SPF
1 4120 1/SPF
2 4112 1/SPF
3 4104 1/SPF
4 4096 1/SPF
5 4088 1/SPF
6 4080 1/SPF
7 4072 1/SPF
8 4064 1/SPF
9 4056 1/SPF
10 4048 1/SPF
11 4040 1/SPF
12 4032 1/SPF
13 4024 1/SPF
.14 4016 1/SPF
15 4008 1/SPF
16 4000 1/SPF
17 3992 1/SPF
18 3984 1/SPF
19 3976 1/SPF
20 3968 1/SPF
21 3960 1/SPF
22 3952 1/SPF
23 3944 1/SPF
24 3936 1/SPF
25 3928 1/SPF
26 3920 1/SPF
9. Acidize Middle Blineberry 3920?-4120? with 2500 g 15% and bio-balls.
10. Frac the 2nd stage Blineberry with 114,850 g 20# cross ling gel & 148,400 lbs 16/30 White and
30,000 lbs resin coated sand. (2x all sand? 20# XL, 8 tanks)
11. Flowback
12. Set a 5 ?? CBP @3885?
13. RU wireline and perforate the third Blineberry stage as listed below. (1 spf, .41? EH)
```

32. Additional remarks, continued

```
Perf # Depth SPF
1 3850 1/SPF
2 3842 1/SPF
3 3834 1/SPF
4 3826 1/SPF
5 3818 1/SPF
6 3810 1/SPF
7 3802 1/SPF
8 3794 1/SPF
9 3786 1/SPF
10 3778 1/SPF
10 3770 1/SPF
11 3770 1/SPF
12 3762 1/SPF
13 3754 1/SPF
14 3746 1/SPF
15 3738 1/SPF
16 3730 1/SPF
17 3722 1/SPF
18 3714 1/SPF
19 3706 1/SPF
20 3698 1/SPF
21 3690 1/SPF
22 3682 1/SPF
23 3674 1/SPF
24 3666 1/SPF
25 3658 1/SPF
26 3650 1/SPF
```

- 14. Acidize the Upper Blineberry 3650?-3850? with 2500 g 15% and bio-balls.
 15. Frac the third stage Blineberry 3650?-3850? with 114,850 g 20# cross ling gel & 148,400 lbs 16/30 White and 30,000 lbs resin coated sand. (2x all sand ? 20# XL, 8 tanks)

16.30 White and 30,000 lbs resin coated sand. (2x all sand? 20# AL, 6 tanks)
16. Flowback.
17. TIH w 2 7/8? tbg and drill out CBP @ 3885? and 4150? and clean out to PBTD ~ 6900?.
18. Set SN@ 4420? and TAC @ 3600?, 8 jt MA.
19. RIH w 2? insert trash pump,(24? long, double SV, single TV, grooved plunger, steel parts), 6-1
5/8? Sinker bars, 95 ? 7/8? T66 or N97 rods, and 50 ? 1.25? FG rods.

20. Turn well to production.

COG Operating Procedure

Beech Federal #2

Logan Draw Field

Eddy County, NM

TWP: 18 S - Range: 32 E - Sec. 5

Additional Well info listed below procedure:

Objective: Set a CIBP over the Wolfcamp interval. Complete the Blineberry formation in three stages. Install 2 7/8" tbg and FG rods. Install pumping unit?

- 1. MIRU POH w rods & tbg. (224 jt 2 3/8" L-80 tbg SN@7021', TAC@6828', 95 7/8", 182- ¾" rods, 1.25" insert pump) Scan tbg while POH and send to Concho yard.
- 2. RIH w/5 ½" CIBP and set @6900' with 20 sks of Class C cmt on top. Test csg to 3500 psi for 10 minutes w kill truck. If csg tests good, then frac down csg. If not, then frac via 3 ½" N80 9.3 # work string.
- 3. RU wireline and perforate the first Blineberry stage as listed below. (1 spf, .41" EH)

Perf #	Depth	SPF
11	4390	1/SPF
2	4382	1/SPF
3	4374	1/SPF
4	4366	1/SPF
5	4358	1/SPF
6	4350	1/SPF
7	4342	1/SPF
8	4334	1/SPF
9	4326	1/SPF
10	4318	1/SPF
11	4310	1/SPF
12	4302	1/SPF
13	4294	1/SPF
14	4286	1/SPF
15	4278	1/SPF
16	4270	1/SPF
17	4262	1/SPF
18	4254	1/SPF
19	4246	1/SPF
20	4238	1/SPF

		,
21	4230	1/SPF
22	4222	1/SPF
23	4214	1/SPF
24	4206	1/SPF
25	4198	1/SPF
26	4190	1/SPF

-4120' with 2500 g 15% and bio-balls.

- 10. Frac the 2nd stage Blineberry with 114,850 g 20# cross ling gel & 148,400 lbs 16/30 White and 30,000 lbs resin coated sand. (2x all sand – 20# XL, 8 tanks)
- 11. Flowback
- 42. The w/2½//8 BJ-55 6.4# tbg and PKR, Set PKR @4090'. Acidize perfs 4190'-4390' with 2500 g 15% 13. Ru wireline and perforate the third Blineberry stage as listed below. (1 spf, .41" EH)
- 5. Frac the 1st stage Blineberry 4190′-4390′ with 114,850 g 20# cross ling gel & 148,400 lbs 16/30 **Depth** White and 30,000 lbs resin coated sand. 28 all sand 20# XI. 8 tanks)

_	Claudocale			1/01 1
6.	Flowback	2	3842	1/SDE
-	C-+ - E 1/// CDD @ 41 E0		3042	1/377
7.	Set a 5 ½" CBP @ 4150	and test.	2024	1/QDE
_	D	۱ ن	J. 5. 3834	1/526
8.	RU wireline and perfo	rate the secon	d biineberry st	age as II

4	3826	1/525
5	3818	1/SPF
6	3810	1/SPF
7	3802	1/SPF
8	3794	1/SPF
9	3786	1/SPF
10	3778	1/SPF
11	3770	1/SPF
12	3762	1/SPF
13	3754 ₁	1/58F ₁
14	37461	1/58F1
151	3,73β₁	1/SBF ₁
15 ₁ 16 ₁	373Q1	1/SBF ₁
17 ₁ 18 ₁ 19 ₁ 20	37721	1/SBF ₁
181	37,14₁	1/SBF ₁
191	3706 ₁ 3698	1/SBF ₁ 1/SPF
20	3698	1/SPF
21	3690	1/SPF
22	3682	1/SPF
23	3674	1/SPF
24	3666	1/SPF
25	3658	1/SPF
26	3650	1/SPF

- 14. Acidize the Upper Blineberry 3650'-3850' with 2500 g 15% and bio-balls.
- 15. Frac the third stage Blineberry 3650'-3850' with 114,850 g 20# cross ling gel & 148,400 lbs 16/30 White and 30,000 lbs resin coated sand. (2x all sand 20# XL, 8 tanks)
- 16. Flowback.
- 17. TIH w 2 7/8" tbg and drill out CBP @ 3885' and 4150' and clean out to PBTD ~ 6900'.
- 18. Set SN@ 4420' and TAC @ 3600', 8 jt MA.
- 1 . RIH w 2" insert trash pump,(24' long, double SV, single TV, grooved plunger, steel parts), 6-1 5/8" Sinker bars, 95 7/8" T66 or N 7 rods, and 50 1.25" FG rods.
- 20. Turn well to production.

Beech Federal

KB -

Lease & Well

#2

Spud - 5/31/01 Elevation - 3579' Co, NM

Sec 5, T18S, 32E, 660 FNL & 660 FWL

8 5/8" 32# STC J-55 @ 395', c/w 100 sx Thickset, 250 sx C, circ. 100 sx.

Perf'd 4 holes @ 5,230' & cemented 2/ stage

TOC 1st stage cmt @ 5,434'

Wolfcamp

6915 - 26', 12 holes

6981 - 88', 8 holes

Acidized w/2,000 gal 155 NEFE

11/26/01: 32,000 g hot 20% HCL, 54,000 g heated 40# gel

1st stage: 500 50/50/C, c/n open DV tool, TOC @ 5434', CBL.

2nd stage: perf'd 4 holes 5,230', cmt w/ 950 sx lite, 150 sx tail, circ 134 sx.

5 1/2" 17# LTC J-55 @ 7,800'

DV tool @ 6164'

Marker jt - 6795'

PBTD -7,752'

Beech Federal 2 30-015-31790 COG Operating LLC February 25, 2010 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location as H2S has been reported.
- 4. A minimum of a 2M BOP is required and must be tested prior to RIH. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 5. Contact BLM 575-361-2822 prior to starting recompletion.
- 6. Contact the BLM if casing does not test.
- 7. Need to pump 25 sacks on top of CIBP @ 6,900'.
- 8. Need 160' plug @ 6,632' to cover the top of the Wolfcamp (6,583').
- Need 160' plug @ 6,214' to cover the DV tool (6,164'), WOC & Tag.
 - *10. Need 150' plug @ 5,260' to cover the top of the Abo (5,210').
 - 11. Subsequent sundry and completion report required.

MAK 030210