

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-005-1-140
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Twin Lakes San Andres Unit
8. Well No. 53
9. Pool name or Wildcat Twin Lakes San Andres (Assoc.)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3941 KB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Hanagan Petroleum Corporation
3. Address of Operator P.O. Box 1737, Roswell, NM 88202	4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>2</u> Township <u>9S</u> Range <u>28E</u> NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3941 KB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to Plug & Abandon as follows:

Notify NMOC-D-Artesia, 24 hours prior to commencement of plugging.

- 1) Set CIBP @ 2520' & cap w/35' cement plug (top perf. @ 2542')
- 2) Fill hole w/mud & set 100' plug across T/San Andres from 1965' to 1865' (T/San Andres @ 1915'). * 255X MIN CMT Plug.
- 3) Fill hole w/mud & set 100' plug across surface shoe interval from 480' - 380'. * 255X MIN CMT Plug.
- 4) Fill hole w/mud & set 10 SK plug @ surface.
- 5) Install Dry Hole marker & clean location.

TAG MAY 13 1998
RECEIVED
OCD - ARTESIA

Notify NMOC-D-Artesia to witness plugging operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael G. Hanagan TITLE President DATE 5/13/98
TYPE OR PRINT NAME Michael G. Hanagan TELEPHONE NO. 505/623-5053

(This space for State Use)

APPROVED BY Marie S. Littlefield TITLE Field Rep. II DATE May 21-98
CONDITIONS OF APPROVAL, IF ANY: