

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**OIL CONSERVATION DIVIS**  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

151  
b

Form C-103  
Revised 10-1-73

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
**LG-566-1**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPERATE OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - C-101 FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name <b>NA</b>
2. Name of Operator <b>Jack J. Grynberg</b>	8. Farm or Lease Name <b>Grynberg 16 State</b>
3. Address of Operator <b>5000 South Quebec, Suite 500, Denver, CO 80237</b>	9. Well No. <b>4</b>
4. Location of Well UNIT LETTER <b>G</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>East</b> LINE, SECTION <b>16</b> TOWNSHIP <b>5S</b> RANGE <b>24E</b> N.M.P.M.	10. Field and Pool, or Whicet <b>Pecos Slope Abo Gas</b>
11. Elevation (Show whether DF, RT, GR, etc.) <b>3982 K.B.</b>	12. County <b>Chaves</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well will be plugged as follows:

1. Set CIBP at 3500' and cap with 35' of cement.
2. Equalize 100' plug inside 4-1/2" casing from 1525' to 1425'.
3. Perforate at 1000' and equalize 75 sk plug inside and outside 4-1/2" casing. **TAG**
4. Cut off casing strings 2' below ground level.
5. Lay 10 sk plug inside 4-1/2" casing at surface.
6. Leave salt gel mud mixed with 25#/bbl brine water between plugs.
7. Install dry hole marker 4' above ground level.
8. Cut off anchors and flow line 1' below ground level.
9. Clean and level location.

10-3/4" @ 901'  
4-1/2" @ 3991  
PBTD 3700'  
TOC @ 1475'  
Perfs: 3547-3650'

↑  
MAR 1998  
RECEIVED  
OCD - ARTESIA

\* Notify NMOC before beginning plugging operations.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED KR Kuller TITLE Engineer DATE 3/23/98

APPROVED BY Mark Stollfeld TITLE Field Rep. II DATE 3/31/98

ATIONS OF APPROVAL, IF ANY: