## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we, or cortex acceives		
DISTRIBUTION		_
SANTA FE	V	_
FILE	10	7
U.S.G.S.		
LAND OFFICE		_
OFFRATOR		_

## OIL CONSERVATION DIMESTON

i	DISTRIBUTION			Р. О. ВО	X 2088	Form C-103 ·
	SANTA FE	V			V MEXICO 87501	Revised 10-1-78
[	FILE	i	~		MAD 2 0 1733	
	U.S.G.S.				MAR 29 1983	5a. Indicate Type of Lease
Ī	LAND OFFICE				<b>o</b> -	State Fee X
	OPERATOR	1			O. C. D.	5, State Oil & Gas Lease No.
_					ARTESIA, OFFICE	
	(DO NOT USE THIS FOR	SUI	NDRY	NOTICES AND REPORTS ON OSALS TO DAILL OF TO DELPTH OR PLUG OF FOR PERMIT - P. (FORM C-101) TOR SUC		
	USE *	*APPL	ICATIO	IN FOR PERMIT -" (FORM C-101) FOR SUC	CH PROPOSALS.)	
	11 GAS	$\overline{\mathbf{x}}$		OTHER-		7. Unit Agreement Name
	ne of Operator					
	- •	C				8, Farm or Lease Hame
	tes Petroleum (	corp	orai	tion		Sacra SA
	lress of Operator					9. Well No.
20	7 South 4th St	., A	Artes	sia, NM 88210		9
4. Loc	ation of Well					10. Field and Pool, or Wildcat
u	HIT LETTERM	· · ·	660	O FEET FROM THE South	LINE AND 660	
TI	west	NE. 51	ECTION	19 township 6S	26E	
					NMP	
111		111	111	15. Elevation (Show whether	DF, RT, GR, etc.)	12. County
		III	IIII	3742'.k	GR	Chaves
16.	(	Chec	k Ap	ppropriate Box To Indicate N	Vature of Notice Report of C	ther Data
	NOTIC	E OF	INT	TENTION TO:		NT REPORT OF:
					308320021	TREPORT OF:
*****	AM REMEDIAL WORK			PLUG AND ABANDON		
	=			PEGG AND ABANDON	REMEDIAL WORK	ALTERING CASING
	BRARILY ABANDON				COMMENCE DRILLING OPHS.	PLUG AND ABAHDONMENT
FULL C	OR ALTER CASING			CHANGE PLANS	CASING TEST AND CEMENT JOB	
					OTHER Production Cas:	ing, Perforate, Treat X
0T H	(EA					
					•	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4200'. Ran 105 jts of 4-1/2" 9.5# J-55 ST&C casing set 4200'. 1-regular guide shoe set 4200'. Float collar set 4185'. Cemented w/500 sacks 50/50 Poz, .6% D-19, .3% D-31 and 4#/sack KCL. Compressive strength of cement - 1050 psi in 12 hours. PD 5:45 AM 3-19-83. Bumped plug to 1000 psi, released pressure and float held okay. WOC 18 hours. Ran 1500' of 1". Cemented w/300 sacks Pacesetter Lite. WIH and perforated 3790-4038' w/22 .40" holes as follows: 3790-96' (12 holes - 2 SPF); 3944, 46, 64, 66, 80 and 82 (1 shot each), 4036, 4038' (4 holes - 2 SPF). RIH w/tubing packer and RBP. Acidized perforations 3790-4038' w/3000 gallons  $7\frac{1}{2}\%$  Spearhead acid and 14 ball sealers. Frac'd perforations 3790-4038' (via casing) w/40000 gallons gelled KCL water, 70000# 20/40 sand and 1000 712% Spearhead acid. POOH w/tools. Swabbed back load. Ran tubing and packer and set packer at 3743'.

my knowledge and belief.		
my knowledge and belief.		
my knowledge and belief.		
luction Supervisor	DAYE	3-28-83
riginal Signed By oslie A. Clements		MAR 2 9 1983
E	estie A. Clements  upervisor District II	estie A. Clements