		Leslie A. Clements	IUN 0 7 1984
OICHED Whise yarms	TITLE Dr	illing/Production Co — Original Signed By	ordinato _{kit}
10110/		4114ma/D	vordinator
18. I hereby comiff that the information above to tr	ue and complete to the best	of my knowledge and belief.	
	,		
_			
	•		
	•		
SEE ATTACHED "EXHIBIT A"			
CDD AMMACUED REVUIDEM A	.a		
work) SEE RULE 1103.			•
17. Describe Proposed or Completed Operations (Cl	learly state all pertinent deto	ils, and give pertinent dates, in	cluding estimated date of starting any proposed
OTHER			
	السر أ	Perforate,	Stimulate, Test X
PULL OR ALTER CASINS	CHANGE PLANS	CARLING TEST AND CEMENT 103	Stimulate Test
PERFORM REMEDIAL WORK	PLUG AND ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
	PLUG AND ABANDON	RENIEDIAL WORK	ALTERING CASING
NOTICE OF INTENTION	1 TO:	SUBSEC	QUENT REPORT OF:
16. Check Appropria	te Box To Indicate N	ature of Notice, Report	
3812' MSL		Chaves	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
THE West LINE, SECTION 20	томизить <u>УБ</u>	RANGE Z/E	. MMPM. ([[]]]]]]]]
UNIT CETTER L 1980	EET FROM THE South	LINE AND FEE	Und. S. Pecos Slope Abo
1. Location of Well			10. Field and Pool, or Wildeat
5000 S. Quebec, Suite 500, Denver, CO 80237			#1
Jack J. Grynberg V 3. Address of Operator			9. Well No.
Z. Name of Operator			Grynberg State Com.
WELL WELL (A) OTHER-			8. Farm or Lease Name
1.			7. Unit Agreement Name N/A
SURIUM T NO HILE TOOM FOR PROPOSALS TO DE USE "APPLICATION FOR PERM	THE ON TO OXEPEN ON PLUG SA THE ON TO OXEPEN ON PLUG SA THE AND TO STORM C-1011	WELLS ARTESIA OFFICE	
STEIDDY NOTICE	S AND DEPORTS ON	WELLS ARTESIA OCCUPE	
OPERATOR V	. 🗴		LH-1898
LAND CFFICE		JUN 07 1984	State X Fee 5. State Oil & Gas Lease No.
VILE 22			5a, Indicate Type of Leuse
BANTAKE	SANTA FE, NEW	MEXICRECENTED BY	
HOLTUBERTEID	P. O. BOX 2088		Form C-103 Revised 10-1-78
FNEHGY AND MINERALS DEPARTMENT	OIL CONSERVAT	TION DIVISIC	
STATE OF NEW MEXICO	•		
and the second second	•		

EXHIBIT "A"

- 3/13/84 Perf. 6198-6207' w 2 SPF Run 196 jts. (6171.32') 2 3/8 4.7# API tubing.
- 3/14/84 Acidize, 2000 gals. 10% MORFLO, 65,000 SCF nitrogen. Flowback.
- 3/15/84 Small flow of gas. Perf. 6163-6170', 2 SPF.
- 3/16/84 Acidize with 2000 gals. 10% MORFLO, 65,000 SCF nitrogen. Flowback.
- 3/17/84 FRAC w/20,000 gals. Versagel 1300, 6700 gals. CO2, 30,000 lbs. 20/40 sand. SI, Flowback. Well Dead 3/18/84.
- 3/20/84 Set CIBP @ 5540'. Perf 5414" to 5429', 2 SPF.
- 3/21/84 Acidize with 3000 gals., 15% acid, 500 SCF/bbl. nitrogen.SI, Flowback.
- 3/22/84 Small show of gas. Blew down, swabbed.
- 3/23/84 3/26/84 Attempt to set CIBP @ 4920. Would not hold pressure test. Ran tracer survey, no casing problems.
- 3/27/84 Set CIBP @ 4756', pressure test, held okay. Perf. 4728-4736' 2 SPF.
- 3/28/84 Acidize w/2000 gals. MOD 101, 1000 SCF/bbl. nitrogen. Flowback.
- 3/29/84 Small show of gas. Frac. w/20,000 gals., gelled 20% KCL, 6000 gals. liquid CO2, 15,000 lbs. 20/40 sand, 14,000 lbs., w/20 sand. SI, Flowback.
- 3/30/84 Well dead, swabbed, FTP 500#, FCP 800#, died again, SI.

Well remains shut-in, waiting on pressure buildup.