, ,	R A I	80 m u m	
	N.	M. Oil Cons. Di	
Form 3160-5 (September 2001)	UNITED STATES	301 W. Grand	AVENUS OMB No. 1004-0135 Expires January 31, 2004
BUREAU OF LAND MANAGEMENTARIOSIA, NMI 882 10 Lease Serial No.			
SUNDR	1M 36408		
Do not use th abandoned we	is form for proposals to drill o ମା. Use Form 3160-3 (APD) for s	or to re-enter an such proposals.	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well		22252627282	
🖸 Oil Well 🖾 Gas Well 🕻	Other		8. V/eil Name and No.
2. Name of Operator EXCO Resources, I			Rose Federal 16
3a. Address 6500 Greenvi		Phone No. (include area coae)	30 005 63414
Dallas, Texas 752	206	21 4 368 208 EIVED	(A) . Field and Pool, or Exploratory Area A Pecos Slope EIA 547405
4. Location of Well (Footage, Sec. M-20-05S-25E	, T., R., M., or Survey Description) 100' N of Center S	SW SW OCD - ARTES	Q /11. County or Parish, State
660' FSL & 660' F	WL	F.91.91 *** ***	(Thaves
12. CHECK AP	PROPRIATE BOX(ES) TO INE	DICATE NATURE OF NOTI	CE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	DN
	🛛 Acidize	Deepen Deepen Deepen	on (Start/Resurie) 🔲 Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat 🔲 Reclama	~
Subsequent Report		New Construction U Recomp	
Ginal Abandonment Notice		Plug and Abandon 🛄 Tempor Plug Back 🔲 Water D	arily Abandonisposal
testing has been completed. F determined that the site is ready BLM/BIA Bond No. Propose to test,	inal Abandonment Notices shall be filed for final inspection.) on file: NM 2831 perforate and stimuling in the Peccos Slop p. k procedure.	ate the Wolfcamp f	le commingle of
			on tech
Signature CLUM	_Daf	Date 4-2202	
/ THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by alt	۲	Title PE.	Date 4/25/02
certify that the applicant holds le which would entitle the applicant t		the subject lease Office $\frac{k^2}{Ft}$)
Title 18 U.S.C. Section 1001 and States any false, fictitious or fraud	Title 43 U.S.C. Section 1212, make it a ulent statements or representations as to a	crime for any person knowingly and any matter within its jurisdiction.	I willfully to make to any department or agency of the United

J.

Rose Federal No. 16 Pecos Slope Field Chaves County, NM Workover Procedure

•

.

1. Deliver wellhead equipment to location. Make final cut on 4-1/2" casing. Weld on bell nipple.

2. MIRU workover rig.

3. MIRU EL unit. GIH w/CBL/CCL from PBTD @ 4,385' to TOC.

4. PU 4jts 2-3/8" tail pipe, 4-1/2" packer and 2-3/8" tubing. GIH w/same to ± 4,100'. Set pkr. @ same w/20K in compression.

5. PU perforating gun. GIH w/1-11/16" Ported TTP gun to \pm 4,344'. Perforate for production @ 4,344' - 52'. POOH. RD EL unit.

6. MIRU BJ Services. Perform Ball-out Acid job per BJ procedure.

7. RD BJ Services and connect flow back equipment.

8. Place well on test.

9. Swab well in if needed.

Jps April 16, 2002 Rose Federal No. 16 Pecos Slope Field Chaves County, NM AFE No. Workover Procedure

. . •

Objective: Perforate and Stimulate The Wolfcamp Formation. Ground Level: 3,836' above sea level 3,848' Kelly Bushing, 12' above ground level Datum: KOP: 1,243' Total Depth: 4,442' (MD)/ 4,389' (TVD) 4,385' (MD) PBTD: 14-3/4" 60#/ft conductor set @ 40' Casing: Cmt'd to surface. 9-5/8" 36#/ft J-55 ST&C @ 905' Cmt'd w/400 sxs BJ Lite Follow'd w/200 sxs Class "C" w/2% CaCl2 4-1/2" 10.5#/ft J-55 ST&C @ 4,436' Cmt'd w/350 sxs Super "C" Modified Current Perforations: NA Proposed Perforations: 4,344' - 52' "Wolfcamp Formation" 4/15/2002 Prepared By: J. P. Shinn