


OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>



5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG 9357

SUNDRY NOTICES AND REPORTS ON WELL

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A WELL IN RESERVATION. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
Name of Operator Yates Petroleum Corporation ✓	8. Farm or Lease Name Inexco YP State
Address of Operator 207 South 4th St., Artesia, NM 88210	9. Well No. 1
Location of Well UNIT LETTER P 660 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 12 TOWNSHIP 1S RANGE 17E NMPM.	10. Field and Pool, or Wildcat Wildcat Precambrian
15. Elevation (Show whether DF, RT, GR, etc.) 5506.7' GR	12. County Lincoln

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission obtained from Larry Brooks, NMOCD, Artesia, 10:00 AM 6-6-84 to plug and abandon well as follows:

- 1) Notify NMOCD 24 hours in advance of plugging.
- 2) Set CIBP at 2052'± w/35' cement on top.
- 3) Shoot/pull casing at 1690'± (cement top 1690'± per bond log)
- 4) Set cement plug 1740' to 1500' and tag (i.e. - 50' in stub and tie to 8-5/8")
- 5) Set cement plug 370-470' (covers surface shoe)
- 6) Run 1 joint and circulate 15 sacks for surface plug. Set dry hole marker.
- 7) Clean location and notify NMOCD when ready for inspection.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leslie A. Clements TITLE Production Supervisor

DATE 6-6-84

APPROVED BY _____ TITLE Supervisor District II

DATE JUN 07 1984

CONDITIONS OF APPROVAL, IF ANY: