

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-027-20040
5. Indicate Type of Lease	STATE ☐ FEE ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Manzano Oil Corporation 505/623-1996

3. Address of Operator
P.O. Box 2107/Roswell, NM 88202-2107

4. Well Location
Unit Letter J : 2310 Feet From The South Line and 2103 Feet From The East Line

Section 9 Township 4 South Range 11 East NMMP Lincoln County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
6051' GL

7. Lease Name or Unit Agreement Name	Spaid Buckle
8. Well No.	1
9. Pool name or Wildcat	Spaid Buckle; Penn

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☒
PULL OR ALTER CASING ☐		CASING TEST AND CEMENT JOB ☐	
OTHER: ☐		OTHER: ☐	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/29/96 TD 4871'. Prep to P&A well.
11/30/96 Rigging down. Well P&A. Received plugging orders from Tim Gunn w/NMOCD on 11/27/96. Plugged well in the following manner: Set a 100' 30 sx C1 C cmt plug (@ TD 4871') from 4871 to 4771'. Set a 376' 260 sx C1 C cmt plug (at the top of the Abo @ 2434') (to the base of the salt @ 2108'). Wait 4 hrs. Tag plug @ 2000'. Set a 100' 90 sx C1 C cmt plug (at the top of the salt @ 1696') from 1696' to 1596'. Set a 100' 90 sx C1 C cmt plug (at the base of the 13-3/8" csg @ 1150') 50' in & 50' out from 1200' to 1100'. Wait 4 hrs. Tag plug @ 1050'. Set a 15' - 10 sx C1 C cmt plug at the surface.
12/01/96 Rig released.

Post ID-2
1-12-97
P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Allison Hernandez TITLE Engineering Technician DATE 12/02/96
TYPE OR PRINT NAME Allison Hernandez TELEPHONE NO. 623-1996

(This space for State Use)

APPROVED BY Steve S. Hurrell TITLE Field Rep. II DATE 4-7-98