

Proposed P & A Procedure

Page 2 of 2

8. Free point 4 1/2" 11.6# and 10.5# csg, cut off same 50' above free point, and POOH and lay down csg.
9. Change out rams on BOF to 2 3/8"
10. TIH with tbg and set 100 cement stub plug 50' in and out at 4 1/2" stub. WOC and tag plug.
11. Set 200' cmt plug at 8 5/8" shoe 100' in and out of shoe. WOC and tag plug.
12. ~~Set 100' cmt plug at San Andres top at 1400'~~, set 100' plug at 13 3/8" shoe 330' and up. WOC an tag plug.
13. NDBOP, cut off well head 4' below ground level, set 10 sx surface plug.
14. Install P & A Marker with the following information welded on marker 4' above ground level.

Murchison Oil and Gas
Berry Federal Com #1
Sec.28, T-17S, R-27E
1980' FNL and 660' FWL
Eddy County, New Mexico
P&A Date
15. Remove all equipment from location, rip location and seed location with seed required by BLM.