

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR OXY USA Inc.	8. FARM OR LEASE NAME Citco Federal
3. ADDRESS OF OPERATOR P.O. Box 50250 Midland, TX. 79710	9. WELL NO. 2Y
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NENE Sec 21 T16S R26E 330/N 380/E	10. FIELD AND POOL, OR WILDCAT Eddy city Und. San Andres
14. PERMIT NO.	15. ELEVATIONS (Show whether DP, RT, GR, etc.) 3354'
	12. COUNTY OR PARISH Eddy
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	PULL OR ALTER CASING
FRACURE TREAT	MULTIPLE COMPLETE
SHOOT OR ACIDIZE	ABANDON*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRACURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

TD-1350' PBTD-1344' San Andres-1211'-1288' It is proposed to Plug and Abandon in the following manner:

1. MIRU PU. TOOH w/rods & pump. ND WH, NU BOP. TOOH w/tbg.
2. RU wireline, RIH w/CIBP and set @ 1200'. RD wireline.
3. TIH w/tbg OE and tag CIBP. Circ hole w/9.5#/gal mud laden fluid. Spot 9 sx plug from 1200' to 1070'. PU on tbg to 455'. Spot 7 sx plug from 455' to 354'.
4. PU on tbg to 50' and spot 4 sx plug from 50' to surface. TOOH and LD tbg. Cut off wellhead & install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED David Stewart for TITLE Operations Manager

DATE 12/18/89

(Prepared by David Stewart)

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE PETROLEUM ENGINEER

DATE 12-20-89

*See Instructions on Reverse Side