Submit 3 copies	State of	New Mexico		C 9 F Form C-103
to Appropriate		tural Resources Depa.	.ıt	C Portine C-103
District Office	<i>y</i> , while als and wa	tui ai Resources Depa.	.1L	Revised 1-1-89
				\cup
DISTRICT I	OIL CONSERVAT	ION DIVISION		WELL API NO.
P.O. Box 1980, Hobbs, NM 88240	P.O. Box			30-015-30560
<u>DISTRICT II</u>	Santa Fe, New Mexico	87504 -2088		5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210		21314151672		STATE 📈 FEE
DISTRICT III		18 C 18	8	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410			3	B-8617
	SUNDRY NOTICES AND REPOR	TS ON WELLS	-61-	
	RM FOR PROPOSALS TO DRILL OR TO	IN D. 4 20A	12	7. Lease Name or Unit Agreement Nam
		16 - C/J - M////	N IOM	
DIFFE	CRENT RESERVOIR. USE "APPLICATI		2	Spurck 15 State
	(FORM C-101) FOR SUCH PROPOS.	ALSO SIA	A.	Com
1. Type of Well:			av/	1
	7	16212829303	9	
Well Well	OTHER			
2. Name of Operator V				8. Well No.
Yates Drilling Company 3. Address of Operator				1
105 South 4 th St., Artesia, NM 88210				9. Pool name or Wildcat
4. Well Location		·····		Empire, Penn
Unit LetterD: 660	Feet From The North	Line660		Feet From The West Lin
		and		Feet From The West Lin
Section 15	Township 17S	Range 28E	NMPM	Eddy Count
			V///	
11.	Check Appropriate Box to Indi	cate Nature of Notice,	Report, o	or Other Data
NOTICE	OF INTENTION TO:	SUBS	SEQUE	NT REPORT OF:
PERFORM REMEDIAL WORK	PLUC AND ABANDON	DEMEDIAL WORK	•	<u> </u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
	PLUG AND ABANDON	REMEDIAL WORK		<u> </u>
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	-	ALTERING CASING
			-	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILL	ING OPNS	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
			ING OPNS	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON		COMMENCE DRILL	ING OPNS CEMENT J	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON		COMMENCE DRILL	ING OPNS CEMENT J	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: <u>Perforate</u> , A	ING OPNS CEMENT J	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc	ING OPNS CEMENT J weid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc	ING OPNS CEMENT J weid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: <u>Perforate</u> , 4 and give pertinent dates, inc (with tubing, scrapper and b	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: <u>Perforate</u> , 4 and give pertinent dates, inc (with tubing, scrapper and b	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran
TEMPORARILY ABANDON TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'.	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, ind with tubing, scrapper and 1 -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac cluding estin cluding estin pit. TIH win shots. RIH	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac cluding estin cluding estin pit. TIH win shots. RIH	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac cluding estin cluding estin pit. TIH win shots. RIH	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% E	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, inc with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5%	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, ind (with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 52 tons CO2 with 360510 SC	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5%	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, 4 and give pertinent dates, ind (with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 52 tons CO2 with 360510 SC	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB mated date of starting any proposed th logging tools and ran with UNI VI packer and 2 7/8" tubing.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5%	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 2 tons CO2 with 360510 SC	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB The starting any proposed th logging tools and ran the with UNI VI packer and 2 7/8" tubing. the well in.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5% I hereby certify that the information SIGNATURE	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 2 tons CO2 with 360510 SC	ING OPNS CEMENT J cid, Frac cluding estin oit. TIH win shots. RIH CF N2. Shu	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB Material of starting any proposed th logging tools and ran (with UNI VI packer and 2 7/8" tubing. tt well in16-00
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5% I hereby certify that the information SIGNATURE TYPE OR PRINT NAME	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 2 tons CO2 with 360510 SC	ING OPNS CEMENT J cid, Frac cluding estin oit. TIH win shots. RIH CF N2. Shu	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB The starting any proposed th logging tools and ran the with UNI VI packer and 2 7/8" tubing. the well in.
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5% I hereby certify that the information SIGNATURE TYPE OR PRINT NAME	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, ind (with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 52 tons CO2 with 360510 SC	ING OPNS CEMENT J coid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB Material of starting any proposed th logging tools and ran (with UNI VI packer and 2 7/8" tubing. tt well in16-00
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5% I hereby certify that the information SIGNATURE TYPE OR PRINT NAME	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, ind (with tubing, scrapper and l -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 52 tons CO2 with 360510 SC	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB AD
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Op work) SEE RULE 1103. 4-26-00 RIPU. TIH with bit, scrapper a 4-27-00 Tagged cement at 10187'. Pickl CBL/GR/CCL. TOH with 4-29-00 Rigged up wireline. TIH with 3 Set packer at 9771'. 4-30-00 Acidized with 1000 gals. 7.5% F 5-7-00 Frac'd well with 500 gals 7.5% I hereby certify that the information SIGNATURE TYPE OR PRINT NAME	CHANGE PLANS	COMMENCE DRILL CASING TEST AND OTHER: Perforate, A and give pertinent dates, inc with tubing, scrapper and R -9902', .32" holes, 2 SPF, 24 ed back well. Shut well in. 2 tons CO2 with 360510 SC	ING OPNS CEMENT J ceid, Frac	ALTERING CASING ALTERING CASING PLUG AND ABANDONMENT OB Material of starting any proposed th logging tools and ran (with UNI VI packer and 2 7/8" tubing. tt well in16-00

,

CONDITIONS OF APPROVAL, IF ANY: