

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIP. ATE.
(Other instructions on reverse side)
RECEIVED

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

1985

5. LEASE DESIGNATION AND SERIAL NO.
LC-069111

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Parcell Federal

9. WELL NO.
1

10. FIELD AND POOL, OR WILDCAT
T. Track-SR-Q-GR-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
S31-T18S-R30E

12. COUNTY OR PARISH
Eddy

13. STATE
NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Frank O. Elliott

3. ADDRESS OF OPERATOR
Post Office Box 1355, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations. See also space 17 below.)
At surface
Unit E, 1980' FNL and 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, OR, etc.)
O. C. D.

CARLSBAD AREA

10 52 AM '92

RECEIVED
JAN 17 1992

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>		(NOTE: Report results of multiple completion on Well Completion or Reconpletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Intend to plug and abandon using the following procedures after notification to BLM before beginning:

1. Pull rods and pump. Tally tubing out of hole. Dig workover pit.
2. Set CIBP at 2800' (7"). Circulate hole with mud laden fluid.
3. Spot 50' plug on top of CIBP.
4. Spot 35 sack plug 2275' - 2075'. Tag plug.
5. Perforate casing at 1180' and 400' (each set 2' - 8 holes).
6. Set cement retainer just above perfs at 1180'. Squeeze perfs at 1180' with 35 sacks. Pull out of retainer and spot 50' cap on retainer.
7. Break circulation between 8 5/8" and 7" through holes at 400'. Spot 35 sack plug inside 7" to 275'. Cement should circulate around annulus to surface. CEMENT TOP 50' OF ANNULUS OUTSIDE SURF. CCG.
8. Set 50' surface plug and install marker. Clean and finalize the location as directed by BLM.

18. I hereby certify that the foregoing is true and correct

SIGNED Becky Bloom TITLE Agent DATE 11-26-91


(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE 1-15-92

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

WELL NO. 1
1980' FWL 660' FWL



8 5/8" CSG AT
350' W/50-100 SX?

T.O. SALT AT 610'

B.O. SALT @ 1130'

TOC: ~ 1800' ?

CHL @ 2399'

2846
Perfor. on 11/8/58
2860

P.B.H.D. 2885'

7" CSG AT
2850' W/100 SX
2919 ?

SPADMASTER
Made in USA