

(No number 1983)
(Formerly 94-381)

UNITED STATES

DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Expires August 31, 1985

6/51

Drawer DD

BUREAU OF LAND MANAGEMENT

RECEIVED SUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

APR 1 1985

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Amador Production Company

3. ADDRESS OF OPERATOR

P. O. Drawer 130, Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

990' FNL & 330' FWL

ut. D

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3552'

5. LEASE DESIGNATION AND SERIAL NO.

LC 058581

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Miller

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Loco Hills-Queen-G-SA

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

4 - 18S - 29E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

Re-plug ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Note: The NMOCD requires this well to be replugged.

1. Blade road; dig workover pit; set anchors; dig out surface and install workover head.
2. Rig up pulling unit and reverse unit.
3. Pick up bit and DCs; drill out cement plugs and clean out to bottom cement plug at approximately 2350' as shown on attached schematic. Circulate hole with 10# brine and salt gel mud.
4. Spot 35 sx Class H cement with 5% CaCl from 2350' to 2250'; this plug will cover Grayburg formation top.
5. Tag top of plug after 2 hours; spot 40 sx Class H with 5% CaCl from 885' to 765'; this plug will isolate bottom of Salt section.
6. Tag top of plug after 2 hours; spot 50 sx Class H cement with 5% CaCl from 350' to 200'; this plug will cover 8-5/8" casing shoe and isolate top of Salt section.
7. Tag top of plug after 2 hours; spot 15 sx Class H cement with 5% CaCl from 50' to surface; this will cover surface plug.
8. Cut off all casing and anchors below surface; set P & A marker; clean and level location.

Note: There will be 10# brine and salt gel mud between all plugs.

18. I hereby certify that the foregoing is true and correct

SIGNED Mr. B. Brownell

TITLE Field Foreman

DATE March 5, 1985

(This space for Federal or State office use)


APPROVED BY Orig. [Signature]

TITLE APL [Signature]

DATE 3-29-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

Anadarko Miller # 2
(Ballard 10-2)

①