177 P.	с'ъ.	e .	

	2
orm 9–331	Form Approved.
1973 ≘ 1	Budget Bureau No. 42R1424 :-
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-0559774
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME RECEIVED
Do not use this form for proposals to drill or to deepen or plug back to a different . servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas 🕅 well 🕅 other	CC Tank Unit MAR 2 6 1981 9. WELL NO.
Well Well	1
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Yates Petroleum Corporation V	Wildcat Gigeo
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
207 South 4th St., Artesia, NM 88210	AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Unit F, Sec. 28-19S-24E
below.) jarontul AT SURFACE:	12. COUNTY OR PARISH 13. STATE
AT SURFACE: AT TOP PROD. INTERVAL:	Eddy NM
AT TOTAL DEPTH:	14. API NO.
 CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 	
REFURI, UN UTDEN DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3748' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	J/40 GA
rest water shut-off	
Eacture treat \Box \Box	
SHOOT OR ACIDIZE	~>
REPAIR WELL 🗌 🗌 🖉 🥂 🔨	NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	
CHANGE ZONES	9 Seleve
ABANDON*	$(\mathcal{V}_{\mathcal{U}_{\mathcal{T}}})$
(other)	· VIII
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner 	inectioneny/ormed, give subsurface locations and
aged up & pulled tubing & packer. WIH w/casing a	
gged up & pulled tubing & packer. WIH w/casing & 28-38' w/20.34" holes (2 spf). Set RBP @7102' &	gun on wireline & perforated
28-38' w/20 .34" holes (2 spf). Set RBP @7102' &	gun on wireline & perforated & Uni VI packer @7007' on
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & G	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & G	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well
28-38' w/20.34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off pulus unloaded. Killed well & circulated w/700	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/2 6.30 PM 2-18-81. squeezed to 1750 psi, plug @0	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 '50 sacks Scavinger slurry, 500 sacks Class C w/3 0 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 powed weak indication of cement @5850'. WIH & po	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 nowed weak indication of cement @5850'. WIH & per content w/400 bbls 10# brine. Cemented w/625 sacks (gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3%
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 wowed weak indication of cement @5850'. WIH & pe ell w/400 bbls 10# brine. Cemented w/625 sacks (-HD, PD 4:20 PM 2-21-81. Ran Temperature Surve	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & po 11 w/400 bbls 10# brine. Cemented w/625 sacks -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & po 11 w/400 bbls 10# brine. Cemented w/625 sacks C-HD. PD 4:20 PM 2-21-81. Ran Temperature Surve- mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 00' Pressure tested to 1500# okay. Ban Cement	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/2 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & po 11 w/400 bbls 10# brine. Cemented w/625 sacks PHD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & po 11 w/400 bbls 10# brine. Cemented w/625 sacks -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 00'. Pressure tested to 1500# okay. Ran Cemen Subsurface Safety Valve: Manu. and Type	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & performed w/400 bbls 10# brine. Cemented w/625 sacks Class C v/3 - HD. PD 4:20 PM 2-21-81. Ran Temperature Survemented w/100 sacks Class C via 8-5/8 & 4-1/2 cases 00'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Set @Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & c mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 owed weak indication of cement @5850'. WIH & pe 11 w/400 bbls 10# brine. Cemented w/625 sacks 6 -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 00'. Pressure tested to 1500# okay. Ran Cemen Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering signed by the foregoing is true and correctengineering	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @0 owed weak indication of cement @5850'. WIH & po 11 w/400 bbls 10# brine. Cemented w/625 sacks 0 -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 00'. Pressure tested to 1500# okay. Ran Cemen Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering signed by the foregoing is true and correctengineering	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 owed weak indication of cement @5850'. WIH & pe 11 w/400 bbls 10# brine. Cemented w/625 sacks 6 -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 00'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering SIGNED (This space for Federal or State of (This space for Federal or State of	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 howed weak indication of cement @5850'. WIH & performed w/400 bbls 10# brine. Cemented w/625 sacks (2 50 F-HD. PD 4:20 PM 2-21-81. Ran Temperature Surver emented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering SIGNED (TILE Secretary (This space for Federal or State of (2)) (This space for Federal or State of (2))	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
 28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & a fmud & pull BP, packer & tubing. Shot casing off nulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/30 6:30 PM 2-18-81, squeezed to 1750 psi, plug @60 6:30 PM 2-18-81, squeezed to 1750 psi, plug @60 6:30 PM 2-18-81, squeezed to 1750 psi, plug @60 6:30 PM 2-18-81, squeezed to 1750 psi, plug @60 6:30 PM 2-18-81. Ran Temperature Surverse tested to 1500 # okay. Ran Cement w/100 sacks Class C via 8-5/8 & 4-1/2 cases 000'. Pressure tested to 1500 # okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct Engineering SURVED for t	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd) Ft.
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 howed weak indication of cement @5850'. WIH & performed w/400 bbls 10# brine. Cemented w/625 sacks (2 50 F-HD. PD 4:20 PM 2-21-81. Ran Temperature Surver emented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering SIGNED (TILE Secretary (This space for Federal or State of (2)) (This space for Federal or State of (2))	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 howed weak indication of cement @5850'. WIH & performed w/400 bbls 10# brine. Cemented w/625 sacks (2 50 F-HD. PD 4:20 PM 2-21-81. Ran Temperature Surver emented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering SIGNED (TILE Secretary (This space for Federal or State of (2)) (This space for Federal or State of (2))	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & o mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 howed weak indication of cement @5850'. WIH & performed w/400 bbls 10# brine. Cemented w/625 sacks (2 50 F-HD. PD 4:20 PM 2-21-81. Ran Temperature Surver emented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correctengineering SIGNED (TILE Secretary (This space for Federal or State of (2)) (This space for Federal or State of (2))	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & of mud & pull BP, packer & tubing. Shot casing off inulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6 6:30 PM 2-18-81, squeezed to 1750 psi, plug @6 howed weak indication of cement @5850'. WIH & po 10 w/400 bbls 10# brine. Cemented w/625 sacks (2 c-HD. PD 4:20 PM 2-21-81. Ran Temperature Surve mented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct SignED	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)
28-38' w/20 .34" holes (2 spf). Set RBP @7102' & 2 jts of 2-3/8" tubing. Swabbed well dry. Acid 1000 gal 15% DS-30. Swabbed back acid water & of mud & pull BP, packer & tubing. Shot casing off mulus unloaded. Killed well & circulated w/700 50 sacks Scavinger slurry, 500 sacks Class C w/3 6 6:30 PM 2-18-81, squeezed to 1750 psi, plug @4 howed weak indication of cement @5850'. WIH & po ended weak indication of cement @5850'. WIH & po ented w/400 bbls 10# brine. Cemented w/625 sacks (50 -HD. PD 4:20 PM 2-21-81. Ran Temperature Surve emented w/100 sacks Class C via 8-5/8 & 4-1/2 cas 500'. Pressure tested to 1500# okay. Ran Cement Subsurface Safety Valve: Manu. and Type 18. Thereby certify that the foregoing is true and correct Engineering SIGNED (1996) Society (1997) State of APPROVED BY CONDITIONS OF APPROVAL. IF ANY:	gun on wireline & perforated & Uni VI packer @7007' on dized perforations 7028-38' drilling mud. Circulated well @6950' and pulled 1 joint casing. bbls brine. Cemented 4-1/2 csg. 3# salt, .75% CF-9, .3% AF-HD. 6800'. Temperature Survey erforated 4 holes at 3000'. Circulated Class C, 1% CF-2, 3% CaCl2 & .3% ey & found top of cement at 1605'. sing. Drl'd out & cleaned hole to t Bond log. (cont'd)