NO. OF COPIES RECEIVED	3				Form C-103
DISTRIBUTION			RECE	IVED	Supersedes Old
ANTA FE	1	NEW MEXICO OIL CONS			C-102 and C-103 Effective 1-1-65
FILE	1.				
U.S.G.S.			JUN 9	1977	5a. Indicate Type of Lease
LAND OFFICE					State X Fee
OPERATOR	1		0. C	r.	5. State Oil & Gas Lease No.
			ARTESIA,		K-6774
(DO NOT USE THIS F	SUNDRY	NOTICES AND REPORTS ON DEALS TO DRILL OR TO DEEPEN OR PLUG B. N FOR PERMIT (FORM C-101) FOR SUC	WELLS	T RESERVOIR.	
OIL GAS	L X	OTHER-			7. Unit Agreement Name
Name of Operator			······································	• • ••••••	8. Farm or Lease Name
Coqui	Bass State				
. Address of Operator	9. Well No.				
Ρ.Ο.	Drawer 2	960, Midland, Texas 79	702		۱ ^۲ ۳
Location of Well	10. Field and Pool, or Wildcat				
UNIT LETTERE	Undesignated				
THE West	LINE, SECTION	32 TOWNSHIP 19-S			
	12. County				
	1111111	3280' Gr.			Eddy
16.	Check A	ppropriate Box To Indicate N	ature of Notic	ce. Report or Ot	her Data
NOTI	T REPORT OF:				
PERFORM REMEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
TEMPORARILY ABANDON	_		COMMENCE DRILL	ING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND		
			OTHER Pr	<u>ogress Report</u>	: X
OTHER		[]		-	
		rations (Clearly state all pertinent deta			

2-12-77, Drilled a 12 1/4"hole to 3330'. Ran 8 5/8" csg. to 3054'. Csg. would not go any deeper and would not be pulled. Ran free point. Csg. was 100% stuck at 2900', partially stuck at 2850' and 100% free at 2840'. Perforated 4 holes from 2950' to 2953'. Set 8 5/8" squeeze cementing retainer at 2920'. Cemented below retainer w/150 sxs class "C". Shot 4 holes from 2800' to 2803'. Set 8 5/8" squeeze cementing retainer at 2750'. Started cementing w/155 sxs. Pressure increased to 3000 psi. Reversed out 102 sxs cement. Drilled a 7 7/8" hole to 6241'. Had circulation outside 8 5/8" csg. and inside 13 3/8" csg. Cemented 13 3/8" x 8 5/8" annulus w/1000 sxs cement. Had good circulation throughout. Top of cement behind 8 5/8" was at 270'. WIH w/bit to 102', 8 5/8" csg. parted at 102'. Welded on 8 5/8" lift nipple. POOH w/3 joints of 8 5/8" csg. Made inside cut on 8 5/8" csg. at 152'. Recovered 50' of 8 5/8" csg. using a center spear. WIH w/Bowen csg. bowl on 4 jts. of 8 5/8" csg. Ran 1" tbg. behind 8 5/8" csg. to 300'. Pumped 150 sxs cement w/no returns. Waited on cement for 3 1/2 hrs. Reran 1" to 300'. Pumped 500 sxs w/no returns. Ran 1" tbg. to 300'. Pumped 300 sxs cement. Got returns inside 8 5/8" csg. Pulled 1". Waited on cement 2 hrs. Ran 1" tbg. to 300'. Pumped 200 sxs cement. Got good returns inside 8 5/8" csg. Ran wireline inside 8 5/8" csg. to 529'. WIH w/bit. Stopped at 531'. Milled and worked through bad 8 5/8" csg. Ran 3351' of 7" 26# N-80 crossline and cemented w/ 350 sxs. Top of cement was at 700'. Cemented through bradenhead w/150 sxs cement. PU 3 1/2" drill pipe. Drilled 6 1/8" hole to total depth of 11,500'. CONTINUED ON BACKSIDE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

IGNED	C alon Bump	Engineering Assistant	DATE 6-1-77
APPROVED BY	For Record Caly	TITLE SUPERVISOR, DISTRICT II	JUN 1 0 1977
	s of approval, if any:	TITLE SUPERVISOR, DISTRICT II	JUN 1 0 197

By the attached temperature survey the top of the cement between the 8 5/8" & 13 3/8" after pumping the initial 1000 sxs of class "C" was picked at 270'. By looking at this survey it can be seen that the top could be anywhere from 270' to 300'. It took an additional 1150 sxs of Class "C" with 2726# Lodense, 7800# gilsonite, 425# Cello flake and 500# of CaCl₂ to cement this annulus using 1" tbg. down the 8 5/8" x 13 3/8" annulus. It is apparant that at least one and possibly more than one hole was present in the 8 5/8" from the top of the casing bowl at 152' to top of the cement at 300'. This allowed cement down the 13 3/8" x 8 5/8" annulus into the 8 5/8" csg. This accounts for the excessive amount of cement needed to fill up from 300' back to the surface.

Summary:

- 1. 8 5/8" Intermediate casing stuck. Casing became parted in several places.
- 2. Cleaned out inside parted 8 5/8" casing.
- 3. Ran 7" protective string inside 8 5/8" casing and cemented to surface.