

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised June 10, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-36536
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> P
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lou Wortham
8. Well Number 9
9. OGRID Number 215758
10. Pool name or Wildcat Eunice, San Andres South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Pecos Production Company

3. Address of Operator
400 W. Illinois, Suite 1070, Midland, TX 79701

4. Well Location

Unit Letter C : 330' feet from the North line and 2240' feet from the West line

Section 11 Township 22S Range 37E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3357' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ADD PAY TO UPPER SAN ANDRES PERFS ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Hot-oil well & flowline one day prior to WO.

2. MIRU. POOH w/rods & pump. Install BOP's. Release TAC & POOH w/2-7/8" tbg.

3. Perforate Upper San Andres w/1 SPF at 3883', 85', 87', 88', 3905', 07', 09', 11', 29', 31', 33', 35', 37', 39', 41', 54', 62', 64', 67', 69', 72', 74', 76', 78', 80', 82', 84', 91', 93' (30 - .43" holes).

4. TIH w/ 5-1/2" treating pkr & RBP on 2-7/8" tbg to 4020'. Set RBP, set pkr at 4005' & test to 1500 psi. PU & reset pkr at 3800'.

5. Ball out perforations w/approximately 7000 gal HOT 15% CCA acid. Swab back rest of day.

6. TOOH w/pkr & RBP. Run tbg, pmp & rods, PWOP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dora Lara TITLE Engr Asst DATE 4/07/04

Type or print name Dora Lara

E-mail address: dorab@pecosproduction.com

Telephone No. 432-620-8480

(This space for State use)

APPROVED BY Larry W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 15 2004
Conditions of approval, if any: