Submit 3 Copies To Appropriate District Office		New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals	and Natural Resourc	es WELL API NO.	March 4, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV	ATION DIVISIO	N 30-025-00647	
District III 1000 Rio Brazos Rd., Aztec, NM 87410		n St. Francis Dr.	5. Indicate Type STATE	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe	e, NM 87505	6. State Oil & C	
SUNDRY NOT	ICES AND REPORTS O	N WELLS	7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				MCA Unit
1. Type of Well: Oil Well 🛛 Gas Well 🗌	Other		8. Well Number	79
2. Name of Operator	Atta: Calasta Dala		9. OGRID Num	ber <b>217817</b>
3. Address of Operator	Attn: Celeste Dale	· · · · · · · · · · · · · · · · · · ·	10. Pool name o	or Wildcat
	essa, Texas 79762		Maljamar; Gra	yburg-San Andres
4. Well Location Unit LetterI:660	feet from the	<b>East</b> line and _	1980feet from th	e South line
Section 23	Township <b>17S</b>	Range 32E	NMPM Cou	nty Lea
	11. Elevation (Show wh	hether DR, RKB, RT, G		
Pit or Below-grade Tank Application (Fo	r pit or below-grade tank closu	ires, a form C-144 must be	attached)	
Pit Location: UL_I_Sect_23_Twp_1	7S_Rng_32E Pit typeSt	eelDepth to Groundwate	er70'Distance from neare	st fresh water well <u>2-1/2 mile</u>
Distance from nearest surface water <u>2-1/2</u>	mile. Below-grade Tank Loca	ution ULSect	TwpRng;	
feet from theline and	feet from the	_line		Using Steel Pit
12. Check A         NOTICE OF IN         PERFORM REMEDIAL WORK         TEMPORARILY ABANDON         PULL OR ALTER CASING		REMEDIAL     COMMENC     CASING TE	SUBSEQUENT RE WORK	
	COMPLETION	CEMENT J	OB	- <b></b>
OTHER: 13. Describe proposed or compl	leted operations. (Clearly	state pertinent details	and give pertipent dates	including estimated date of
starting any proposed work)	). SEE RULE 1103. For M	Aultiple Completions: A	Attach WBD of proposed	completion? recompletion.
See Attached plugging pro	DOCEDURE. PLUGCIN IO BE A	MMISSION MUST BE PRICE TO THE BO IG OPERATIONS FO NPPROVED.	GINNING OF	Approved the second sec
I hereby certify that the information a grade tank has been/will be constructed or a	above is true and complete closed according to NMOCD g	e to the best of my know guidelines  , a general per	wledge and belief. I furth mit 🗋 or an (attached) alteri	er certify that any pit or below- native OCD-approved plan [].
SIGNATURE Im Alb			eer Technician DATI	
			Ditti	
Type or print name Tim L. Chas	e E-mail	address: Jim@Tripler	Services.com Telepho	one No. (432) 570-0029
(This space for State use)				
APPPROVED BY Laug W.U.	July T	IDICE FIELD REPRESEN	TATIVE II/STAFF MAN	ADATE
Conditions of approval, if any:			NTATIVE II/STAFE MAN	JUN 2 2 2004
		1. The tange in Alaska and the second		

CURRENT WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit





## **ConocoPhillips**

## **Proposed Plugging Procedure**

MCA Unit #79 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

## See attached wellbore diagrams for wellbore configuration

TA'd (06/99) w/ CICR (no cement cap) @ 3,660'; 5½" casing @ 3,712' w/ isolated Open Hole 3,712 – 4,227';

- Notify OCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. Deliver 3,500' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- 3. RIH w/ workstring, tag CICR @ 3,660'. Circulate hole w/ plugging mud and pump 25 sx C cement on CICR to 3,560'. POOH w/ workstring. **GBSA Plug**
- 4. RU lubricator and RIH w/ wireline, perforate 5<sup>1</sup>/<sub>2</sub>" casing w/ four 1-11/16" link-jet perforating gun @ 1,700'. POOH w/ wireline, RD lubricator.
- 5. RIH w/ 5½" AD-1 packer. Circulate hole w/ plugging mud and pump 35 sx C cement @ 1,700 1,600'. **Base of Salt Plug WOC & TAG.** POOH w/ tubing.
- 6. RU lubricator and RIH w/ wireline, perforate 5<sup>1</sup>/<sub>2</sub>" casing w/ four 1-11/16" link-jet perforating gun @ 850'. POOH w/ wireline, RD lubricator.
- RIH w/ 5½" AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 35 sx C cement w/ 2% CaCl2 @ 850 750'. Top of Salt Plug WOC & TAG. POOH w/ tubing.
- 8. RU lubricator and RIH w/ wireline, perforate 5<sup>1</sup>/<sub>2</sub>" casing w/ four 1-11/16" link-jet perforating gun @ 50'. POOH w/ wireline, RD lubricator.
- 9. ND wellhead and NU BOP, establish circulation and circulate 25 sx C cement 50' to surface. *Surface Plug*
- 10. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

-> 5 POT 100' PLUG F/400'-300' FW

## PROPOSED WELLBORE SKETCH ConocoPhillips Company – Permian Basin Business Unit

