Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-08046 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE STATE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505	 6. State Oil & Gas Lease No. 029405A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	MCA Unit
1. Type of Well: Oil Well Gas Well Other	8. Well Number 56
2. Name of Operator ConocoPhillips Company Attn: Celeste Dale	9. OGRID Number 217817
3. Address of Operator4001 Penbrook StreetOdessa, Texas 79762	10. Pool name or Wildcat
4. Well Location	Maljamar; Grayburg-San Andres
Unit Letter L : _660 feet from theWest line and1980 feet from the line	
Section 19 Township 17S Range 32E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL_L_Sect_19_Twp_17S_Rng_32E_ Pit typeSteel_Depth to Groundwater_70'_Distance from nearest fresh water well <u>1-1/2 mile</u>	
Distance from nearest surface water <u>1-1/2 mile</u> . Below-grade Tank Location ULSectTwpRng;	
feet from theline andfeet from theline	(Using Steel Pit.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
PULL OR ALTER CASING I MULTIPLE CASING TEST AL COMPLETION CEMENT JOB	ABANDONMENT
13. Describe proposed or completed operations. (Clearly state pertinent details, and give pertinent dates' including estimated date of	
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach WBD of proposed completion / recompletion.	
See Attached plugging procedure. THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].	
SIGNATURE Im Hhan TITLE Senior Engineer Te	
	DITL 0/14/04
Type or print name Tim L. Chase E-mail address: Jim@TriplenServices.com Telephone No. (432) 570-0029	
(This space for State use)	JUN 2 2 2004
APPPROVED BY COMPANY AND APPPROVED BY COMPACT AND APPPROVED BY COMPACT AND A APPROVED BY COMPACT AND A APPROVED BY COMPACT AND A APPPROVED BY COMPACT AND A APPROVED BY COMPACT AND A APPROVED BY COMPACT AND A APPPROVED BY COMPACT AND A APPROVED BY COMPACT AND APPROVED BY COMPA	NIATIVE II/STAFF MANAGER

A. S. S. L. LANDERSON MANAGEMENT AND A CONTRACT DOTATION OF A DESCRIPTION OF A DESCRIPTI و و مده د مدهد و علو دو معطو و در در

CURRENT WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: May 16, 2004





ConocoPhillips

Proposed Plugging Procedure

MCA Unit #56 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

TA'd (06/96) w/ CICR (no cement cap) @ 3,492'; 4¹/₂" casing @ 3,567' w/ isolated Open Hole 3,567 – 3,998';

- Notify OCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 5¹/₂" scab liner @ 3,369 3,556' w/ 15 sx (10/46) to shut-off gas
- Possible tight spots in $4\frac{1}{2}$ " casing @ 2,934 3,399'
- 1. Set steel pit and flow down well as needed. Deliver 3,500' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- **3.** RIH w/ workstring, tag CICR @ 3,492'. Circulate hole w/ plugging mud and pump 45 sx C cement on CICR to 2,850' to cover top of 4½' casing collapse. Test 4½'' casing to 500 psi for 30 minutes. If casing does not test, isolate holes in casing. **GBSA Plug**
- 4. PUH w/ workstring to 2,015'. Circulate hole w/ plugging mud and pump 25 sx C cement @ 2,015 1,915'. Base of Salt Plug WOC & TAG. POOH w/ tubing.
- 5. RU lubricator and RIH w/ wireline, perforate 4¹/₂" casing w/ four 1-11/16" link-jet perforating gun @ 775'. POOH w/ wireline, RD lubricator.
- RIH w/ 4½" AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 50 sx C cement w/ 2% CaCl2 @ 775 620'. Casing Shoe/Top of Salt Plug WOC & TAG. POOH w/ tubing.
- 7. RU lubricator and RIH w/ wireline, perforate 4¹/₂" casing w/ four 1-11/16" link-jet perforating gun @ 50'. POOH w/ wireline, RD lubricator.
- 8. ND wellhead and NU BOP, establish circulation and circulate 25 sx C cement 50' to surface. *Surface Plug*
- 9. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

> SPOT 100'PLUG F/400'-300' FW

PROPOSED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

