€.		
Office	New Mexico	Form C-103
District I Energy, Minerals	and Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-08061
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERV	ATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd Azteo NM 87410	St. Francis Dr.	STATE 🛛 FEE 🗌
District IV Santa Fe 1220 S. St. Francis Dr., Santa Fe, NM	, NM 87505	6. State Oil & Gas Lease No.
87505		029405A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		MCA Unit
PROPOSALS.) 1. Type of Well:		8. Well Number 24
Oil Well Gas Well Other M Injector		
2. Name of Operator		9. OGRID Number 217817
ConocoPhillips Company Attn: Celeste Dale		
3. Address of Operator4001 Penbrook StreetOdessa, Texas 79762		10. Pool name or Wildcat Maljamar; Grayburg-San Andres
4. Well Location		
Unit Letter \mathcal{E} : 660 feet from the North line and 1980 feet from the East line		
Section 20 Township 17S		
	ether DR, RKB, RT, GR, etc	<u>NMPM</u> County Lea
GL 4,012'		
Pit or Below-grade Tank Application (For pit or below-grade tank closu		
Pit Location: UL_C_Sect_20_Twp_17S_Rng_32E_Pit type_Steel_Depth to Groundwater_70'_Distance from nearest fresh water well 1-1/2 mile. Distance from nearest surface water 1-1/2 mile Below-grade Tank Location UL_Sect_Twp_Rng_;		
feet from theline andfeet from the	_line	Using Steel Pit
 Check Appropriate Box to Ind NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Describe proposed or completed operations. (Clearly starting any proposed work). SEE RULE 1103. For M See Attached plugging procedure. THE COMMI HOURS PRICE 	SUI REMEDIAL WO COMMENCE DF CASING TEST A CEMENT JOB OTHER: state pertinent details, and g fultiple Completions: Attack	BSEQUENT REPORT OF: RK ALTERING CASING ALTERING CASING ABANDONMENT AND ABANDONMENT Strep perturbent dates, including estimated date of the WBD of proposed completion. ED 24 8557
PLUCEING OPERATIONS FOR THE C-103 20 TO BE APPROVED.		
grade tank has been/will be constructed or closed according to NMOCD g	uidelines [], a general permit [or an (attached) alternative OCD-approved plan
SIGNATURE Im A Chan I	TTLE Senior Engineer 7	Cechnician DATE 6/10/04
Type or print name Tim L. Chase E-mail	address: Jim@TriplenServ	vices.com Telephone No. (432) 570-0029
(This space for State use)		
APPPROVED BY Conditions of approval if any	CHELD REPRESENT	DATE JUN 2 2 2004
APPPROVED BY DATE JUN 2 2 2004 Conditions of approval, if any		

Þ.

CURRENT WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: May 16, 2004





ConocoPhillips

Proposed Plugging Procedure

MCA Unit #24 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

TA'd (12/94) w/ $4\frac{1}{2}$ " OTIS Interlock Packer w/ plug @ 3,635'; $4\frac{1}{2}$ " casing perf'd & sqzd @ 650' w/ 240 sx cmt to repair csg leak 06/73. All perfs (3,709 – 3,764') are isolated.

- Notify OCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. Deliver 3,635' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- 3. RIH w/ workstring, tag packer @ 3,635'. Circulate hole w/ plugging mud and pump 25 sx C cement on packer to 3,535'. POOH w/ tubing. *GBSA Plug*
- **4.** RU lubricator and RIH w/ wireline, perforate 4½" casing w/ four 1-11/16" link-jet perforating gun @ 1,930'. POOH w/ wireline, RD lubricator.
- RIH w/ AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 35 sx C cement w/ 2% CaCl2 @ 1,930 1,830'. Base of Salt Plug WOC & TAG. POOH w/ tubing.
- 6. RU lubricator and RIH w/ wireline, perforate 4¹/₂" casing w/ four 1-11/16" link-jet perforating gun @ 1,000'. POOH w/ wireline, RD lubricator.
- RIH w/ AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 70 sx C cement w/ 2% CaCl2 @ 1,000 – 798'. Top of Salt Plug / Casing Shoe – WOC & TAG. POOH w/ tubing.
- 8. RU lubricator and RIH w/ wireline, perforate 4¹/₂" casing w/ four 1-11/16" link-jet perforating gun @ 50'. POOH w/ wireline, RD lubricator.
- 9. ND wellhead and NU BOP, establish circulation and circulate 25 sx C cement 50' to surface. *Surface plug*
- **10.** Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

-7 JPOT 100' PLUG F/400-300' FRESH WATER

PROPOSED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

