STATE OF NEW MEXICO

Submit 3 Copies to Appropriate District Office

Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

OIL CONSERVATION DIVISION

	2040 Pacheco St.	177	LL API NO.	1 I
P.O. Box 1980, Hobbs, NM 88240	Santa Fe, NM 87505		30-025-08007	
		[5. lr	ndicate Type of Lease	
DISTRICT II P.O. Drawer DD, Artesia, NM 888210		6.5	STATE x F state Oil & Gas Lease No.	EE
P.O. DIAWELDD, AILESIA, NM 500210		0.0	O a Odo Loddo 140.	
DISTRICT III				
1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS				
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS)			ease Name or Unit Agreement I	Name
DIFFERENT RESERVOIR. USE "A		CIOX		
(FORM C-101) FOR S			New Mexico State BH NCT 1	
Type of Well:				-
	GAS OTHE	١ .		Ī
2. Name of Operator Paladin Ene			Well No.	
3. Address of Operator 10290 Monroe Dr., Ste. Ste 301, Dallas, TX 75229		75229 9. 1	9. Pool name or Wildcat	
4 Well Location			Caprock, East Pennsylvanian	
	entern The Marth ()	1000	Fact from The \\Atach	Line
Unit Letter C : 660 F	eet From The North Line a	k <u>1980</u> I	Feet from The West	Line
			,	
	ownship 12-S Range		имри Lea	County
English Commence of the Commen	levation (Show whether DF,RKE	, RT, GR, etc)		
	4371'	601.41 5 4	2.24 / 5 %	<u> </u>
	riate Box to Indicate Nature			
		,	SEQUENT REPORT	
	PLUG AND ABANDON REMEDIAL WOR			ैं । हैं ह
	CHANGE PLANS	COMMENCE DRLG OF	1 1 1 1	ر وعهر
PULL OR ALTER CASING				
OTHER		OTHER: Perforate Pen	V 674	<u>x</u>
 Describe Proposed or Completed Operations (date of starting any proposed work) SEE RULI 		give pertinent date, incl	luding estimated	18181
Work performed from: 3/18/2004 to 5/18				
•				
1 Cut & pull 5-1/2" casing at 3564', GIH w/		k 5-1/2" to surface.	N/U csg. Pressure test-	OK.
1 Cut & pull 5-1/2" casing at 3564'. GIH w/ 2 Set CIBP at 10,400', isolate Devonian, Pe	5-1/2 Bowen Casing Patch, tie bad			
•	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga	al HCL, Swab back 8	k test Penn formation. N	o flow.
2 Set CIBP at 10,400', isolate Devonian, Pe	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga	al HCL, Swab back 8	k test Penn formation. N	o flow.
 Set CIBP at 10,400', isolate Devonian, Person Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. Set CIBP at 9,890', Perf 9820' to 9880',a 	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 nd 9680' to 9770', Acidize w/ 5000	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te	& test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow	o flow. & test
 Set CIBP at 10,400', isolate Devonian, Personal Set CIBP at 10,190', Performation 10,130' to 10,1 Penn formation. No flow. Set CIBP at 9,890', Performation 9880', at 5 Set CIBP at 9,650', Performation 9570' to 9590', 9 	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 nd 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350	al HCL., Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g	o flow. & test all HCL,
 Set CIBP at 10,400', isolate Devonian, Person Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. Set CIBP at 9,890', Perf 9820' to 9880',a 	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 nd 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350	al HCL., Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g	o flow. & test all HCL,
 Set CIBP at 10,400', isolate Devonian, Personal Set CIBP at 10,190', Performation 10,130' to 10,1 Penn formation. No flow. Set CIBP at 9,890', Performation 9880', at 5 Set CIBP at 9,650', Performation 9570' to 9590', 9 	5-1/2 Bowen Casing Patch, tie bacerf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to expend to 10,000 for the second seco	al HCL., Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g	o flow. & test all HCL,
 2 Set CIBP at 10,400', isolate Devonian, Person Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', a Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of set of the se	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to evolute to the best of my knowledge and belief.	al HCL., Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 9320' , Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
 Set CIBP at 10,400', isolate Devonian, Person Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. Set CIBP at 9,890', Perf 9820' to 9880', a Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of the set Penn perfs. 	5-1/2 Bowen Casing Patch, tie bacerf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to expend to 10,000 for the second seco	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
2 Set CIBP at 10,400', isolate Devonian, Per 3 Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', a 5 Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of graduate the street of	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to evaluate to the best of my knowledge and belief.	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
2 Set CIBP at 10,400', isolate Devonian, Per 3 Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', a 5 Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of graph of the structure of the supplies o	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to evolute to the best of my knowledge and belief.	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
2 Set CIBP at 10,400', isolate Devonian, Per 3 Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', a 5 Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of graduate the street of	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to evaluate to the best of my knowledge and belief.	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 320', Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
2 Set CIBP at 10,400', isolate Devonian, Per 3 Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', a 5 Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of graph of the structure of the supplies o	5-1/2 Bowen Casing Patch, tie bac erf 10,200-250', Acidize w/ 5000 ga 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to evaluate to the best of my knowledge and belief.	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	k test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g frac in present Penn per	o flow. & test gal HCL, fs.
2 Set CIBP at 10,400', isolate Devonian, Per 3 Set CIBP at 10,190', Perf 10,130' to 10,1 Penn formation. No flow. 4 Set CIBP at 9,890', Perf 9820' to 9880', at 5 Set CIBP at 9,650', Perf 9570' to 9590', 9 Swab & test Penn perfs, - slight blow of graph of the street o	5-1/2 Bowen Casing Patch, tie bacerf 10,200-250', Acidize w/ 5000 gas 50', 10,090' to 10,110' and 10,060 and 9680' to 9770', Acidize w/ 5000 534' to 9554', 9390' to 9410', 9350 gas, trace of oil. Well Shut-in to endete to the best of my knowledge and belief.	al HCL, Swab back & ' to 10,080', Acidize gal HCL, Swab & te ' to 9378', 9280' to 9 raluate for possible t	test Penn formation. N w/ 5000 gal HCL, Swab est Penn perfs, - no flow 0320', Acidize w/ 5000 g frac in present Penn per DATE 6/23/20 214-6	o flow. & test gal HCL, fs.