Form 3160-5 (September 2001)

## 1625 N. French Drive UNITED STATES Hobbs, NM 88240 DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires January 31, 2004

NMLC-030556(B)

5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS


Do not use this	form for proposals to drill or to re-enter an
abandoned well.	Use Form 3160-3 (APD) for such proposals.
	to such proposals.

6. If Indian, Allottee or Tribe Name

				N/A
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No. N/A	
1. Type of Well			<del></del>	- MA
Oil Well X Gas Well Other  2. Name of Operator				8. Well Name and No. STEVENS B-15 NO.2
MISSION RESOURCES CORPORATION				
3a. Address		2h Dhanabta (* 1.1		9. API Well No.
<del> </del>	3b. Phone No. (include area code) 30-025-10731		30-025-10731	
1331 LAMAR. SUITE 1455 HOUSTON. TEXAS 77010-3039 713-495-3000  4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area
2 - 25	-			JALMAT; TAN-YATES-7RVRS (GAS)
1650' FSL & 1650' FWL OF SECTION 1	5, 123S-R36E			
				11. County or Parish, State
041, 0111		· · · · · · · · · · · · · · · · · · ·		LEA COUNTY, NM
CHECK APPROPRIATE	BOX(ES) TO INC	DICATE NATURE OF	NOTICE, REP	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production	n (Start/Resume) Water Shut-Off
Subsequent Report	Alter Casing	Fracture Treat	Reclamati	ion Well Integrity
Succeptant Report	Casing Repair	New Construction	Recomple	<u></u>
Final Abandonment Notice	Change Plans	X Plug and Abandon	Temporar	ily Abandon
	Convert to Injectio	on Plug Back	Water Dis	sposal
3. Describe Proposed or Completed Operation (clearly	state all pertipent detail	ls including estimated starti	ng data of any	

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleteion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final cite is ready for final inspection.) determined that the final site is ready for final inspection.)

PLEASE FIND ENCLOSED THE PLUG & ABANDONMENT PROCEDURE WITH CURRENT & PROPOSED WELLBORE SCHEMATICS.



14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title			
Nancy K. Gatti	Regulatory Coordinator			
Money K Statts	Date 07/21/04			
THIS SPACE FOR	FEDERAL OR STATE OFFICE USE			
Approved by	Title	Date		
Conditions of approval, if any, are attached. Approval of this notice does recrtify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon.	not warrant or Office e subject lease			

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Mission Resources Corp. Stevens B-15 #2 Jalmat Field Lea County, NM July 21, 2004

## **Plugging and Abandonment Procedure**

- 1. Set CIBP at 2900' and dump bail 35' of cement on top.
- 2. Load hole with gelled 10# brine.
- 3. Mix and pump 100' cement plug from 1360' to 1260'.
- 4. Perforate 5-1/2" casing at 245'.
- 5. Squeeze perfs @ 245' and circulate to surface with 150 sxs cement.
- 6. Cut off wellhead weld on P&A marker.
- 7. Clean off location for OCD inspection.

