Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-20160
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		E-6704
87505 SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	TION FOR PERMIT" (FORM C-101) FOR SUCH	Vacuum Abo Unit Battery 1 Tract 15
	Sas Well 🔲 Other	8. Well Number 04
2. Name of Operator		9. OGRID Number
	ips Company	10. Pool name or Wildcat
3. Address of Operator 4001 Penbro	ook Street Odessa, Texas 79762	Vacuum Abo Reef
4. Well Location		
	1,650 feet from the North line and	330 feet from the West line
Section 8	Township 18-S Range 35-E	
	11. Elevation (Show whether DR, RKB, RT, GR,	
	3,971' RKB	
Pit or Below-grade Tank Application 🗌 or		
· · · · · · · · · · · · · · · · · · ·	ter_78" Distance from nearest fresh water well_N/A_	
Pit Liner Thickness: steel mil	Below-Grade Tank: Volume <u>180</u> ppropriate Box to Indicate Nature of Notic	Construction Materialsteel
	PLUG AND ABANDON A REMEDIAL W CHANGE PLANS COMMENCE	ORK ALTERING CASING DRILLING OPNS. P AND A
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completing the second		DRILLING OPNS. P AND A C ENT JOB C , and give pertinent dates, including estimated date
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion or recompletion.	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: eted operations. (Clearly state all pertinent details, k). SEE RULE 1103. For Multiple Completions: re diagrams and plugging procedure	DRILLING OPNS. P AND A ENT JOB .
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion or recompletion.	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: eted operations. (Clearly state all pertinent details, k). SEE RULE 1103. For Multiple Completions:	DRILLING OPNS. P AND A ENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. See attached wellbox	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: eted operations. (Clearly state all pertinent details k). SEE RULE 1103. For Multiple Completions: re diagrams and plugging procedure THE COMMISSION MUST BE NOT HOURS PRIOR TO THE BEGINNIN PLUGGING OPERATIONS FOR THE	DRILLING OPNS. P AND A ENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. See attached wellbox	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: ted operations. (Clearly state all pertinent details, k). SEE RULE 1103. For Multiple Completions: re diagrams and plugging procedure THE COMMISSION MUST BE NOTH HOURS PRIOR TO THE BEGINNIN PLUGGING OPERATIONS FOR THE TO BE APPROVED. bove is true and complete to the best of my knowl losed for only a general permit	DRILLING OPNS. P AND A ENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. See attached wellbox See attached wellbox I hereby certify that the information a grade tank has been/will be constructed or completion	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: ted operations. (Clearly state all pertinent details, k). SEE RULE 1103. For Multiple Completions: re diagrams and plugging procedure THE COMMISSION MUST BE NOTH HOURS PRIOR TO THE BEGINNIN PLUGGING OPERATIONS FOR THE TO BE APPROVED. bove is true and complete to the best of my knowl losed for only a general permit	DRILLING OPNS. P AND A ENT JOB
TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. See attached wellbox	CHANGE PLANS COMMENCE MULTIPLE COMPL CASING/CEM OTHER: ted operations. (Clearly state all pertinent details, k). SEE RULE 1103. For Multiple Completions: re diagrams and plugging procedure THE COMMISSION MUST BE NOTH HOURS PRIOR TO THE BEGINNIN PLUGGING OPERATIONS FOR THE TO BE APPROVED. bove is true and complete to the best of my knowl losed for only a general permit	DRILLING OPNS. P AND A ENT JOB

h

WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit





ConocoPhillips

Proposed Plugging Procedure

Vacuum Abo Unit #15-04 Vacuum Abo Field Section 8, T18S, R35E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI producer

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- Test rig anchors if last test over 2 years old
- 1. Set steel pit and flow well down as needed.
- 2. MIRU plugging equipment. *ND wellhead and NU 6" 5,000# hydraulic BOP.
- RIH w/ 2³/₄" workstring to CIBP @ 8,750'. RU cementer and circulate hole w/ 150 bbls plugging mud. Pump 25 sx C cmt on CIBP 8,750 8,500'. POOH w/ tbg to 6,767'. Abo plug
- 4. Pump 25 sx C cmt 6,767 6,514'. POOH w/ tbg to 4,802'. Glorieta plug
- 5. Pump 25 sx C cmt 4,802 4,550'. POOH w/ tbg to 3,313'. San Andres plug
- 6. Pump 25 sx C cmt 3,313 3,060'. POOH w/ tbg. Intermediate casing shoe plug
- 7. RU lubricator and RIH w/ wireline, perforate casing @ 2,974'. POOH w/ wireline.
- RIH w/ AD-1 packer to 2,600'. Load hole, set packer, and establish rate into squeeze perforations. Squeeze 40 sx C cmt w/ 2% CaCl₂ 2,974 2,874'. If unable to establish rate at 1,000 psi or less, pump 25 sx C cmt balanced plug minimum 50' below perforations. WOC and tag this plug no deeper than 2,874'. base of salt plug
- 9. RU lubricator and RIH w/ wireline, perforate casing @ 1,673'. POOH w/ wireline.
- 10. RIH w/ AD-1 packer to 1,400'. Load hole, set packer, and establish rate into squeeze perforations. Squeeze 40 sx C cmt w/ 2% CaCl₂ 1,673 1,573'. If unable to establish rate at 1,000 psi or less, pump 25 sx C cmt balanced plug minimum 50' below perforations. WOC and tag this plug no deeper than 1,573'. top of salt plug
- 11. RU lubricator and RIH w/ wireline, perforate casing @ 356'. POOH w/ wireline.

- 12. RIH w/ AD-1 packer to 120'. Load hole, set packer, and establish rate into squeeze perforations. Squeeze 40 sx C cmt w/ 2% CaCl₂ 356 256'. If unable to establish rate at 1,000 psi or less, pump 25 sx C cmt balanced plug minimum 50' below perforations. WOC and tag this plug no deeper than 256'. Surface casing shoe plug
- **13.** RIH w/ wireline, perforate casing @ 50'. POOH w/ wireline.

14. ND BOP and NU wellhead. Establish circulation in 5½ x 8%" annulus and circulate 30 sx C cmt 50' to surface. **surface plug**

15. SI well. RDMO. Clean steel pit and dispose of bottoms.

16. Cut off wellhead and anchors, level location. Leave location clean and free of trash.

PROPOSED PLUGGED WELLBORE SKETCH

ConocoPhillips Company - Permian Basin Business Unit

Date: August 24, 2004 RKB @ _____3,971' DF @ GL@______3,960' Subarea : Buckeye Vacuum Abo Unit #15-04 Lease & Well No. : 1,650' FNL & 330' FWL, Section 8, T-18-S, R-35-E Legal Description : 30 sx C cmt 50' to surface, perf & sqz County : Lea State : New Mexico Field : Vacuum Abo Reef Date Spudded : December 12, 1962 (PP) 13-3/8" 35.6# @ 306' w/ 320 sx, circ, API Number : 30-025-20160 Status: Temporarily Abandoned 40 sx C cmt 356 - 256', perf & sqz WOC & TAG Formation Tops: Yates 3,002 Seven Rivers 3,363 4,019 Queen Grayburg 4,446 San Andres 4,802 40 sx C cmt 1,673 - 1,573', perf & sqz Glorieta 6 767 WOC & TAG 8,683 Abo Top of Salt @ 1,673' -TRIPLE N **PROPOSED PLUGS** MICLAND, TX 40 sx C cmt 2,974 - 2,874', perf & sqz, WOC & TAG 1) 25 sx C cmt 8,750 - 8,500' Base of Salt @ 2,874' 2) 25 sx C cmt 6,767 - 6,514 TOC 3,188' T.S. 3) 25 sx C cmt 4,802 - 4,550' 8-5/8" 32# @ 3,263' w/ 1,200 sx 4) 25 sx C cmt 3,313 - 3,060' 5) 40 sx C cmt 2,974 - 2,874', perf & sqz, WOC & TAG 25 sx C cmt 3,313 - 3,060' ' 6) 40 sx C cmt 1,673 - 1,573', perf & sqz, WOC & TAG 7) 40 sx C cmt 356 - 256', perf & sqz, WOC & TAG 8) 30 sx C cmt 50' to surface, perf & sqz 25 sx C cmt 4,802 - 4,550' 25 sx C cmt 6,767 - 6,514' 25 sx C cmt 8,750 - 8,500' CIBP @ 8,750' (set 11/20/92) Abo Perforations 8 848 - 8 905 7-7/8" Hole 5-1/2" 17# @ 9,000' w/ 775 sx PBTD: 8.910 TD: 9,010