Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Re	esources May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIV	ISION 30-025-26179
District III	1220 South St. Francis D	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 c, 14141 07303	6. State Oil & Gas Lease No.
87505		B-10233
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BAC	
PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FOR SUC	State NN-12
	Gas Well Other	8. Well Number 6
2. Name of Operator		9. OGRID Number
	llips Company	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
3. Address of Operator		10. Pool name or Wildcat
4001 Penbr	ook Street Odessa, Texas 79762	Eumont Yates Seven Rivers Queen
4. Well Location		the state of the s
Unit Letter L :	1,980 feet from the South lin	ne and 660 feet from the West line
Section 12	Township 19-S Rang	
Section 12	11. Elevation (Show whether DR, RKB,	
	3,737' GL	KI, GK, etc.)
Pit or Below-grade Tank Application On		
		er well_3/8 mile_ Distance from nearest surface water_N/A
Pit Liner Thickness: STEEL mi	Below-Grade Tank: Volume180	bbls; Construction Material STEEL
12. Check A	ppropriate Box to Indicate Nature	of Notice, Report or Other Data
NOTICE OF IN		
NOTICE OF IN	1	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		EDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS ☐ COM	IMENCE DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING	MULTIPLE COMPL	ING/CEMENT JOB
	MULTIPLE COMPL CAS	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl	eted operations. (Clearly state all pertine	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl	eted operations. (Clearly state all pertine	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl	eted operations. (Clearly state all pertine	ING/CEMENT JOB ER:
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wo	eted operations. (Clearly state all pertine	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wo or recompletion.	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. SEE ATTACHED WELLBORI	OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com	ER: Int details, and give pertinent dates, including estimated date appletions: Attach wellbore diagram of proposed completion
PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. SEE ATTACHED WELLBORI	OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com	ING/CEMENT JOB
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Com E DIAGRAM Triple N rig #24, workstring, and plug	ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). N	OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 23%" workstring	ER:
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). No circulated hole w/ mud, pumped 2	OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 23%" workstring	ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notice of the circulated hole w/mud, pumped 2 POOH w/tbg and SDFN.	OTH eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 2½" workstring. 25 sx C cmt 2,670 – 2,422'. POOH w	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date appletions: Attach wellbore diagram of proposed completion agging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670°. RU cementer and / tbg to 1,583° and pumped 25 sx C cmt @ 1,583°.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia D.	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422'. POOH w. Dickey. RIH w/ tubing, tagged cmt @	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372°. NU wellhead	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 2¾" workstring and plug enviro-vat. RIH w/ 2½" workstring. S sx C cmt 2,670 – 2,422'. POOH we Dickey. RIH w/ tubing, tagged cmt @ l and circulated 45 sx C cmt 372' to si	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670°. RU cementer and / tbg to 1,583° and pumped 25 sx C cmt @ 1,583°. 1,366°. POOH w/ tubing. ND enviro-vat & BOP and prace. ND wellbead. POOH w/ that Toward off
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372°. NU wellhead	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 2¾" workstring and plug enviro-vat. RIH w/ 2½" workstring. S sx C cmt 2,670 – 2,422'. POOH we Dickey. RIH w/ tubing, tagged cmt @ l and circulated 45 sx C cmt 372' to si	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670°. RU cementer and / tbg to 1,583° and pumped 25 sx C cmt @ 1,583°. 1,366°. POOH w/ tubing. ND enviro-vat & BOP and prace. ND wellbead. POOH w/ that Toward off
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372°. NU wellhead	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422'. POOH we Dickey. RIH w/ tubing, tagged cmt @ I and circulated 45 sx C cmt 372' to state KP-13 #4. Approved as to plugging of	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670°. RU cementer and / tbg to 1,583° and pumped 25 sx C cmt @ 1,583°. 1,366°. POOH w/ tubing. ND enviro-vat & BOP and prace. ND wellbead. POOH w/ that Toward off
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422°. POOH we have a circulated 45 sx C cmt 372° to state KP-13 #4. Approved as to plugging of Liability under bond is retained.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date appletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg_2 topped off the Well Bore. Indicate the well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422'. POOH we Dickey. RIH w/ tubing, tagged cmt @ I and circulated 45 sx C cmt 372' to state KP-13 #4. Approved as to plugging of	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date appletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg_2 topped off the Well Bore. Indicate the well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422°. POOH we have a circulated 45 sx C cmt 372° to state KP-13 #4. Approved as to plugging of Liability under bond is retained.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date appletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg_2 topped off the Well Bore. Indicate the well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed was or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Noticulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23% workstring. S sx C cmt 2,670 – 2,422°. POOH we have a circulated 45 sx C cmt 372° to state KP-13 #4. Approved as to plugging of Liability under bond is retained.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and arrace. ND wellhead, POOH w/ tbg 2 topped off the Well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or compl of starting any proposed wor or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). No circulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia E RIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfil	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23%" workstring. S sx C cmt 2,670 – 2,422". POOH we have a circulated 45 sx C cmt 372" to state KP-13 #4. Approved as to plugging of Liability under bond is retailed cellar. surface restoration is comp	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and arface. ND wellhead, POOH w/ tbg 2 topped off f the Well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notificulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfill	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23/8" workstring. S sx C cmt 2,670 – 2,422'. POOH we have a circulated 45 sx C cmt 372' to state of the composition of the co	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and arrace. ND wellhead, POOH w/ tbg 2 topped off f the Well Bore.
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notificulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfill	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23/8" workstring and plug RU enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to state of the company o	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion Eging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off f the Well Bore. The W
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notificulated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfill	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug RU enviro-vat. RIH w/ 23/8" workstring and plug RU enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to state of the company o	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion Eging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off f the Well Bore. The W
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU Wellhead and NU BOP (D&L). Notified and NU BOP (D&L). Notified OCD, Sylvia ENTER Wellbore Words and SDFN. 10/05/04 Notified OCD, Sylvia ENTER Words to 372°. NU wellhead wellbore words complete or wellbore words. RDMO to State Cut off wellhead and anchors, backfill I hereby certify that the information and grade tank has been/will be constructed or starting any proposed words.	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come E DIAGRAM Triple N rig #24, workstring, and plug IU enviro-vat. RIH w/ 23/8" workstring. S sx C cmt 2,670 – 2,422'. POOH w. Dickey. RIH w/ tubing, tagged cmt @ I and circulated 45 sx C cmt 372' to state of the labelity under bond is retained cellar. Surface restoration is compared according to NMOCD guidelines A general places of the labelity. TITLE James F.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and arrace. ND wellhead, POOH w/ tbg 2 topped off the Well Bore. The Well Bore of the Well Bore of the Well Bore. The Well Bore of the Well Bore of the Well Bore. The Well Bore of the Well Bore of the Well Bore. The Well Bore of the Well Bore of the Well Bore of the Well Bore. The Well Bore of th
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU Wellhead and NU BOP (D&L). Notirculated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372°. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfill I hereby certify that the information a grade tank has been/will be constructed or of the starting and proposed work.	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come of the DIAGRAM Triple N rig #24, workstring, and plug right enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to sure and circulated 45 sx C cmt 372' to sure restoration is retained as the plugging of the Liability under bond is retained cellar. Surface restoration is compared according to NMOCD guidelines A, a general right environment.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion Eging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off f the Well Bore. The W
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU Wellhead and NU BOP (D&L). Notified and NU BOP (D&L). Notified OCD, Sylvia ENTER Wellbore Words and SDFN. 10/05/04 Notified OCD, Sylvia ENTER Words to 372°. NU wellhead wellbore words complete or wellbore words. RDMO to State Cut off wellhead and anchors, backfill I hereby certify that the information and grade tank has been/will be constructed or starting any proposed words.	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come of the DIAGRAM Triple N rig #24, workstring, and plug right enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to sure and circulated 45 sx C cmt 372' to sure restoration is retained as the plugging of the Liability under bond is retained cellar. Surface restoration is compared according to NMOCD guidelines A, a general right environment.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off the Well Bore. The Well
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notified and SDFN. 10/05/04 Notified OCD, Sylvia Described and SDFN. 1	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come of the DIAGRAM Triple N rig #24, workstring, and plug right enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to sure and circulated 45 sx C cmt 372' to sure restoration is retained as the plugging of the Liability under bond is retained cellar. Surface restoration is compared according to NMOCD guidelines A, a general right environment.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off the Well Bore. The Well
PULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. SEE ATTACHED WELLBORI 10/04/04 Notified OCD. MIRU wellhead and NU BOP (D&L). Notirculated hole w/ mud, pumped 2 POOH w/ tbg and SDFN. 10/05/04 Notified OCD, Sylvia ERIH w/ tbg to 372'. NU wellhead wellbore w/ cmt. RDMO to State Cut off wellhead and anchors, backfill I hereby certify that the information a grade tank has been/will be constructed or SIGNATURE Type or print name James F. N	eted operations. (Clearly state all pertine rk). SEE RULE 1103. For Multiple Come of the DIAGRAM Triple N rig #24, workstring, and plug right enviro-vat. RIH w/ 23/8" workstring and circulated 45 sx C cmt 372' to sure and circulated 45 sx C cmt 372' to sure restoration is retained as the plugging of the Liability under bond is retained cellar. Surface restoration is compared according to NMOCD guidelines A, a general right environment.	ING/CEMENT JOB ER: Int details, and give pertinent dates, including estimated date apletions: Attach wellbore diagram of proposed completion aging equipment. RU cementer, opened well. ND g, tagged CIBP @ 2,670'. RU cementer and / tbg to 1,583' and pumped 25 sx C cmt @ 1,583'. 1,366'. POOH w/ tubing. ND enviro-vat & BOP and urface. ND wellhead, POOH w/ tbg 2 topped off the Well Bore. The Well

PLUGGED WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

Stimulation History:

RKB @ 3753' DF @ 3737'


Subarea :	Hobbs			
Lease & Well No. :	State KN-	-12 No	. 6	
Legal Description :	1980' FSL & 660' FWL, Sec. 12, T-19-S, R-36-E			
County:	Lea	State :	New Mexico	
Field :	Eumont (Yates/	Seven Rive	rs/Queen)	
Date Spudded :	February 1, 1979	IPP:	March 16, 1979	
API Number :	30-025-26179		17 BO, 11 BW	
Status:				

<u>Gals</u>

Lbs.

Sand

DF @ _	
GL @	3737'



45 sx C cmt 372' to surface

	<u>Interval</u>	<u>Date</u>
12-1/4" Hole	3828-3997	2/13/7 2/13/7
		2/27/7

8-5/8" 24# K-55 @ 1,468' w/ 750 sx
circ 100 sx to surface
25 sx C cmt 1,583 - 1,366' TAGGED
Top of Salt @ 1,528'

			· 					
		2/13/79	Perf 3828-3997 14	holes				
38	28-3997	2/13/79	15% HCI NE	2,800	28 BS	4200	2050	8.0 3-1/2"
			TFW Gel	59,000	128,000	3900	2600	25.0 5-1/2"
		2/27/79	Test: 5 BO, 91 BW					
		3/16/79	Test: 17 BO, 11 BW					
		12/2/94	Set CIBP @ 3771' - Temporarily Abandoned					
		5/14/02	Perf Queen 2 SPF 3684-3698					
		5/14/02	15% NEFE HCI	500				
36	84-3698	5/16/02	Viking 2500	30,000	74,000	2800	2190	25.0
		5/16/02	15% NEFE HCI	500				
		5/17/02	Perf 7 Rivers 2 SPF 3140-3432					
31	40-3432	5/17/02	15% NEFE HCI	1,500	100 BS	2800		
			Viking 2500	30,000	86,000	2800	1750	35.0
		5/18/02	Perf Yates @ 2 SPF 2755-2877					
27	55-2877	5/18/02	15% NEFE HCI	1,500	100 BS	2060	1860	9.0
			Viking 2500	30,000	85,380	2100	1695	35.0
			No show oil or gas					
		5/21/02	CO to 3771'					
		5/29/02	Set CIBP @ 3650'					
		5/31/02	Spot 35' cmt on CIB	P @ 3650'	; TOC @ 3	615'		
	Set CIBP @ 3100'; spot 35' cmt; TOC @ 3065'							
		6/4/02	Set CIBP @ 2705'; spot 35' cmt; TOC @ 2670'					
		7/10/02	OCD Sundry Notice fi	iled to requ	iest TA Stu	ıtus		
		9/17/04	Prepare Application for	or Abandoi	nment of V	Vell		

<u>Type</u>

25 sx C cmt 2,670 - 2,422' TAGGED CIBP/cmt @ 2,670

Base of Salt @ 2,609'

2867-2872 2876-2877

3154-3157 3164-3166 3181-3186

CIBP @ 2,705'; TOC @ 2,670' <u>Yates</u> 2755-2758 2765-2774 2805-2811 2820-2826 2844-2847 2856-2863

CIBP @ 3,100'; TOC @ 3,065'
7 Rivers
3140-3144 3149-3152

3422-3432

CIBP @ 3,650'; TOC @ 3,615' Queen 3684-3698

CIBP @ 3,771'
Penrose
3828 3834 3845 3850
3917 3922 3930 3949
3953 3965 3968 3982
3987 3997

7-7/8" Hole 5-1/2" 14# K-55 ST&C @ 4,104' w/ 950 sx, circ 125 sx **ACTUAL PLUGS**

TRIPLE N
SERVICES INC.
MIDLAND, TX

Date: September 20, 2004

Max

Press ISIP Rate Down

- 1) TAGGED CIBP/cmt @ 2,670
- 2) 25 sx C cmt 2,670 2,422' 3) 25 sx C cmt 1,583 - 1,366' TAGGED
- 4) 45 sx C cmt 372' to surface

PBTD: 2,670° TD: 4,104°

==

==

==

Formation Tops: Rustler

Yates 2,754'
7 Rivers 3,024'
Queen 3,673'
Penrose
Grayburg 4,005'