Submit 2 Coming To Appropriate District	F			
Submit 3 Copies To Appropriate District State of New Mexico	Form C-103			
District I Energy, Minerals and Natural Resources	May 27, 2004 WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 District II	30-025-06096			
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE 🗍 FEE 🖂			
District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505	NM 0557686			
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	SEMU Eumont			
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number 66			
2. Name of Operator	9. OGRID Number			
ConocoPhillips Company Attn: John Abney	217817			
3. Address of Operator 4001 Penbrook Street Odessa, Texas 79762	10. Pool name or Wildcat			
·	Eumont Yates 7 Rivers Queen			
4. Well Location Unit Letter L : 1,980 feet from the South line and 6	60 fast from the West line			
Section 14 Township 20-S Range 37-E 11. Elevation (Show whether DR, RKB, RT, GR, e				
DF 3,549'				
Pit or Below-grade Tank Application 🛛 or Closure 🗌				
Pit type_steelDepth to Groundwater_80'Distance from nearest fresh water well_1 mile	Distance from nearest surface water_1 mile			
Pit Liner Thickness: steel mil Below-Grade Tank: Volume 180 bbls;	Construction Material steel			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON CHANGE PLANS				
PULL OR ALTER CASING 📋 MULTIPLE COMPL 🔲 CASING/CEME	INT JOB			
OTHER: OTHER:				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
or recompletion.				
10.15.10-				
SEE ATTACHED WELLBORE DIAGRAMS & PLUGGING PROCEDURE				
	5,5			
	E De			
	1930 2/22232 97930 2/22232 97900 97900 97900 9000 9000 9000 9000			
THE OIL CONSERVATION DIVISION MUST				
BE NOTIFIED 24 HOURS PRIOR TO THE				
BECININIAG OF PLUGGING OPERATIONS.				
PLUGUING OPERATIONS.				
I hereby certify that the information above is true and complete to the best of my knowle	dge and belief. I further certify that any nit or below			
grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit	or an (attached) alternative OCD-approved plan			
SIGNATURE TITLE James F. Newman	P.E. (Triple N Services) DATE 11/08/04			

.

SIGNATURE	Mr. ft	TITLE James F. Newman, P.E. (Triple N Ser	vices) DATE <u>11/08/04</u>
Type or print name For State Use Only	James F. Newman	E-mail address: jim@triplenservices.com	Telephone No. 432-687-1994
APPROVED BY: 7	Jan Writink	OC FIELD REPRESENTATIVE II/STAFF MA	DATE MARK
Conditions of Approva	ll (if any)		NOV 1 0 2004

WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

.





ConocoPhillips

Proposed Plugging Procedure

SEMU Eumont #66 Eumont Yates (Seven Rivers Queen) Field API #30-025-06096 Unit Letter L, 1,980 FSL & 660 FWL, Section 14, T20S, R37E Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

SI producer. Last work 09/30/04, set RBP @ 3,500', tubing @ 3,468'

- Notify BLM & OCD 24 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- Test rig anchors if last test over 2 years old
- 1. Set steel pit and flow well down as needed.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- 3. POOH w/ 3,468' tubing. RIH w/ retrieving head for RBP on production tubing, tag RBP @ 3,500'. RU cementer and circulate hole w/ 70 bbls plugging mud, latch onto RBP and release. POOH w/ RBP.
- RIH w/ HM tbg-set CIBP on production tubing to 3,500'. RU cementer and set CIBP @ 3,500'. Pump 25 sx C cmt (14.8 ppg, 1.32 ft³/sk, 33.0 ft³ slurry volume, calculated fill 240') 3,500 3,260'. Eumont plug
- 5. POOH w/ tbg to 2,600'. Load hole w/ plugging mud and pump 25 sx C cmt (14.8 ppg, 1.32 ft³/sk, 33.0 ft³ slurry volume, calculated fill 240') 2,600 2,360'. **Base of salt plug**
- POOH w/ tbg to 1,375'. Pump 25 sx C cmt w/ 2% CaCl₂ @ 1,375' (14.8 ppg, 1.32 ft³/sk, 33.0 ft³ slurry volume, calculated fill 240'). POOH w/ tbg and WOC. RIH w/ tbg and tag cmt no deeper than 1,275'. Top of salt plug
- POOH w/ tubing, NU lubricator and test to 1,000 psi. RIH w/ wireline and perforate casing @ 388', POOH w/ wireline. RD lubricator.
- RIH w/ AD-1 packer to 200'. Load hole, set packer, and establish rate into perforations @ 388'. If rate is established at 1,000 psi or less, squeeze 50 sx C cmt w/ 2% CaCl₂ (14.8 ppg, 1.32 ft³/sk, 66.0 ft³ slurry volume) 388 288'. WOC and tag this plug no deeper than 288'. Surface casing shoe plug
- 9. POOH w/ packer. NU lubricator and test to 1,000 psi. RIH w/ wireline and perforate casing @ 50', POOH w/ wireline. RD lubricator.

- **10.** NU wellhead, circulate 30 sx C cmt 50' to surface (14.8 ppg, 1.32 ft³/sk, 39.6 ft³ slurry volume, calculated fill 110'). **Surface plug**
- 11. NU wellhead. Pump 5 sx C cmt to surface as needed. SI well.
- 12. RDMO. Clean steel pit and dispose of bottoms.

•

13. Cut off wellhead, install dry hole marker, and cut off anchors, level location. Leave location clean and free of trash.

A diff

WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit

Date: November 8, 2004 RKB @ 3549' DF @ GL @ 3539 Subarea : Hobbs Lease & Well No. : SEMU Eumont No. 66 Legal Description : 1980' FSL & 660' FWL, Sec. 14, T-20-S, R-37-E, 30 sx C cmt 50' - 3', perf & sqz County : State : Lea New Mexico 12-1/4" Hole Eumont Yates 7 Rivers Queen (Pro Gas) Field : Date Spudded : May 26, 1956 API Number : 30-025-06096 8-5/8" 24# J-55 SLMS @ 338' w/ 225 sx, circ. Status: Temporarily Abandoned 50 sx C cmt 388 - 288', perf & sqz, TAG Drilled as Skaggs B-14 No. 1 Stimulation History: Lbs. Max Max Interval Date Type <u>Gals</u> Sand Press ISIP Rate Down 6/12/56 Perf 3660 - 3707 -- 4 SPF 6/12/56 Acid 1,000 3660-3707 Frac Oil (FO) 10,000 10,000 2900 1400 18 5 3" 6/13/56 Perf 3548 - 3638 -- 4 SPF 3548-3638 6/14/56 1,000 Acid Frac Oil (FO) 10,000 10,000 2900 1500 19.0 3" 6/20/56 IP test: CAOF 9115 MCF on 8 hours 8/1/57 Name changed to SEMU Eumont 66 TOC @ 1,263' calc 3/5/98 Tag fill @ 3475, swab 400', fluid in hole 25 sx C cmt 1,375 - 1,275', TAG 3548-3707 2/19/99 15% HCI NEFE 500 Top Salt @ 1,375' 9/29/04 Casing leak detected @ 950' using a packer and plug. Temporary plug set above Eumont perforations @3500' Ran 2-3/8" tbg to +/- 3468' 9/30/04 10/25/04 Prepare Application for Abandonment of Well PROPOSED PLUGS THIPLE N SERVICES ING. MQ TX set CIBP @ 3,500' 1) 25 sx C cmt 3,500 - 3,260' 2) 25 sx C cmt 2,600 - 2,360' 3) 25 sx C cmt 1,375 - 1,275', TAG 50 sx C cmt 388 - 288', perf & sqz, TAG 30 sx C cmt 50' - 3', perf & sqz 4) 5) 6) Base Salt @ 2,498' 25 sx C cmt 2,600 - 2,360' 25 sx C cmt 3,500 - 3,260' set CIBP @ 3,500' 3548 - 3553 3561 - 3572 == == 3580 - 3590 ΞΞ 3596 - 3610 3618 - 3638 == 3660 - 3671 == == 3680 - 3688 3695 -3707 == Formation Tops: Anhydrite 1284' Salt 1375' BP @ 3750' w/11 sx cmt 6-3/4" Hole Base Salt 2498' Yates 2646' 7 Rivers 2900' 5-1/2" 14# H-40 Smls @ 3,799' Queen 3440' Cmt'd w/ 1,430 sx Penrose 3545' TOC @ 1263' (Est.) Grayburg 3716 4-1/2" Hole OH 3799' - 3822' PBTD @ 3822 TD @