

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brason Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-28368
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-9683
7. Lease Name or Unit Agreement Name	Anderson Ranch Unit
8. Well No.	18
9. Pool name or Wildcat	Anderson Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator Conoco Inc.	
3. Address of Operator 10 Dexta Dr. Midland, TX 79705	
4. Well Location Unit Letter D : 660 Feet From The North Line and 600 Feet From The West Line Section 11 Township 16S Range 32E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Add perfs - acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-1-90 Finish GIH w/5 1/2" cog, scraper & bit to 9888 PDB. POH w/workstring. Make 3 runs w/4" gun. Perfs as follows: 1st run 9730-34 2 JSF 9854-64 2 JSF (-28 shots). 2nd run 9838-44; 9848-50 4 JSF. 3rd run 9742-46; 9788-92 4 JSF. Total shots 84 w/.40" EHD. RD wireline. GIH w/Baker 5 1/2" 17# ptr to 1260.

10-2-90 Set ptr at 9667. Loaded backside w/90 BBLs 9# brine. Test 800# - HELD. 2nd iron 6000#. Start pump acid pump 10 BBLs acid 15% HCL NEFE drop 20 balls pump acid dropping 2 balls every barrel pump. Pump 100 BBLs acid + 60 BBLs flush average rate 5 BPM average 75#. Shut in well. Ck ball gun found 191 balls in gun only 38 balls dropped. Pump 5 BBLs acid drop 40 balls (1.3 SG) Pump 95 BBLs acid dropping 2 balls/BBL. Begin rate 3 BPM 50# 66 BBLs acid on formations 3 BPM 50# Balls on formation average rate - press 3 BPM 50# pump 60 BBLs flush at 4 BPM at 60 #. No ball action drop 220 balls. Ck ball gun, all balls gone. JSF strong vacuum.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christine L. Neff TITLE Gas Assistant DATE 4-17-91
TYPE OR PRINT NAME Christine L. Neff TELEPHONE NO. 686-5494

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

MAY 28 1991