

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

3a. Indicate Type of Lease
State ☐ Fee ☒
3. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name: WEST DOLLARHIDE DRINKARD UNIT
2. Name of Operator TEXACO PRODUCING INC	8. Farm or Lease Name
3. Address of Operator P.O. BOX 728, HOBBS, NEW MEXICO 88240	9. Well No. 8
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>SOUTH</u> LINE AND <u>2303-4</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>19</u> TOWNSHIP <u>24-S</u> RANGE <u>38-E</u> N.M.P.M.	10. Field and Pool, or Wildcat DOLLARHIDE TUBB DRINKARD
15. Elevation (Show whether DF, RT, GR, etc.) 3164 G.R.	12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPHS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU. INSTALL BOP.
2. GIH w/CEMENT RETAINER. SET RETAINER AT 4300'. SPOT 10 SX CLASS C CEMENT WITH 2% CaCl₂ ON TOP.
3. SPOT 9.5 LB PER GAL MUD FROM 4300'-3200'. POOH.
4. RIG UP WIRELINE. PERFORATE 5 1/2" CSG AT 3900'.
5. GIH w/PKR ON 2 7/8" WORKSTRING. SET PKR AT 3850'. ESTABLISH RATE. POOH.
6. GIH w/CEMENT RETAINER. SET RETAINER AT 3850'. PUMP 100SX CLASS C CEMENT WITH 2% CaCl₂. RAISE TO BEHIND 5 1/2" CSG TO 3350'. RAISE UP TO 3200'.
7. SPOT 100' CEMENT PLUG 3200'-3100'. POOH.
8. RIG UP WIRELINE. CHEMICALLY CUT 5 1/2" CSG AT 3055'. (100% FREEPOINT AS PER 5/5/88 FREE POINT).
9. PULL 5 1/2" CSG.
10. TIH. CIRCULATE 9.5 PER GAL MUD FROM 3200' TO SURFACE.
11. SPOT 100' CEMENT PLUG 3100'-3000' (8 5/8" CSG) AND 100' CEMENT PLUG 1225' TO 1325' (ACROSS TOP OF SALT) @ 1325'.
12. PULL UP AND 100' CEMENT PLUG 400'-300'.
13. POOH.
14. SPOT 10' SURFACE PLUG (10' TOO).
15. INSTALL DRY HOLE MARKER. RIG DOWN. CLEAN LOCATION.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Jerry Sexton</u>	TITLE <u>AREA SUPERINTENDENT</u>	DATE <u>SEP 22 1988</u>
ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	TITLE _____	DATE <u>SEP 26 1988</u>
APPROVED BY _____	TITLE _____	DATE _____

CONDITIONS OF APPROVAL, IF ANY: