BUNDRY I					
SUNDRY I	Form 3160-5 (April 2004) IN Frence (April 2004) IN Frence UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007	
	NOTICES AND REI		110	5. Lease Serial No. LC 029410B	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIP	LICATE- Other instr	uctions on reve	rse side.	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Oil Well	Gas Well 📝 Other			8920003410	
2. Name of Operator ConocoPhillips Company ATTN: Celeste Dale				8. Well Name and No. MCA Unit #217 9. API Well No.	
3a Address 4001 Penbrook, Odessa, Texas 79	3b. Phone No. (include 432-368-1244	e area code)	9. Art wen No. 30-025-00774 10. Field and Pool, or Exploratory Area Maljamar Grayburg-San Andres		
4. Location of Well (Footage, Sec., T.,	432-300-1244				
660' FSL & 1,980' FWL, Section 30, T-17-S, R-32-E, Unit Letter N				11. County or Parish, State	
· · · · · · · · · · · · · · · · · · ·				Lea, New Mexico	
······································	ROPRIATE BOX(ES) TO	INDICATE NATUR	E OF NOTICE, F	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent	Acidize	Deepen Fracture Treat	Production (St		
Subsequent Report	Casing Repair	New Construction	Reclamation	Well Integrity	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Al		
	Convert to Injection	Plug Back	Water Disposal		
See attached wellbore diagra	Va	DOUS -	52622	APPROVED	
		21-10000	5	DEC 16 2004 GARY GOURLEY PETROLEUM ENGINEER	
14. Thereby certify that the foregoi Name (Printed/Typed) James F. Newman, 1	ng is true and correct			DEC 16 2004 GARY GOURLEY PETROLEUM ENGINEER	
Name (Printed/Typed)	ng is true and correct		gincer, Triple N Ser	DEC 16 2004	
Name (Printed/Typed) James F. Newman, 1 Signature	ng is true and correct	Title En Date	gincer, Triple N Ser	DEC 16 2004 GARY GOURLEY PETROLEUM ENGINEER	
James F. Newman, J	ng is true and correct P.E.	Title En Date EDERAL OR S1	igincer, Triple N Ser 12 TATE OFFICE	DEC 16 2004 GARY GOURLEY PETROLEUM ENGINEER Tvices, Inc. 432-687-1994 2/06/2004 USE	
Name (Printed/Typed) James F. Newman, 1 Signature	ng is true and correct P.E. THIS SPACE FOR F	Title En Date EDERAL OR SI res not warrant or	igincer, Triple N Ser 12 TATE OFFICE	DEC 16 2004 GARY GOURLEY PETROLEUM ENGINEER	

 c_{i}^{3}

WELLBORE SKETCH

ConocoPhillips Company - Permian Basin Business Unit

Date: December 6, 2004





ConocoPhillips

Proposed Plugging Procedure

MCA Unit #217W API #42-025-00774 Maljamar Grayburg San Andres Field Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

4½" cmt retainer @ 3,605' (set April, 1996). 7" 20# casing @ 3,581', estimated TOC 2,600'; 85%" csg @ 995' w/ 50 sx, TOC surface (?). <u>SALT</u>: 1,000 - 1,985'

- Notify NMOCD & BLM 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. Deliver 3,700' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" hydraulic BOP.
- 3. RIH w/ stinger for Baker cement retainer on 2³/₈" workstring to cement retainer @ 3,605'. RU cementer and circulate hole w/ mud, attempt to sting into retainer and establish rate into open hole. If rate is established, squeeze 60 sx C cmt (1.32 ft³/sk yield, 79.2 ft³ slurry volume), displacing to retainer. Sting out of retainer and pump 25 sx C cmt on retainer (1.32 ft³/sk yield, 33.0 ft³ slurry volume, 362' calculated fill) 3,605 3,243'. POOH w/ tbg. *GBSA Plug*
- **4.** RU lubricator and RIH w/ wireline, perforate 4½ & 7" casings w/ four 3½" strip-jet charges @ 2,085'. POOH w/ wireline, RD lubricator.
- RIH w/ 4½" AD-1 packer to 1,600'. Load hole, set packer, and establish rate into perforations at 1,000 psi or less, squeeze 50 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 66.0 ft³ slurry volume, 185' estimated fill) 2,085 1,985'. POOH w/ packer. If unable to establish rate, pump 25 sx C cmt balanced plug @ 2,135'. WOC and tag this plug no deeper than 1,985'. Base of salt plug
- 6. RU lubricator and RIH w/ wireline, perforate 4½ & 7" casings w/ four 3½" strip-jet charges @ 1,045'. POOH w/ wireline, RD lubricator.
- 7. RIH w/ 4½" AD-1 packer to 500'. Load hole, set packer, and establish rate into perforations at 1,000 psi or less, squeeze 65 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 85.8 ft³ slurry volume, 246' estimated fill) 1,045 900'. POOH w/ packer. If unable to establish rate, pump 25 sx C cmt balanced plug @1,095'. WOC and tag this plug no deeper than 945'. Top of salt & surface casing shoe plug
- 8. SI BOP and pressure-test casing 945' to surface to 500 psi. If casing does not test, isolate holes in casing prior to perforating.
- 9. RU lubricator and RIH w/ wireline, perforate 4½ & 7" casings w/ four 3½" strip-jet charges
 @ 400'. POOH w/ wireline, RD lubricator.

10. If casing tested, SI BOP and establish rate thru perforations. NU BOP and circulate 110 sx C cement (1.32 ft³/sk yield, 145 ft³ slurry volume, 406' estimated fill) 400' to surface.

11. SI well, RDMO.

ŝ,

12. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash. Clean steel pit and dispose of bottoms.

PROPOSED PLUGGED WELLBORE SKETCH ConocoPhillips Company - Permian Basin Business Unit

Date: December 6, 2004

