New Mexico	13 CONSERVATION (1975) 1625 N. Franch Bola	10月22年,夏季新闻者"武官"
Form 3160-5 UNITED STAT (April 2004) DEPARTMENT OF TI BUREAU OF LAND M	Modds, NM 55240 TES HE INTERIOR ANAGEMENT	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No.
SUNDRY NOTICES AND R Do not use this form for proposal abandoned well. Use Form 3160-3	s to drill or to re-enter a	
SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Gas Well JOIL Well Gas Well		
2. Name of Operator ConocoPhillips Company ATTN: Cele	ste Dale	9. API Well No.
3a Address 4001 Penbrook, Odessa, Texas 79762	3b. Phone No. (include area cod 432-368-1244	10. Field and Pool, or Exploratory Area
 Location of Well (Footage, Sec., T., R., M., or Survey Description 660' FNL & 1,980' FWL, Section 34, T-17-S, R-32-E, Un 	,	Maljamar Grayburg-San Andres 11. County or Parish, State Lea, New Mexico
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF N TYPE OF A	
Attach the Bond under which the work will be performed or p following completion of the involved operations. If the operat testing has been completed. Final Abandonment Notices shall determined that the site is ready for final inspection.) See attached wellbore diagrams & plugging procedu	Fracture Treat Re New Construction Re Plug and Abandon Te Plug and Abandon Te Plug Back Wa ertinent details, including estimated star tally, give subsurface locations and mea rovide the Bond No. on file with BLM/ ion results in a multiple completion or no be filed only after all requirements, incl Place Place	asured and true vertical depths of all pertinent markers and zones BIA. Required subsequent reports shall be filed within 30 days ecompletion in a new interval, a Form 3160-4 shall be filed once luding reclamation, have been completed, and the operator has
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) James F. Newman, P. J. Signature	Title Engineer,"	Triple N Services, Inc. 432-687-1994 12/06/2004
U THIS SPACE FOR	R FEDERAL OR STATE	
Approved by Conditions of approval, if any, are attached. Approval of this not certify that the applicant holds legal or equitable title to those righ which would entitle the applicant to conduct operations thereon.	ce does not warrant or ts in the subject lease Office	Date
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make States any false, fictitious or fraudulent statements or representation	it a crime for any person knowingly a ns as to any matter within its jurisdicti	nd willfully to make to any department or agency of the Unite on.
(Instructions on page 2)		

٩

يني ن WELLBORE SKETCH

ConocoPhillips Company -- Permian Basin Business Unit



 \mathbf{x}

MADI AND TY

ConocoPhillips

Proposed Plugging Procedure

MCA Unit #227 API #42-025-00818 Maljamar Grayburg San Andres Field Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

7" cmt retainer @ 3,700' (set Jan, 2000). 7" 32# casing @ 3,743', estimated TOC 2,443'; 8%" csg @ 1,135' w/ 50 sx, TOC surface (?). <u>SALT</u>: 1,100 - 2,285'

- Notify NMOCD & BLM 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. Deliver 3,700' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" hydraulic BOP.
- RIH w/ stinger for Baker cement retainer on 2%" workstring to cement retainer @ 3,700'. RU cementer and circulate hole w/ mud, attempt to sting into retainer and establish rate into open hole. If rate is established, squeeze 60 sx C cmt (1.32 ft³/sk yield, 79.2 ft³ slurry volume), displacing to retainer. Sting out of retainer and pump 25 sx C cmt on retainer (1.32 ft³/sk yield, 33.0 ft³ slurry volume, 145' calculated fill) 3,700 – 3,555'. POOH w/ tbg. *GBSA Plug*
- **4.** RU lubricator and RIH w/ wireline, perforate 7" casing w/ four 1-11/16" link-jet charges @ 2,385'. POOH w/ wireline, RD lubricator.
- RIH w/ 7" AD-1 packer to 2,000'. Load hole, set packer, and establish rate into perforations at 1,000 psi or less, squeeze 50 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 66.0 ft³ slurry volume, 185' estimated fill) 2,385 2,285'. POOH w/ packer. If unable to establish rate, pump 25 sx C cmt balanced plug @ 2,435'. WOC and tag this plug no deeper than 2,285'. Base of salt plug
- 6. RU lubricator and RIH w/ wireline, perforate 7" casing w/ four 1-11/16" link-jet charges @ 1,185'. POOH w/ wireline, RD lubricator.
- RIH w/ 7" AD-1 packer to 500'. Load hole, set packer, and establish rate into perforations at 1,000 psi or less, squeeze 90 sx C cement w/ 2% CaCl₂ (1.32 ft³/sk yield, 119 ft³ slurry volume) 1,185 1,050'. POOH w/ packer. If unable to establish rate, pump 25 sx C cmt balanced plug @1,235'. WOC and tag this plug no deeper than 1,050'. Top of salt & surface casing shoe plug
- 8. SI BOP and pressure-test casing 1,050' to surface to 500 psi. If casing does not test, isolate holes in casing prior to perforating.
- 9. RU lubricator and RIH w/ wireline, perforate 7" & 8%" casings w/ four 3½" strip-jet charges
 @ 400'. POOH w/ wireline, RD lubricator.

10. If casing tested, SI BOP and establish rate thru perforations. NU BOP and circulate 150 sx C cement (1.32 ft³/sk yield, 198 ft³ slurry volume) 400' to surface.

11. SI well, RDMO.

12. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash. Clean steel pit and dispose of bottoms.

MCA #227 procedure.doc

PROPOSED PLUGGED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

Date: December 6, 2004

.

