	State of New Mexico	Form C-103
1625 N. French Dr., Hobbs, NM 88240	ergy, Minerals and Natural Resources	May 27, 2004 WELL API NO. 30-025-36860
District II 1301 W. Grand Ave., Artesia, NM 88210 District III	L CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE X  6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Suitu 1 0, 11111 07505	6. State Off & Gas Lease No.
SUNDRY NOTICES ANI (DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR. USE "APPLICATION FO PROPOSALS.)	RILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Cooper 7
1. Type of Well: Oil Well Gas Well	X Other	8. Well Number 001
2. Name of Operator Chesapeake Operating,	Inc.	9. OGRID Number 147179
3. Address of Operator P. O. Box 11050 Midland, TX 7970.	2-8050	10. Pool name or Wildcat  Monument; Tubb, West (Gas) 96968
4. Well Location		
Unit Letter D: 660 feet from the North line and 900 feet from the West line		
Section 7	Township 20S Range 37E vation (Show whether DR, RKB, RT, GR, etc.)	NMPM CountyLea
	7 GR	
Pit typeDepth to Groundwater	<del>-</del>	nce from nearest surface water
		struction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION	ON TO: SUBS	SEQUENT REPORT OF:
	AND ABANDON 🔲 REMEDIAL WORK	☐ ALTERING CASING ☐
	E PLANS	
	CASING/CLIVILINI	10B
	OT: 150 P. 8/4 : 1	
OTHER:  13. Describe proposed or completed oper	OTHER:Perf/Acid ations. (Clearly state all pertinent details, and	give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed oper	OTHER:Perf/Acid ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta	ach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 60312-23-04 RIH w/186 jts. tbg to 6,058'. MIRU	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta	ach wellbore diagram of proposed completion ug. Test to 2000# for 5 mins. RIH w/WL,
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 -	ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF	ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  I perf Upper Binebry 2740 - 5776 @ 2
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals	ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  I perf Upper Binebry 2740 - 5776 @ 2
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op.	ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  I perf Upper Binebry 2740 - 5776 @ 2
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, inje	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @	ach wellbore diagram of proposed completion  ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  Square 15/20 NeFe. Used 4  1 perf Upper Brace 15/20 NeFe. Used 2  across perfs. + 5 BS per 3.5 bbls HCL.
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, inje 01-08-05 RIH w/5.5" Weatherford cmt retain	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 its tbg. RU kill trk and pump through.	ach wellbore diagram of proposed completion  ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  Square 15/20 NeFe. Used 4  1 perf Upper Brace 15/20 NeFe. Used 2  across perfs. + 5 BS per 3.5 bbls HCL.
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 60312-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, inject 01-08-05 RIH w/5.5" Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,601-09-05 MIRU Halliburton. Sq. perfs from	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throu 5000# on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer	ach wellbore diagram of proposed completion  ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  Sqool 140 - 5776 @ 2  across perfs. + 5 BS per 3.5 bbls HCL.  25534, 174' above perfs.  ugh ret., set ret. @ 5,695'. Press up on tbg  n Plus Halad 447 w/Gilsonite 1/4# Flo
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 60312-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection of the complex of the compl	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throu 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retained	ach wellbore diagram of proposed completion  ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  Sqool 140 - 5776 @ 2  across perfs. + 5 BS per 3.5 bbls HCL.  25534, 174' above perfs.  ugh ret., set ret. @ 5,695'. Press up on tbg  n Plus Halad 447 w/Gilsonite 1/4# Flo
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603·12-23-04 RIH w/186 jts. tbg to 6,058′. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978′ + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730′ + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection 01-08-05 RIH w/5.5″ Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,601-09-05 MIRU Halliburton. Sq. perfs from tail in w/100 sx Prem Plus w/1% CaCl. Run j hrs. press to 580#, 40# bleed down rate for 1 to 01-11-05 Run bond log 5690′ - TOC 4,684′.	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op.  '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throu 200# on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retainemin. POOH w/tbg and stinger. SI	ach wellbore diagram of proposed completion  ug. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  Sqool 140 - 5776 @ 2  across perfs. + 5 BS per 3.5 bbls HCL.  25534, 174' above perfs.  ugh ret., set ret. @ 5,695'. Press up on tbg  n Plus Halad 447 w/Gilsonite 1/4# Flo
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection of the survey o	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op.  '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ 1000# on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retainemin. POOH w/tbg and stinger. SI	ach wellbore diagram of proposed completion ug. Test to 2000# for 5 mins. RIH w/WL, 6059' w/5000 gals 15% NeFe. Used 4 Sq. NeFe. Used 4 I perf Upper Blinebry 2740 - 5776 @ 2 across perfs. + 5 BS per 3.5 bbls HCL.
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603·12-23-04 RIH w/186 jts. tbg to 6,058′. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978′ + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730′ + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection 01-08-05 RIH w/5.5″ Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,601-09-05 MIRU Halliburton. Sq. perfs from tail in w/100 sx Prem Plus w/1% CaCl. Run j hrs. press to 580#, 40# bleed down rate for 1 to 01-11-05 Run bond log 5690′ - TOC 4,684′.	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throu 200# on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retained min. POOH w/tbg and stinger. SI  CONTINUED PAGE 2	and belief. I further certify that any pit or below.
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection 01-08-05 RIH w/5.5" Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,401-09-05 MIRU Halliburton. Sq. perfs from tail in w/100 sx Prem Plus w/1% CaCl. Run j hrs. press to 580#, 40# bleed down rate for 1 to 01-11-05 Run bond log 5690' - TOC 4,684'. 01-12-05 Squeeze perfs 5710 - 5714'. Swab.	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes. U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op. '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throu 200# on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retained min. POOH w/tbg and stinger. SI  CONTINUED PAGE 2	and belief. I further certify that any pit or below.
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injee 01-08-05 RIH w/5.5" Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,001-09-05 MIRU Halliburton. Sq. perfs from tail in w/100 sx Prem Plus w/1% CaCl. Run j hrs. press to 580#, 40# bleed down rate for 1 m 01-11-05 Run bond log 5690' - TOC 4,684'. 01-12-05 Squeeze perfs 5710 - 5714'. Swab. I hereby certify that the information above is trepred tank has been/will be constructed or closed according the stank has bee	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes.  U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op.  '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump throughout on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retained min. POOH w/tbg and stinger. SI  CONTINUED PAGE 2  Tue and complete to the best of my knowledge reding to NMOCD guidelines \( \), a general permit \( \) on TITLE Regulatory Analyst  E-mail address: bcoffman@chl	ach wellbore diagram of proposed completion  ag. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  I perf Upper Binebry 2740 - 5776 @ 2  across perfs. + 5 BS per 3.5 bbls HCL.  2 5534, 174' above perfs.  agh ret., set ret. @ 5,695'. Press up on tbg  an Plus Halad 447 w/Gilsonite 1/4# Flo,  er, rev. out 1 1/2 times tbg. cap. SD 24  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan   DATE 01/31/2005  Seenergy.com Telephone No. (432)687-2992
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  12-22-04 POOH w/189 jts. tbg. MIRU Gray perforate Middle Blinebry 6,002 - 6024, 603: 12-23-04 RIH w/186 jts. tbg to 6,058'. MIRU BS/4 bbls acid.  12/29/04 RIH set CIBP @ 5978' + 2 sx cmt of spf (73holes).  12-30-04 MIRU Cudd, acidize Upper Blineb Swab  01-04-05 Set CIBP @ 5,730' + 1 sx cmt on to 01-06-05 Perf. Upper Blinebry 5,710 - 5,714 01-07-05 Run temperature survey. RIH, injection 01-08-05 RIH w/5.5" Weatherford cmt retain to 4000#, pull out of retainer, sting in, set 20,601-09-05 MIRU Halliburton. Sq. perfs from tail in w/100 sx Prem Plus w/1% CaCl. Run jchrs. press to 580#, 40# bleed down rate for 1 modeling 5690' - TOC 4,684'. 01-12-05 Squeeze perfs 5710 - 5714'. Swab. I hereby certify that the information above is treated tank has been/will be constructed or closed according the start of the s	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: Atta WL. Set CIBP @ 6100', dump 2 sx cmt on pl 9 - 6056 @ 2 spf, 80 holes.  U Cudd, acidize Middle Blinebry perfs 6002 - on top. load and test to 2000# for 5 mins. RIF ry w/3500 gals 15% NeFe HCL, spot 200 gals op.  '. RD. RUWL RIH w/tbg. ct tracer into perfs 5,710 - 5,714 - temp chg. @ ter and 175 jts tbg. RU kill trk and pump through on ret. SD 5,710 - 14' w/250 gals superflush, 200 sx Prer ob, took everything on vac. Pull out of retained min. POOH w/tbg and stinger. SI  CONTINUED PAGE 2  Tue and complete to the best of my knowledge reding to NMOCD guidelines \( \), a general permit \( \) or TITLE Regulatory Analyst	ach wellbore diagram of proposed completion  ag. Test to 2000# for 5 mins. RIH w/WL,  6059' w/5000 gals 15% NeFe. Used 4  I perf Upper Binebry 2740 - 5776 @ 2  across perfs. + 5 BS per 3.5 bbls HCL.  2 5534, 174' above perfs.  agh ret., set ret. @ 5,695'. Press up on tbg  an Plus Halad 447 w/Gilsonite 1/4# Flo,  er, rev. out 1 1/2 times tbg. cap. SD 24  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan   DATE 01/31/2005  Seenergy.com Telephone No. (432)687-2992

## CHESAPEAKE OPERATING, INC. P. O. BOX 11050 MIDLAND, TEXAS 79702-8050

## February 2, 2005

PAGE 2 C-103

## Cooper 7, Well #1

- 01-13-05 Break Circ. Drill on cmt retainer @ 5,688', drill out, RIH to 5,727', drill on CIBP, push down to 5,762', circ bottoms up.
- 01-14-05 Drill on CIBP, push to 5,978. Circ well clean. POOH, lD bit and 6 DC's, RIH w/ 173 jts. Tbg., set Arrow Set pkr @ 5,635'. Swabbing
- 01-15-05 MIRU Gray WL, perforate Blinebry 5,740 5,776' @ 2 spf (73 holes). RIH w/tbg and pkr, spot 200 gals, set pkr. MIRU Cudd, acidize Upper Blinebry 5,740 5,776 w/3500 gals 15% NeFe HCL + BS. Swabbing
- 01-20-05 MIRU Gray WL Service. Set CIBP @ 5,705' + 1 sx cmt on top. Test to 2000# for 5 mins. Held good. Perforate Blinebry 5,683 5,689' @ 4 spf (25 holes)
- 01/21/05 MIRU Cudd Acidize Blinebry 5,683-5,689-w/1,000 gals 15% NeFe. RIH to 5,690, spot 100 gals HCL + 2 BS per 1 bbl HCL. POOH, rev. spot acid, set pkr, load and pressure up to 1000#. Ball out Swab
- 01-25-05 Rel. pkr. POOH w/tbg. MIRU Gray WL set CIBP @ 5,650' + 2 sx cmt on top test to 2000#. RIH w/4" csg. Guns, perforate Paddock 5,230 5,234, 5247 5,259' @ 4 spf.
- 01-26-05 MIRU Cudd, acidize Paddock w/2,000 gals 15% neFe HCL, spot 200 gals @ 5,259'. Rev. spot acid, set pkr w/20,000# compression, load and press. BS to 1000#, run acid jot, drop 5 BS/ 2 bbls HCL. Swabbing
- 01-28-05 Swab dry. MIRU Gray WL set CIBP @ 5,190' + 2 sx cmt on top. Test to 2000# OK
- 01-29-05 Shut down no activity.