| abmit 3 Copies To Appropriate District | State of New Mexico | Form C-103 |
|--|--|--|
| fice | Energy, Minerals and Natural Resources | May 27, 2004 |
| istrict I 25 N. French Dr., Hobbs, NM 88240 | | WELLAPINO. AD - 30.011.10003 |
| istrict II 101 W. Grand Ave., Artesia, NM 88210 | OIL CONSERVATION DIVISION | 5. Indicate Type of Lease |
| istrict III | 1220 South St. Francis Dr. | STATE FEE |
| 00 Rio Brazos Rd., Aztec, NM 87410 istrict <u>IV</u> | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 220 S. St. Francis Dr., Santa Fe, NM 7505 | | STATS BA |
| SUNDRY NOTIO | CES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| IFFERENT RESERVOIR. USE "APPLICA | ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH | STATE BA |
| ROPOSALS.) . Type of Well: Oil Well | Gas Well 🔲 Other | 8. Well Number #00/ |
| . Name of Operator | | 9. OGRID Namber 708-3 |
| 3. Address of Operator | Broot | 10. Pool name or Wildcat |
| 720 W. Wils | shire, ste. 115, 2Kc, | 0K 73116 |
| 4. Well Location | | 35 C feet from theline |
| Unit Letter 7:4 | | |
| Section | Township Range | NMPM County |
| | 11. Elevation (Show whether DR, RKB, RT, GR, | , <i>elc.)</i> |
| it or Below-grade Tank Application 🗌 or | r Closure | |
| it typeDepth to Groundwa | | _ Distance from nearest surface water |
| it Liner Thickness: mil | Below-Grade Tank: Volume bbls | s; Construction Material |
| 12. Check A | Appropriate Box to Indicate Nature of Not | nce, Report or Other Data |
| PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. | MULTIPLE COMPL CASING/CE | |
| | | |
| DE NUTIFIED 24 | See Attached. VATION DIVISION LIJST HOURS PRIOR TO THE LUGGING OPERATIONS. | 000 000 000 000 000 000 000 000 |

Orbit Enterprises State BA # 1 UL A, Section 34, T7S, R35E **Plugging Procedure**

8 5/8" casing set at 332 ft, Cement circulated 4 1/2" 9.5#/ft casing set at 4430 ft, TOC 3500 ft by TS Perfs 4354-4389ft

- Move in rig up plugging rig 1.
- Pull production equipment 2.
- Nipple up BOP 3.
- Run and set CIBP at 4300 ft 4.
- Cap CIBP with 35 feet of cement by dump baller 5.
- Run tubing and tag cement plug 6.
- Displace well with gelled brine water 7.
- Pull tubing to 3550 feet 8.
- Spot 25 sack coment plug 9.
- Pull tubing 10.
- Perf casing at 1949 ft 11.
- Run packer and tubing, set packer at 1750 ft, -12.
- Squeeze perfs with 25 sack cement 13.
- WOC 14.
- Release packer and tag cement plug, Maximum depth 1849 ft. sade and the second se 15.
- Pull tubing and packer 16.
- Perf casing at 382 ft 17.
- Establish circulation through 4 ½" x 8 5/8" casing annulus 18.
- Circulate cement to surface, Estimated at 100 sack cement 19.
- Cut off wellhead and Install PA marker 20.
- Rig down move out service unit 21.
- Cut off anchors and clean location 22.

BEP 6/20/02

an an tait de la companya de la comp

and the second states of the second