
Office	State of N	ew Mexico		:	Form C-103	
District I	Energy, Minerals as	nd Natural Resources	WELLAND	·	May 27, 200	
1625 N. Frenc's Dr., Hobbs, NM 88240 District II	OIL CONGERN	ATION DITUOION	WELL API N 30-025	i o. 5-29455		
1301 W. Grand Avc., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE FEE KX		
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa re,	NM 87303	6. State Oil &	c Gas Lease No.		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Nan	7. Lease Name or Unit Agreement Name		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Cooper		
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator			8. Well Num	<u> </u>		
2. Name of Operator Spence Energy Co.			9. OGRID N			
3. Address of Operator 4925 Greenville Ave., Ste. 605, Dallas, TX 75206			10. Pool name or Wildcat			
4925 Greenville Ave.,	Ste. 605, Dallas	s, TX 75206	South Fly	ving M- Abo	<u> </u>	
Unit Letter A	330 feet from the	North line and	330 feet	from the <u>Eas</u>	st line	
Section 23	Township	9S Range 32E	NMPM		Lea	
560401	11. Elevation (Show when			County	пса	
, · -	`4337 '					
Pit or Below-grade Tank Application or		OVER		. 0	ER	
Pit typeSTEEL Depth to Groundwat	er_69 Distance from neare	st fresh water well 1000	istance from nearest	surface water 10	00'	
Pit Liner Thickness: mil	Below-Grade Tank: Volu	mebbls;	Construction Materi	al		
12. Check A	propriate Box to Indi	icate Nature of Notice	e. Report or Oth	her Data		
NOTICE OF INT	PLUG AND ABANDON	REMEDIAL WO	BSEQUENT PRK [RILLING OPNS.[ALTERING	F: SCASING ☐ ☐	
PULL OR ALTER CASING		☐ CASING/CEME	_	=	LJ	
_		_	_	_		
OTHER:		OTHER:				
 Describe proposed or completed of starting any proposed work 						
or recompletion.						
1. Set CIBP @ 8200' w/ 3	35' of cmt. on to	p. Fill hole ful	1 of mud.			
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49	000', sqz. w/ 35	p. Fill hole ful sx 4900-4800', V	1 of mud. NOC & tag.		_	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5	000', sqz. $w/35$ $6-1/2''$ csg.	sx 4900-4800', V	OC & tag.	6617 18 19 20	27.00	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i	000', sqz. w/ 35 5-1/2" csg. .nside & outside	sx 4900-4800', Woof csg. stub. WO	OC & tag.	NE 17 18 19 20		
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728-	000', sqz. w/ 35 5-1/2" csg. .nside & outside ·1628', WOC & tag	sx 4900-4800', Woof csg. stub. WO	OC & tag.	(617 18 19 20)		
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3	000', sqz. w/ 35 5-1/2" csg. .nside & outside ·1628', WOC & tag	sx 4900-4800', Woof csg. stub. WO	OC & tag.	G 17 18 19 20 3	3	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'.	000', sqz. w/ 35 0-1/2" csg. .nside & outside 1628', WOC & tag 000', WOC & tag.	sx 4900-4800', Woof csg. stub. Wo	OC & tag.	17 18 19 20 3 A B B B B B B B B B B B B B B B B B B	Section 1	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'.	000', sqz. w/ 35 0-1/2" csg. .nside & outside 1628', WOC & tag 000', WOC & tag.	sx 4900-4800', Woof csg. stub. Wo	OC & tag.	18 19 20 3 18 19 20 3		
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins	000', sqz. w/ 35 0-1/2" csg. nside & outside 1628', WOC & tag 000', WOC & tag.	sx 4900-4800', Woof csg. stub. Wo	OC & tag.	617 18 19 20 Sept 17 17 17 17 17 17 17 17 17 17 17 17 17	3	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins	OOO', sqz. w/ 35 5-1/2" csg. .nside & outside .1628', WOC & tag .00', WOC & tag. .tall dry hole ma	sx 4900-4800', Woof csg. stub. Wood.	COC & tag. CC & tag. Ccation.	17 18 19 20 - 18 19 20		
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE	OOO', sqz. w/ 35 0-1/2" csg. .nside & outside 1628', WOC & tag 000', WOC & tag. .tall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL	sx 4900-4800', Voor csg. stub. Work. Trker, & clean lower complete the complete th	Coc & tag. Cocation. JST	6 17 18 19 20 3 10 17 18 19 20 3 10 17 17 17 17 17 17 17 17 17 17 17 17 17		
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE	OOO', sqz. w/ 35 5-1/2" csg. .nside & outside .1628', WOC & tag .00', WOC & tag. .tall dry hole ma	sx 4900-4800', Voor csg. stub. Work. Trker, & clean lower complete the complete th	Coc & tag. Cocation. JST	677 18 19 20 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	3	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE	OOO', sqz. w/ 35 0-1/2" csg. .nside & outside 1628', WOC & tag 000', WOC & tag. .tall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL	sx 4900-4800', Voor csg. stub. Work. Trker, & clean lower complete the complete th	Coc & tag. Cocation. JST	617 18 19 20 Sept 1 4	3	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE	OOO', sqz. w/ 35 0-1/2" csg. .nside & outside 1628', WOC & tag 000', WOC & tag. .tall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL	sx 4900-4800', Voor csg. stub. Work. Trker, & clean lower complete the complete th	Coc & tag. Cocation. JST	677 18 19 20 - 18 19 2	3	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG	ooo', sqz. w/ 35 o-1/2" csg. nside & outside 1628', WOC & tag ooo', WOC & tag. stall dry hole ma OIL CONSERVAT NOTIFIED 24 HOU INNING OF PLUG	of csg. stub. Wood. of csg. stub. Wood. orker, & clean location DIVISION MINISTER PRIOR TO TO TO THE GING OPERATION OF THE COURSE OF THE COU	COC & tag. Cocation JST HE NS.	orther certify that	any pit er belov	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG	ooo', sqz. w/ 35 o-1/2" csg. nside & outside 1628', WOC & tag ooo', WOC & tag. stall dry hole ma OIL CONSERVAT NOTIFIED 24 HOU INNING OF PLUG	of csg. stub. Wood. of csg. stub. Wood. orker, & clean location DIVISION MINISTER PRIOR TO TO TO THE GING OPERATION OF THE COURSE OF THE COU	COC & tag. Cocation JST HE NS.	orther certify that	any pit or below	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE	ooo', sqz. w/ 35 o-1/2" csg. nside & outside 1628', WOC & tag ooo', WOC & tag. stall dry hole ma OIL CONSERVAT NOTIFIED 24 HOU INNING OF PLUG	of csg. stub. Wood. of csg. stub. Wood. orker, & clean location DIVISION MINISTER PRIOR TO TO TO THE GING OPERATION OF THE COURSE OF THE COU	COC & tag. Cocation JST HE NS.	orther certify that	any pit or below	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG [hereby certify that the information a grade tank has been/will be constructed or constructed or constructed.	ono', sqz. w/ 35 5-1/2" csg. Inside & outside 1628', WOC & tag 300', WOC & tag. Itall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL INNING OF PLUG bove is true and complete losed according to NMOCD gr	of csg. stub. Wood. of csg. stub. Wood. orker, & clean loos. INSPRIOR TO	COC & tag. Cocation JST HE NS.	ourther certify that lternative OCD-ap	any pit or belov proved plan 2-08-05	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' if 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG Chereby certify that the information a grade tank has been/will be constructed or constructed or constructed. SIGNATURE Roger Ma	ono', sqz. w/ 35 5-1/2" csg. Inside & outside 1628', WOC & tag 300', WOC & tag. Itall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL INNING OF PLUG bove is true and complete losed according to NMOCD gr	of csg. stub. Wo. of csg. stub. Wo. orker, & clean lo TION DIVISION MI JRS PRIOR TO TO GING OPERATIO to the best of my knowle idelines , a general permit	COC & tag. Cocation JST HE NS.	orther certify that Iternative OCD-ap	any pit or belov proved plan 2-08-05	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' i 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG [hereby certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information a grade tank has been/will be constructed or certify that the information and the constructed or certify that the information and the certification and the certif	ono', sqz. w/ 35 5-1/2" csg. Inside & outside 1628', WOC & tag 300', WOC & tag. Itall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL INNING OF PLUG bove is true and complete losed according to NMOCD gr	of csg. stub. Wood. of csg. stub. Wood. orker, & clean loos. INSPRIOR TO	Coc & tag. Cocation. JST HE NS. dge and belief. If	ourther certify that lternative OCD-ap	any pit or below proved plan 2-08-05	
1. Set CIBP @ 8200' w/ 3 2. Perforate 5-1/2" @ 49 3. Cut & pull 4500' of 5 4. Spot 30 sx cmt. 50' is 5. Spot 40 sx cmt. 1728- 6. Spot 35 sx cmt. 400-3 7. Spot 10 sx 30-3'. 8. RDMO. Cut off WH, ins THE BE BEG Thereby certify that the information a grade tank has been/will be constructed or	ono', sqz. w/ 35 5-1/2" csg. Inside & outside 1628', WOC & tag 300', WOC & tag. Itall dry hole ma OIL CONSERVAT NOTIFIED 24 HOL INNING OF PLUG bove is true and complete losed according to NMOCD gr	of csg. stub. Woods. Trker, & clean location DIVISION MINES PRICE TO THE GING OPERATION TO THE Agent Agent Agent	Coc & tag. Cocation. JST HE NS. dge and belief. If	ourther certify that lternative OCD-ap	any pit or below proved plan 2-08-05	

Proposed



PLUO # 8

PUD0 4 9 PLUG# 19 PLUGS PLUGS

TD 8366

DRINKARD

ENN ETRAWN LTOKA FORROW

HADROVE