		f New Mexico		Form C-103	
District I 1625 N. French Dr., Hobbs, NM 88240		ls and Natural Resources	WELL API NO.	May 27, 2004	
District II 1301 W. Grand Ave., Artesia, NM 882	OIL CONSER	OIL CONSERVATION DIVISION		30-025-00081	
District III	1220 Sour	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa I	Fe, NM 87505	6. State Oil & Gas Lease !		
1220 S. St. Francis Dr., Santa Fe, NM 87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Ag State ECH	7. Lease Name or Unit Agreement Name State ECH	
PROPOSALS.) 1. Type of Well: Oil Well [Gas Well Other		8. Well Number 1		
2. Name of Operator			9. OGRID Number		
Paladin Energy Corp 3. Address of Operator).		10. Pool name or Wildcat		
10290 Monroe Dr., S	Ste. 301, Dallas,	TX 75229	East Caprock Devo	nian	
4. Well Location					
Unit Letter P	: 660 feet from the			Eastlinc	
Section 2	Township		NMPM County	Lea	
	11. Elevation (Show)	whether DR, RKB, RT, GR, et	(c.)		
Pit or Below-grade Tank Application					
Pit type Steel Depth to Groun	ndwater <u>26 [†] Distance from n</u>	earest fresh water well[Distance from nearest surface water_		
Pit Liner Thickness:	mil Below-Grade Tank: V	Volumebbls;	Construction Material		
12. Chec	k Appropriate Box to I	Indicate Nature of Notice	e, Report or Other Data		
NOTICE OF	INTENTION TO:	l su	BSEQUENT REPORT	OF:	
PERFORM REMEDIAL WORK				NG CASING 🗌	
TEMPORARILY ABANDON	☐ CHANGE PLANS	_ ;	RILLING OPNS. P AND		
PULL OR ALTER CASING	■ MULTIPLE COMPL	CASING/CEME	ENT JOB		
OTHER:		OTHER:			
10 5 "	ampleted operations (Clear	rly state all pertinent details,	and give pertinent dates, includ	ing estimated date	
Describe proposed or co	impicion operations. (Cical				
of starting any proposed	i work). SEE RULE 1103.	For Multiple Completions:	Attach wellbore diagram of pro	posed completion	
of starting any proposed or recompletion. 1/1	iwork). SEE RULE 1103. 2/05 Establish ra	te under pkr. set	@ 5400', 3-3/4 BPM (0 O PST. Mix	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm	iwork). SEE RULE 1103. 2/05 Establish ra t. displaced TOC	te under pkr. set down to 5500' WOC.	@ 5400', 3-3/4 BPM (0 PSI. Mix	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1	work) SEE RULE 1103. 2/05 Establish ra it. displaced TOC of /13/05 Spot 100 st	te under pkr. set down to 5500' WOC.	@ 5400', 3-3/4 BPM (Pressure test to 5)	0 PSI. Mix 00 PSI and	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt.	<pre>iwork). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag</pre>	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg	0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @	iwork). SEE RULE 1103. 2/05 Establish ra it. displaced TOC 1/13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05: 3'. Sqz. 75 sx "C"	@ 5400', 3-3/4 BPM e Pressure test to 5e WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO	iwork). SEE RULE 1103. 2/05 Establish ra at. displaced TOC //13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr	@ 5400', 3-3/4 BPM e Pressure test to 5e WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @	iwork). SEE RULE 1103. 2/05 Establish ra at. displaced TOC //13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr	@ 5400', 3-3/4 BPM e Pressure test to 5e WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO	iwork). SEE RULE 1103. 2/05 Establish ra at. displaced TOC //13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr	@ 5400', 3-3/4 BPM e Pressure test to 5e WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO	iwork). SEE RULE 1103. 2/05 Establish ra at. displaced TOC //13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar	iwork). SEE RULE 1103. 2/05 Establish ra 2/05 Establish ra 1t. displaced TOC 1/13/05 Spot 100 stable gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/2 ker & clean locat.	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx crion.	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC id. /13/05 Spot 100 side gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/1 ker & clean location	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion.	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat: roved as to plugging of dity under bond is retain	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC id. /13/05 Spot 100 side gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/1 ker & clean location	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat: roved as to plugging of dity under bond is retain	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until	@ 5400', 3-3/4 BPM @ Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg. Spot 35 sx "C" cmt. cmt. thru perfs. w	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Apple Liabi surfa	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat roved as to plugging of dity under bond is retain ce restoration is completion above is true and comp	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted.	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. wmt. surface plug. Right April 19 Company of the surface plug of	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI. 000 030 030 030 031 030 031 030 031 031	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Approximate the construction of the	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat roved as to plugging of dity under bond is retain ce restoration is completion above is true and comp	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted.	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. wmt. surface plug. Right and belief. I further certify to or an (attached) alternative OCT	00 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 . 1/18/05 . 0 1612'. / 0 PSI. DMO 2 20 3 C 300 03/1, 7 y SOUT 13. hat any pk or below- approved plan □.	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Apple Liabi surfa	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat roved as to plugging of dity under bond is retain ce restoration is completion above is true and comp	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted.	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. wmt. surface plug. Right April 19 Company of the surface plug of	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI. 000 22 36 030 0 03/1,707 y \$000 03	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Approximate the construction of the	is work). SEE RULE 1103. 2/05 Establish rate. displaced TOC /13/05 Spot 100 stages. 1/14/05 Je@ 3658' WOC & tages 350' set pkr. @ 9 C & tages 216'.1/ker & clean locate roved as to plugging of lity under bond is retain the restoration is completed or closed according to NMOC Manny.	the under pkr. set down to 5500' WoC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx crion. the Well Bore. ned until eted.	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. wmt. surface plug. Right and belief. I further certify to or an (attached) alternative OCT	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 . 1/18/05 . 0 1612'. / 0 PSI. DM013 20 36	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Approximate the construction of the	i work). SEE RULE 1103. 2/05 Establish ra it. displaced TOC /13/05 Spot 100 s: # gel. 1/14/05 Je @ 3658' WOC & tag 350' set pkr. @ 9 C & tag @ 216'.1/ ker & clean locat roved as to plugging of dity under bond is retain ce restoration is completion above is true and comp	the under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted. lete to the best of my knowled D guidelines [], a general permit	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w mt. surface plug. Ri dge and belief. I further certify t or an (attached) alternative OCC	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 . 1/18/05 . 0 1612'. / 0 PSI. DM013 20 36	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Approximately Approximately Approximately Approximately Control of the construction of the cons	is work). SEE RULE 1103. 2/05 Establish rate. displaced TOC /13/05 Spot 100 stages. 1/14/05 Je@ 3658' WOC & tages 350' set pkr. @ 9 C & tages 216'.1/ker & clean locate roved as to plugging of lity under bond is retain the restoration is completed or closed according to NMOC Manny.	the under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted. lete to the best of my knowled D guidelines [], a general permit	@ 5400', 3-3/4 BPM Pressure test to 50 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w mt. surface plug. Ri dge and belief. I further certify to	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 . 1/18/05 . 0 1612'. / 0 PSI. DM013 20 3C	
of starting any proposed or recompletion. 1/1 and pump 750 sx H cm held. Tag @ 5679'. 1 Circulate hole w/ 10 Spot 75 sx "C" cmt. 1/19/05 Perforate @ Displaced to 250' WO Install dry hole mar Application of the construction of	is work). SEE RULE 1103. 2/05 Establish rate. displaced TOC /13/05 Spot 100 stages. 1/14/05 Je@ 3658' WOC & tages 350' set pkr. @ 9 C & tages 216'.1/ker & clean locate roved as to plugging of lity under bond is retain the restoration is completed or closed according to NMOC Manny.	te under pkr. set down to 5500' WOC. x "C" cmt. @ 5679' t cut 5-1/2" csg. @ 3405'. 1/18/05 3'. Sqz. 75 sx "C" 19/05 Spot 10 sx cr ion. the Well Bore. ned until eted. lete to the best of my knowle D guidelines [], a general permit	@ 5400', 3-3/4 BPM Pressure test to 5 WOC & tag @ 4612'. @ 3600' POOH w/ csg Spot 35 sx "C" cmt. cmt. thru perfs. w mt. surface plug. Ri dge and belief. I further certify t or an (attached) alternative OCC	@ 0 PSI. Mix 00 PSI and 1/13/05 . 1/18/05 @ 1612'. / 0 PSI. DM013 20 3C	