Submit 3 Copies To Appropriate District State of New Mexico		
Office State of New Mexico	Form C-103 May 27, 2004	
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-36370	
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	OG-1999	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name KG 35 State Com	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well X Other	8. Well Number 1	
2. Name of Operator ConocoPhillips Company	9. OGRID Number 217817	
3. Address of Operator 4001 Penbrook Street	10. Pool name or Wildcat	
Odessa, TX 79762	Vacuum; Wolfcamp	
4. Well Location		
Unit Letter <u>I</u> : <u>1395</u> feet from the <u>South</u> line and _		
Section 35Township 17-SRange 33-E11. Elevation (Show whether DR, RKB, RT, GR, International States of the states of th	NMPM CountyLea	
11. Elevation (Snow whether DR, RKB, R1, GR, 4120' GR	erc.)	
Pit or Below-grade Tank Application _ or Closure _		
Pit typeDepth to GroundwaterDistance from nearest fresh water well		
	Construction Material	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS		
PULL OR ALTER CASING		
OTHER: OTHER:	П	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
Stimulate/Cleanout		
11/15/04 Drove crew to location & held safety mtg. MIRU DDU unhang well & unseat pmp. SISD due to weather.		
11/16/04 Drove to location, held safety mtg. POOH w/rods & pmp, sent pmp in chk for scale. Found light scale in pmp, but was acid soluble. RU pmp trk, kill well, install BOP. POOH w/tbg, tbg anchor was clean. RIH w/20 stands kill string & SD.		
11/19/04 Held safety mtg. RU Schlumberger for acid stimulation. Held saftey mtg. & job scope. PSI tstd lines to 4027#, Pmpd 60.3		
BFW, start pmpg acid & balls. Pmpd 46.6 bbls acid when leak under TIW valve was detected. Stopped acid & pmpd 4.6 BW, Rep.		
leak & proceded w/job. Pmpd remainder of acid, 84 Bbls, start flush, pmpd total 230 Bbls flush. Treating psi max was 3140.14 w/ avg psi of 2202.37. Avg rate of fluid was 2.26 BPM, max rate was 7.17 BPM. After job was complete, we dropped dn 6 stands & set		
pack to tst plug, plug was tstd to 500# and held. RD Schlumberger. RU swab equip. FL was @ 4500' from surf. (5902' above SN)		
Made 5 runs, rec 30 BW. FL was @ 5400' from surf. (5002' above SN) SD closed well in.		
11/20/04 Held safety mtg. & job scope. Tbg psi was 0. FL was 6500' from surf. (3902' above SN). Made 8 swab runs, rec 48 BW for a 2 day total of 78 Bbls. FL staying @ 7200' from surf. (3202' above SN). RD swab equip., rel pkr. POOH w/tbg & pkr. RIH w/2" SN,		
2-7/8" poly jt & 18 jts, TA & remainder of tbg, 327 jts. Closed well in and SD.		
11/22/04 Drove crew to loc & held saftety mtg. Tbg psi 10#, csg 0#. Bled press. off we tension (12K). NU WH, RIH w/pmp & rods. Hang & space well out. Load & tet tbg. C	ell, RU pmp trk, ND BOP, set the anchor in	
11/22/04 Drove crew to loc & held saftety mtg. Tbg psi 10#, csg 0#. Bled press. off we tension (12K). NU WH, RIH w/pmp & rods. Hang & space well out. Load & tst tbg. C	ell, RU pmp trk, ND BOP, set the anchor in	
11/22/04 Drove crew to loc & held saftety mtg. Tbg psi 10#, csg 0#. Bled press. off we tension (12K). NU WH, RIH w/pmp & rods. Hang & space well out. Load & tst tbg. C	ell, RU pmp trk, ND BOP, set the anchor in	
tension (12K). NU WH, RIH w/pmp & rods. Hang & space well out. Load & tst tbg. C I hereby certify that the information above is true and complete to the best of my knowl	ell, RU pmp trk, ND BOP, set tbg anchor in k pmp action. OK. Clean loc, RDMO.	
tension (12K). NU WH, RIH w/pmp & rods. Hang & space well out. Load & tst tbg. C	ell, RU pmp trk, ND BOP, set tbg anchor in k pmp action. OK. Clean loc, RDMO. edge and belief. I further certify that any pit or below- X or an (attached) alternative OCD-approved plan .	

-		
Type or print name Celeste G. Dale	E-mail address:celeste.g.dale@conocophillipsTe	ekephone No. (432)368-1667
APPROVED BY: Lary W. Wink	OC FIELD REPRESENTATIVE IVSTAFF MANAGER	FEB 2 3 2005
APPROVED BY: Lay W. Ump.	TITLE	DATE
Conditions of Approval (if <b>a</b> y):	and a second set of second	
	Υ.	